

---

## AC Switch Panel Discolored at Edges

---

### Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	2019-2020	E3	N/A	N/A

### Revision History

Revision	Release Date	Changes
0	February 6, 2020	Original document

### Condition

The AC Switch Panel can become discolored at the edges.



### Technical Background

The discoloration is the result of too much solvent in the paint under the surface.

### Service Information

Replace the AC Control Panel  
All old parts have been purged from stock.

### Production Solution

The issue has been fixed in production as of April 26, 2019. Vehicles built after this date have the improved part.

### Warranty

As always, be sure to document the repair completely in PCSS. For this repair, please code the "cause" follows:

Cause location:	9627	Operator control unit in front center console
Cause symptom:	3071	Deviation from the shade

Use the following labor operation: 96271900 Operator control unit in front center console remove and reinstall

### Search Items

AC switch, AC Control, AC panel, AC Control Panel, AC switch panel

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

---