

Technical Bulletin

Model
All

Group
7

Subject: Reconditioning Leather Upholstery

Part Identifier
72 . .

Number
9002

ATTENTION: Service Manager/Service Technician

Concern:

1. Replacing leather seat covers and upholstery rather than repairing.
2. Reconditioning leather seat covers and upholstery due to:
 - a. accident damage
 - b. normal wear

Service Information:

Porsche Cars North America, Inc. recommends **COLOR-PLUS** products for repair to leather seat covers and upholstery (door panels, consoles, steering wheels, etc.).

Their products provide for minor repairs and complete re-dyeing "in-house" with a minimum of disassembly, allowing a substantial reduction in time and expense. Front seats can be dyed without removing seat covers.

Standard Porsche leather colors from M.Y. 1987 (except pearl and 1988 911 jubilee silver blue) will be matched and assigned a formula number for your convenience.

A **Color-Plus** brochure is enclosed, including a list of products, prices and tips on leather care and repair. For additional information on reconditioning leather, call Color-Plus at (201) 659-4708 or write to:

Color-Plus
P.O. Box 404
Kearny, NJ 07032

Dealership
Distribution
Routing

Service manager _____ Shop foreman _____ Service technician _____
Asst. manager _____ Warranty admin. _____ Service technician _____

©1990 Porsche Cars
North America, Inc.
All Rights Reserved
Porsche Technical
Publications



SERVICE

Page 1 of 1
June 22, 1990