

Musante Motorsports
 1257 John Fitch Boulevard #12
 South Windsor, CT 06074
 (860) 291-9415

the vehicle for the purposes of
 edged on vehicle to secure the
 ge to vehicle or articles left in
 ur control. I agree to pay
 ured to customer without
 ince Estimate. I request that
 gning this form, I authorize
 ned of up to a maximum of
 r or oral consent.

ion. Vehicles left after repair is

2001 Porsche 911

VIN:
Engine: H6 3.4L, 3400cc, Gas, FI
Trans:

License #
Odom: 90456
Color:
Mfg. Date:
Unit #

Inv Date: 2/04/2014

Service Writer:
Status: Appointment
Driver: Porter, Ian
PO #

Vehicle Problems	Requests for Service	Services Performed	Qty	Price	Ext
Notes: IMS/RMS Update (Winter Special)					
Check Plugs & Coil Packs - if not prev. replaced, change plugs.					
if Coil Packs are bad, call [redacted] (Both had been Previously Replaced)					
Motor Mounts need Replacing					
Clutch needs Replacement					
Labor Service -					
New	TRANSMISSION/DRIVE	Engine Mount			216.00
New	CLUTCH KIT	Clutch Kit	1.00	183.80	183.80
			1.00	781.42	781.42
Labor Service - 996 IMS Bearing - Dual or single Row. Remove Transaxle. Remove Clutch and Flywheel. Replace Intermediate Shaft Bearing. Replace Rear Main Seal. Install Flywheel, Clutch and Transmission. Road Test. Final inspect for leaks					
New	REAR MAIN	Seal 996/997 Latest Design	1.00	19.72	19.72
New	INTERMEDIATE SHAFT	M96 Engine Single bearing retrofit	1.00	650.00	650.00
Labor Service - Oil and Filter Change for 996					
New	OIL FILTER	996/997/Boxster/Cayenne	1.00	26.24	108.00
New	OIL	Motul 8100 X-Cess 5/40	8.75	9.95	26.24
Labor Service - Winter IMS/RMS Discount					
					-471.02

Warranty

Oral Authorization :
 Date _____ Customer Request _____

 _____ All repair work is warranted for 30 days.

Estimate only, do not pay.

Repair Order Summary:

Parts 1,748.24
Labor 932.98

Sub Total 2,681.22
Sales Tax (DEF) 170.25

Total 2,851.47

X

 Customer acknowledges receipt of merchandise and services.