

The present document was valid at the time of print. A later version may be available online

WM 300549 Eliminating noise symptoms - Reworking the clutch pedal

General information

Symptoms

Noise when actuating the clutch pedal.

Causes and remedial action

Noises that occur when actuating the clutch pedal can be eliminated by applying appropriate lubricants.

Reworking the clutch pedal

Reworking the clutch pedal

1. Grease the clutch pedal. → *300519 Removing and installing clutch pedal - section on "Installing"*

Working times

Working times

30051900: Removing and installing the clutch pedal; Labor time **130 ZE**

997110, 997111, 997120, 997121

Model year as of 2005

C00, C02, C05, C07, C08, C09, C10, C11, C12, C13, C14, C15, C16, C18, C19, C20, C21, C22, C23, C24, C25, C26, C27, C28, C32, C33, C34, C35, C36, C37, C38, C39, C45, C46, C98, C99

