

B CUSTOMER STATES VEHICLE TAKE OFF AT LOW SPEED, FEEL THERE IS A
CLICKING FROM THE DRIVETRAIN . CHECK AND ADVISE

39650199 Following ATI procedures to diagnosing
customer concern. Disconnected transfer case
module and verified issue.

130100	W	(N/C)
1 958-301-047-01	VENT LINE	(N/C)
1 N-104-312-02	LINE BRACKET.	(N/C)
2 N-107-873-01	SPACER RING	(N/C)
10 WHT-003-211	12 POINT SCREW 10X50	(N/C)
1 958-349-491-10	CIRCLIP TRANSFER BOX	(N/C)
1 958-349-493-00	CIRCLIP TRANSFER BOX	(N/C)
1 958-341-042-X	TRANSFER BOX	(N/C)
CORE CHARGE	W	(N/C)

-1 958-341-042-X CORE RETURN (N/C)

~~39651940 TRANSFER BOX REMOVED AND REINSTALLED~~

130100	W	(N/C)
39655555	TRANSFER BOX REPLACED	(N/C)
130100	W	(N/C)
39702390	VENT LINE INSTALLED	(N/C)
130100	W	(N/C)
03350060	ON BOARD DIAGNOSTIC .	(N/C)
130100	W	(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

42593 Test drove vehicle and confirmed customer complaint of
shudder and vibrations at low speeds. Performed a pre-val. Followed ATI
procedure for diagnosing transfer case. Disconnected transfer case
module and test drove vehicle and issue went away. Performed a
inter-val. Proceeded with replacement of transfer case as per repair
manual. Installed vent tube to vehicle. Programmed module to vehicle.
Test drove vehicle and no faults were present. Performed a post-val.

C PLEASE PERFORM TIRE AIR PRESSURE CHECK. INFLATE TO FACTORY
RECOMMENDED SPECIFICATIONS AND DOCUMENT AS NECESSARY