Follow the steps below to update firmware:

Extract the **G51A_UPD.rom** file from the update package, copy the file to the root of a USB flash drive and then connect the USB drive to the Gateway 500S BT while it is powered up (**ignition ON**). If possible please also copy 2-3 MP3 files to the USB device, again to the root. If there is an iPod connected to Gateway, please disconnect it before you connect the USB drive.

The update procedure will start automatically within a few seconds and takes approximately **2 minutes**. During the update procedure the Gateway 500S BT will restart a couple of times. **Do not disconnect the USB drive or turn the ignition OFF within this time (!)**.

When finished, you may need to reselect Gateway again from the Head Unit (car stereo).

After a successful update the **G51A_UPD.rom** is deleted from the USB flash drive and the new software version number will be visible in the Gateway **Settings\About** menu.

Test the Gateway 500S BT functionalities. For more information read Knowledge Base.

We do appreciate also if you can give us a feedback about the result, therefore please go to www.dension.com click on 'Support' and create a support ticket.

Please note: Although we do support playing music content from a USB hard disk drive, for the firmware update please use a USB flash stick/pen drive.