

This document was valid at the time of print. A later version may be available online.

## Technical Information

Service  
226/20 en\_US 4432

4

01/08/2021

### TI, 4432 Complaint - Tire Pressure Monitoring (TPM) System Error Message in Instrument Cluster - Observe Specified Procedure (226/20)

#### Model year

From 2020 To 2021

#### Model Line:

Cayman / Boxster (982)

Cayenne (9YA / 9YB)

Panamera (971)

Macan (95B)

#### Concerns:

**Tire Pressure Monitoring (TPM) system**

#### Equipment:

Tire Pressure Monitoring 433 MHz (I-no. 7K3)

#### Symptom:

The message "TPM fault - Service necessary" is displayed in the instrument cluster - particularly during the test drive for the sales check or after changing the wheels.

#### Action Required:

Teach wheel electronics using the PIWIS Tester.

#### Information

There is a possibility that the wheel electronics must be taught again at a later time using the PIWIS Tester, e.g. when changing a wheel.

The topic is currently the subject of further analysis. Please do not replace the wheel electronics at present, as it cannot be guaranteed at this time that this will correct the problem. As soon as a permanent remedial action is available, this Technical Information will be updated accordingly.

#### Teaching wheel electronics for Tire Pressure Monitoring (TPM)

##### Work Procedure:

Teach the Tire Pressure Monitoring (TPM) system using the PIWIS Tester, see

- > 443455 Replacing TPM control unit

#### Invoicing

##### Invoicing:

For documentation and warranty invoicing, enter the PQIS coding specified below in the warranty claim:

##### PQIS coding:

Location key (FES5)	4432	Wheel electronics
Damage code (SA4)	1100	Adjustment fault

##### References:

- > 443455 Replacing control unit for Tyre Pressure Monitoring (TPM)

95BAG1, 95BAM1, 95BBH1, 95BBL1, 95BCI1, 97AAA1, 97AAI1, 97AAY1, 97ABA1, 97ABE1, 97ABI1, 97ABX1, 97ABY1, 97ADB1, 97ADG1, 97ADN1, 97ADS1, 97ADZ1, 97AFF1, 97AFH1, 97AFR1, 97AFT1, 97AGA1, 97AGY1, 97AHE1, 97AHY1, 97BAA1, 97BAI1, 97BBE1, 97BBI1, 97BBX1, 97BBY1, 97BDB1, 97BDN1, 97BDZ1, 97BFF1, 97BFH1, 97BFR1, 97BFT1, 97CBA1, 97CBE1, 97CBI1, 97CBX1, 97CBI1, 97CBY1, 97CDB1, 97CDG1, 97CDN1, 97CDS1, 97CDZ1, 97CFF1, 97CFH1, 97CFR1, 97CFT1, 97CHE1, 97CHY1, 982120, 982121, 982130, 982131, 982140, 982141, 982150, 982151, 982160, 982161, 982320, 982321, 982330, 982331, 982340, 982341, 982350, 982351, 982360, 982361, 982510, 982511, 982810, 982811, 9YAAA1, 9YAAE1, 9YAAM1, 9YABB1, 9YABG1, 9YACF1, 9YACH1, 9YBAA1, 9YBAE1, 9YBAM1, 9YBBB1, 9YBBG1, 9YBCF1, 9YBCH1

From 2020

C02, C36