

CHAPTER 15. ROTOR GAP TEST

Section I. Breaker Point, All Chrysler Electronic, Ford Solid State and Dura Spark, and Prestolite BID Ignition Systems

15-1. DESCRIPTION	49
15-2. HOOK-UP PROCEDURE	49
15-3. TEST PROCEDURE	50
15-4. TEST RESULTS	50
A. Normal Pattern	50
B. Unsatisfactory Pattern	50

Section II. GM HEI and FORD TFI Systems

15-5. DESCRIPTION	50
15-6. HOOK-UP PROCEDURE	50
15-7. TEST PROCEDURE	52
15-8. TEST RESULTS	52
A. Normal Pattern	52
B. Unsatisfactory Pattern	52

CHAPTER 16. ALTERNATOR TEST

16-1. DESCRIPTION	53
16-2. HOOK-UP PROCEDURE	53
16-3. TEST PROCEDURE	54
16-4. TEST RESULTS	54
A. Normal Pattern	54
B. Unsatisfactory Pattern	54

CHAPTER 17. MAGNETIC PICK-UP COIL TEST

Section I. GM HEI System

17-1. DESCRIPTION	55
17-2. HOOK-UP PROCEDURE	55
17-3. TEST PROCEDURE	55
17-4. TEST RESULTS	55
A. Normal Pattern	55
B. Unsatisfactory Pattern	56

Section II. Chrysler Electronic Ignition Systems (6 and 8 Cylinder Only)

17-5. DESCRIPTION	56
17-6. HOOK-UP PROCEDURE	56
17-7. TEST PROCEDURE	57
17-8. TEST RESULTS	57
A. Normal Pattern	57
B. Unsatisfactory Pattern	57

Section III. Ford SSI, DSI, DSII, Ignition Systems

17-9. DESCRIPTION	57
17-10. HOOK-UP PROCEDURE	57
17-11. TEST PROCEDURE	58
17-12. TEST RESULTS	58
A. Normal Pattern	58
B. Unsatisfactory Pattern	58

CHAPTER 18. ADDITIONAL SCOPE PATTERNS

18-1. GENERAL	59
18-2. TURBULENCE	59
18-3. INDUCTION LEAKS	59
18-4. DEFECTIVE COIL	59
18-5. DEFECTIVE CONDENSER	59
18-6. FAULTY SPARK PLUGS	59
18-7. AUXILIARY GAP SPARK PLUGS	60
18-8. MAGNETO SYSTEM	60
18-9. ROTARY ENGINE	60
APPENDIX A TUNE-UP TIPS	61
APPENDIX B REPAIR PARTS	63