
## Measure distance "A" with a suitable gage



Size new Wear limit 18 mm 34 mm