

Technical Bulletin

Model
6 Cyl.

Group
4

Subject: Revised Front Wheel Hubs
and Tension Ring

Part Identifier
4057

Number
9405

Installation:

1. When the front wheel hub is removed, the wheel bearing is damaged and must be replaced.
2. Always replace the self-locking nut.
3. Torque front wheel nut to 460Nm (311 ft.lb.). (Thread and nut contact surface **without** grease — only 993.)

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.

