



Foreign and Domestic
Sales and Service

900 Wildwood Road * Mahtomedi MN 55115
(651)777-6924

DATE: 05/23/2003

REPAIR ORDER # 54860

Written by: 5

VEHICLE INFORMATION

Year: 1991
 Make: PORSCHE Model: 964 CARRERA 2 TARGA
 VIN: MfgDate: 01/91
 Lic#: Mileage: 84191 Year: 1991
 Engine: 3.6L Supercharged Trans: Auto.

Customer Information

P
:
M.

{Work1:(

CUSTOMER INSTRUCTION

1. Install H & R coil over spring and shock kit

WORK PERFORMED

Install H&R coil over spring and shock kit. Extended 720.00
 Four wheel alignment

PARTS REQUIRED

| | Part # | Price | Qty | Extended |
|---|---------|---------|-------|----------|
| H&R Coil Over Strut and Lowering Spring Kit | 29580.2 | 2295.00 | 1.000 | 2295.00 |

SUB-CONTRACTED

| | Ref. # | Price | Qty | Extended |
|--------------------------------|--------|-------|------------------|----------|
| Freight On H & R Coil Over Kit | | 16.75 | 1.000 | 16.75 |
| | | | Labor: \$ | 720.00 |
| | | | Parts: \$ | 2295.00 |
| | | | Sub-C: \$ | 16.75 |

Total for Group: \$ 3031.75

CUSTOMER INSTRUCTION

2. Adjust Fuel System for Nevada

WORK PERFORMED

Replace oxygen sensor and set fuel system to meet Nevada requirements Extended 120.00

PARTS REQUIRED

| | Part # | Price | Qty | Extended |
|---------------|-------------|--------|------------------|----------|
| Oxygen Sensor | 96560612601 | 170.65 | 1.000 | 170.65 |
| | | | Labor: \$ | 120.00 |
| | | | Parts: \$ | 170.65 |

Total for Group: \$ 290.65

CUSTOMER INSTRUCTION

3. Replace rear tail light and center lens.

WORK PERFORMED

Replace both taillights and center Porsche light. Extended 80.00

PARTS REQUIRED

| | Part # | Price | Qty | Extended |
|--------------------|-------------|--------|------------------|----------|
| Rear Porsche Light | 96463116000 | 260.95 | 1.000 | 260.95 |
| Tail Light - Right | 96463190701 | 190.70 | 1.000 | 190.70 |
| | | | Labor: \$ | 80.00 |
| | | | Parts: \$ | 451.65 |

Total for Group: \$ 531.65

PDF Editor Mac Free



Foreign and Domestic
Sales and Service

900 Wildwood Road * Mahtomedi MN 55115
(651)777-6924

DATE: 05/23/2003

REPAIR ORDER # 54860

Written by: 5

VEHICLE INFORMATION

Year: 1991
 Make: PORSCHE Model: 964 CARRERA 2 TARGA
 VIN: MfgDate: 01/91
 Lic#: Mileage: 84191 Year: 1991
 Engine: 3.6L Supercharged Trans: Auto.

Customer Information

[Empty box for customer information]

CUSTOMER INSTRUCTION

4. Install aluminum pedal pads.

WORK PERFORMED

R & R gas pedal assembly. Install Sparco aluminum pedal pads

Extended

160.00

PARTS REQUIRED

| Part # | Price | Qty | Extended |
|----------------------------|-------|------------------|----------|
| Sparco Aluminum Pedal Pads | 74.95 | 1.000 | 74.95 |
| | | Labor: \$ | 160.00 |
| | | Parts: \$ | 74.95 |
| Total for Group: \$ | | | 234.95 |

CUSTOMER INSTRUCTION

5. Install customer supplied updated supercharger control module

WORK PERFORMED

Install upgraded supercharger control unit.

Extended

120.00

Labor: \$ 120.00

Total for Group: \$ 120.00

CUSTOMER INSTRUCTION

6. Replace Rear Wiper Arm

WORK PERFORMED

Replace rear wiper arm

Extended

32.00

PARTS REQUIRED

| Part # | Price | Qty | Extended |
|----------------------------|--------|------------------|----------|
| Rear Wiper Arm | 114.66 | 1.000 | 114.66 |
| | | Labor: \$ | 32.00 |
| | | Parts: \$ | 114.66 |
| Total for Group: \$ | | | 146.66 |

Total for Parts: \$ 3106.91

Total for Sub-C: \$ 16.75

Shop Supplies: \$ 10.00

Tax: \$ 202.60

Total for Labor: \$ 1232.00

E.P.A. Charge: \$ 2.00

Total: \$ 4570.26

PDF Editor Mac Free