



Foreign and Domestic
Sales and Service

900 Wildwood Road * Mahtomedi MN 55115
(651)777-6924

DATE: 06/04/1999

REPAIR ORDER # 42699

Written by: 1

VEHICLE INFORMATION

Year: 1991
 Make: PORSCHE Model: 964 CARRERA 2 TARGA
 VIN: MfgDate: 01/91
 Lic#: Mileage: 94353 Year: 1991
 Engine: 3.6L Supercharged Trans: Auto.

Customer Information

[Empty box for customer information]

{v. 040 0005 / Mobile er:

CUSTOMER INSTRUCTION

1. Check oil leak.

WORK PERFORMED

Extended

Left side cylinder base gaskets leaking (cleaned off). Does not appear to be that bad.

CUSTOMER INSTRUCTION

2. Bore throttle housing. Also install K&N air filter.

WORK PERFORMED

Extended

Install big bore throttle housing. Readjust fuel system.
 Install K&N air filter.

264.00

PARTS REQUIRED

	Part #	Price	Qty	Extended
K&N Air Filter	332077	59.95	1.000	59.95
Big Bore Throttle Housing	INV.905803	350.00	1.000	350.00
			Labor: \$	264.00
			Parts: \$	409.95
Total for Group: \$				673.95

CUSTOMER INSTRUCTION

3. Install B&B exhaust.

WORK PERFORMED

Extended

Install B&B exhaust system.

132.00

PARTS REQUIRED

	Part #	Price	Qty	Extended
B&B Exhaust (4"outlet)	FPOR-6105	950.00	1.000	950.00

SUB-CONTRACTED

	Ref. #	Price	Qty	Extended
Freight on exhaust.		42.00	1.000	42.00
			Labor: \$	132.00
			Parts: \$	950.00
			Sub-C: \$	42.00

Total for Group: \$ 1124.00

PDF Editor Mac Free

Total for Parts: \$ 1359.95

Total for Sub-C: \$ 42.00

Shop Supplies: \$ 7.50

Tax: \$ 91.62

Total for Labor: \$ 396.00

E.P.A. Charge: \$ 1.00

Total: \$ 1898.07