

Technical Information

2021

Porsche Cayman GT4 Clubsport (981)

Porsche 718 Cayman GT4 clubsport

Porsche GT2 RS Clubsport

Porsche 935

Gearbox repair

Vehicle: Cayman GT4 Clubsport (981)
718 Cayman GT4 CS
911 GT2RS CS
935

Part: Gearbox

Model: 981, 982, 991 II, 935

Please ensure that trained specialists only carry out any technical work made on your cars.

If you are no longer the owner of the car, please forward this information to the current owner.

For Porsche Motorsport North America, the topics of quality, safety and customer satisfaction have top priority. For this reason, we turn to you today.

Porsche Motorsport North America would like to inform you that the Clubsport PDK transmissions can be repaired by ZF Friedrichshafen AG at a charge. The following repair packages are offered by ZF Friedrichshafen AG:

Repair package Leakage	Repair package Sensor	Repair package Double clutch
Replacement components: <ul style="list-style-type: none">• Sealing components• Consumables*	Replacement components: <ul style="list-style-type: none">• Sensor• Consumables*	Replacement components: <ul style="list-style-type: none">• Clutch• Clutch cover• Radial sealing clutch cover• Consumables*
Oil filling Function test on test bench	Oil filling Function test on test bench	Oil filling Function test on test bench
Costs: 3059€ excluding VAT**	Costs: 3956€ excluding VAT**	Costs: 4329€ excluding VAT** *Screws, cleaning supplies etc. **Status April 2021

In case of repair, please contact ZF Friedrichshafen AG at the following address:

Frank Dahmann

Email: transmissionperformance@zf.com

The gearbox must be freed from all holders and hoses before transport. The gearbox should be transported on a wooden pallet in a wooden box. Ensure that the gearbox does not rest on the oil pan during transport. Furthermore, the gearbox must be secured against slipping with tension belts.

The following address must be given for dispatch:

ZF Friedrichshafen AG
ZF Services Berlin
Blomberger Weg 4F
13437 Berlin
Germany

A processing time of at least 2-3 weeks should be allowed. The shipping costs will be charged to the customer. ZF Friedrichshafen AG offers a fee-based pick-up and delivery service within Germany for 150€ plus VAT. The following information should be noted on the delivery note:

- Serial number
- Part number
- Order number ZF (after email contact to ZF)

In the event that the gearbox is shipped outside the EU, it is mandatory to state "Repair" as the reason in order to avoid unnecessary customs clearance costs. Any import charges levied will be recharged to the customer.

If you have any technical questions about this or any other technical information of the Clubsport car models, please feel free to contact us at any time by e-mail to techsupport@porschemotorsport.com