



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. CLIENT REQUESTS 4 HOUR PRE-PURCHASE INSPECTION.



Package Results

Lyle Pearson Porsche Courtesy Inspection

Failed Task	Observation	Recommendation	Done
Inspect drive belts	Due bytime/mileage or Dealer History	Replace serpentine belt	

Cautioned Task	Observation	Recommendation	Done
Inspect cabin air (HEPA/micro) filter (if equipped)	Found cabin air (pollen)filter dirty		

Passed Task	Observation	Recommendation	Done
Fill windshield washer fluid	Found washer fluid level low: Filled to proper level		
Measure rear brake pads	9 mm		
Measure front brake pads	10 mm		
Left front tire tread depth	05 mm of Tire tread above wear bar.		
Left rear tire tread depth	05 mm of Tire tread above wear bar.		
Right front tire tread depth	05 mm of Tire tread above wear bar.		
Right rear tire tread depth	05 mm of Tire tread above wear bar.		
Check and adjust front tire pressure	Tire pressure was set to manufacturer specification - Check tire pressures monthly		
Check and adjust rear tire pressure	Tire pressure was set to manufacturer specification - Check tire pressures monthly		

Passed Tasks

- ✓ Inspect exhaust system for leaks, damage, and loose parts
- ✓ Inspect for wheel bearing free play
- ✓ Inspect axles, driveshaft and CV joints/boots

- ✓ Inspect engine mounts
- ✓ Inspect air filter
- ✓ Check engine oil level and condition
- ✓ Check transmission fluid level and condition (if applicable)
- ✓ Inspect reverse light operation
- ✓ Inspect headlight low and high beam operation
- ✓ Inspect dash and interior lights
- ✓ Inspect brake system components
- ✓ Inspect all hoses and clamps
- ✓ Inspect rear suspension components
- ✓ Inspect brake system for leaks
- ✓ Inspect steering system for leaks
- ✓ Left rear tire tread depth
- ✓ Check and adjust front tire pressure
- ✓ Check power locking system operation
- ✓ Inspect LED daytime running lights (If equipped)
- ✓ Inspect wheels for damage
- ✓ Inspect cornering lamps
- ✓ Inspect transmission mounts
- ✓ Fill windshield washer fluid
- ✓ Check engine coolant level and condition
- ✓ Inspect hazard light operation
- ✓ Inspect taillight, turn signal, side marker, and license plate lights
- ✓ Check horn operation
- ✓ Measure rear brake pads
- ✓ Perform battery performance test
- ✓ Inspect steering components
- ✓ Inspect engine for oil leaks
- ✓ Inspect cooling system for leaks
- ✓ Inspect sway bar components
- ✓ Right front tire tread depth
- ✓ Check and adjust rear tire pressure
- ✓ Inspect overall tire wear and condition
- ✓ Inspect lower engine cover
- ✓ Inspect windshield wiper blades
- ✓ Inspect fuel tank, lines, and connections
- ✓ Check power steering fluid level and condition
- ✓ Check brake fluid level and condition
- ✓ Inspect brake light operation
- ✓ Inspect taillight, turn signal, and side marker assemblies for cracks and damage
- ✓ Inspect heat and air conditioning operation
- ✓ Measure front brake pads
- ✓ Inspect battery terminals and cables
- ✓ Inspect front suspension components
- ✓ Inspect transmission for leaks
- ✓ Inspect fog/driving lights (if equipped)
- ✓ Left front tire tread depth
- ✓ Right rear tire tread depth
- ✓ Check power window operation
- ✓ Check hood strut(s)
- ✓ Inspect windshield for cracks, chips and pitting
- ✓ Inspect wiper and washer operation

Additional Observations	Recommendation
tires are new but non N rated porsche approved tires	advise on tires
body shop visit with airbag replacement	check car fax
cup holder worn out	replace cup holder
cigar lighter element missing and oddment tray rubber mat	install cig lighter element and oddment tray mat
scratches around rear lid and opening along with several small dents in rear lid	advise
oil has been changed but is overfilled	advise on oil fill level
service now message is displayed	advise on service message displayed at start



Previously Deferred Recommendations

We have kept a close watch on your maintenance history and believe that these previously recommended actions should still be performed:

Recommendation	Deferred	Approved
perform major service with brake fluid and drive belt		



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved	
A. CLIENT REQUESTS 4 HOUR PRE-PURCHASE INSPECTION.				X	
Subtotal		\$0.00			
Inspection & Additional Recommendations	Insp	Status	Cost	Deferred	Approved
Replace serpentine belt (Due bytime/mileage or Dealer History)	x	Fail	\$316.50		See AI-357
replace cup holder (cup holder worn out)		Fail	\$601.00		
install cig lighter element and oddment tray mat (cigar lighter element missing and oddment tray rubber mat)		Fail	\$78.00		
advise on oil fill level (oil has been changed but is overfilled)		Fail			
advise on service message displayed at start (service now message is displayed)		Fail			
Subtotal		\$995.50			
advise on tires (tires are new but non N rated porsche approved tires)		Caution			
check car fax (body shop visit with airbag replacement)		Caution			
advise (scratches around rear lid and opening along with several small dents in rear lid)		Caution			
Subtotal		\$0.00			
Previously Deferred Recommendations	Status	Cost	Deferred	Approved	
perform major service with brake fluid and drive belt	Caution	\$1,850.00			
Subtotal		\$1,850.00			
Totals, Taxes and Fees	Cost	Deferred	Approved		
Estimate Subtotal	\$2,845.50	\$0.00	\$0.00		
Environmental Compliance and Shop Supplies	\$37.67		\$0.00		
Taxes	\$36.88		\$0.00		
Estimate Total	\$2,920.04		\$0.00		