


Thank you for allowing us to help you maintain your vehicle. In our effort to help you keep your vehicle operating at peak performance, we have assembled this customized Action Plan that addresses the needs of your vehicle. Please review its contents and let your advisor know which services you would like us to perform today. If you have any questions or concerns please don't hesitate to contact us. We are here to help you.



DOLF VANKESTEREN

Service Consultant

P. Roop

Certified Technician



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

✓ A. C/S: CERTIFIED INSPECTION TO SELL

✓ B. PERFORM BILL PEARCE MOTORS MULTI- POINT INSPECTION

C. PERFORMED COURTESY EXTERIOR WASH AND VACUUM AN \$18 VALUE AT NO CHARGE



Package Results

Bill Pearce Porsche "World Class Inspection"

Cautioned Task	Observation	Recommendation	Done
Left front tire tread depth	3/32" Of Tire Tread Remainig.		
Left rear tire tread depth	2/32" Of Tire Tread Remainig.		
Right front tire tread depth	3/32" Of Tire Tread Remainig.		
Right rear tire tread depth	2/32" Of Tire Tread Remainig.		

Passed Task	Observation	Recommendation	Done
Fill windshield washer fluid	Found washer fluid level low: Filled to proper level		
Measure rear brake pads	8 mm		
Measure front brake pads	7 mm		
Check and adjust front tire pressure	Tire pressure was set to manufacturer specification - Check tire pressures monthly		
Check and adjust rear tire pressure	Tire pressure was set to manufacturer specification - Check tire pressures monthly		
Inspect overall tire wear and condition	All tires require inspection next service		

Passed Tasks				
Inspect exhaust system for leaks, damage, and loose parts	Inspect for wheel bearing free play	Inspect axles, driveshaft and CV joints/boots		
✓ Inspect engine mounts	Inspect transmission mounts	Inspect fuel tank, lines, and connections		
Fill windshield washer fluid	Check power steering fluid level and condition	Check engine coolant level and condition		
Check brake fluid level and condition	Inspect hazard light operation	Inspect brake light operation		

Inspect reverse light operation	Inspect taillight, turn signal, side marker, and license plate lights	Inspect taillight, turn signal, and side marker assemblies for cracks and damage
Inspect headlight low and high beam operation	Inspect wiper and washer operation	Check horn operation
Inspect heat and air conditioning operation	Inspect dash and interior lights	Measure rear brake pads
Measure front brake pads	Inspect brake system components	Inspect windshield wiper blades
✓ Inspect drive belts	Inspect all hoses and clamps	Inspect steering components
Inspect front suspension components	✓ Inspect rear suspension components	✓ Inspect engine for oil leaks
Inspect transmission for leaks	Inspect brake system for leaks	Inspect cooling system for leaks
Inspect fog/driving lights (if equipped)	✓ Inspect rear wiper blade (if applicable)	Inspect steering system for leaks
Inspect sway bar components	Check and adjust front tire pressure	Check and adjust rear tire pressure
Check power window operation	Check power locking system operation	✓ Inspect overall tire wear and condition
Check hood strut(s)	Inspect LED daytime running lights (If equipped)	Inspect lower engine cover
Inspect windshield for cracks, chips and pitting	Consulted to deferred services/recommendations	Consulted to time and mileage recommendations
Inspect instrument panel warning lamps	✓ Visually inspect front tires	✓ Visually inspect rear tires
Inspect for clarity of headlamp lenses	Inspect body for damage, dings, and dents	

Additional Observations	Recommendation
FOUND CLIP FOR TRUNK COVER BROKEN	RECOMMEND REPLACING CLIP



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
A. C/S: CERTIFIED INSPECTION TO SELL		\$495.00		X
B. PERFORM BILL PEARCE MOTORS MULTI- POINT INSPECTION		\$0.00		X
C. PERFORMED COURTESY EXTERIOR WASH AND VACUUM AN \$18 VALUE AT NO CHARGE				X
Subtotal		\$495.00		\$495.00
Additional Recommendations	Status	Cost	Deferred	Approved
RECOMMEND REPLACING CLIP (FOUND CLIP FOR TRUNK COVER BROKEN)	Caution	\$2.98		X
Subtotal		\$2.98		\$2.98
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$497.98	\$0.00	\$497.98

3

Totals, Taxes and Fees	Cost	Deferred	Approved
Shop Supplies	\$60.00		
Tax	\$4.96		
Estimate Total	\$562.94		