



6800 East Independence Blvd.
 CHARLOTTE, NORTH CAROLINA 28227
 (704) 531-3344
 www.hendrickporsche.com



CUSTOMER NO. 80020123		ADVISOR ANDREW MUELLER	121774	TAG NO. 595	INVOICE DATE 10/30/23	INVOICE NO. POWS103577	
GMP Performance 710 Pressley Rd. Charlotte, NC 28217		LABOR RATE	LICENSE NO.	MILEAGE 36,753	COLOR /	STOCK NO.	
		YEAR / MAKE / MODEL 15/PORSCHE/911/2DR CPE GT3				DELIVERY DATE	DELIVERY MILES
		VEHICLE I.D. NO. W P O A C 2 A 9 3 F S 1 8 9 0 9 6				SELLING DEALER NO.	PRODUCTION DATE
QUENTIN@GMPPERFORMANCE.COM		F. T. E. NO. 006046342		P. O. NO.	R. O. DATE 09/20/23		
RESIDENCE PHONE	BUSINESS PHONE 704-525-0941 x252	COMMENTS				MO: 36762	

LABOR & PARTS

J#	11POZCKENG	CK ENG LIGHT	HOURS:	20.46	TECH(S):	130215	4255.68
TECH#	DATE	START	FINISH	ACT	TIME	DESCRIPTION	
130215	10/02/23	14.30	16.90	2.60	0.00	NON WORKING	
130215	10/03/23	8.20	9.20	1.00	0.00	HOLD AUTHORIZATION	
130215	10/03/23	16.00	17.30	1.30	0.00	NON WORKING	
130215	10/04/23	7.60	9.00	1.40	0.00	HOLD PARTS	
130215	10/12/23	16.30	16.40	0.10	0.00	NON WORKING	
130215	10/13/23	7.80	7.90	0.10	0.00	HOLD OTHER	
130215	10/26/23	8.30	16.90	8.60	0.00	NON WORKING	
130215	10/27/23	9.40	18.00	8.60	0.00	NON WORKING	
130215	10/30/23	8.40	8.40	0.00	0.00	FINISHED	
130215	10/30/23	0.00	0.00	0.00	20.46	FINISHED	
TOTAL TECH TIME				23.70	20.46		

SERVICE CHARGE The Service Charge covers or defrays some of Dealer's service department overhead costs, including, but not limited to, shop supplies, employee safety measures and training, and waste disposal and handling, many of which do not lend themselves to precise itemization or allocation. Not all repair or service transactions will cause Dealer to incur all of the costs defrayed by the Service Charge. The Service Charge may include Dealer profit. The Service Charge is not a government required fee.

As part of our effort to provide the highest possible level of service to our customers, we would like your authorization for this Dealership to contact you in order to ensure you are happy with your purchase, keep you informed of new product offerings and promotions, remind you of necessary vehicle maintenance or service, and for any other reason we feel is necessary or appropriate. **UNLESS YOU CHECK THE BOX BELOW**, by signing this form, you give this Dealership **PERMISSION** to contact you (**either personally, via text messages or with prerecorded telemarketing messages**) at the telephone numbers (which may include **wireless phone numbers**), fax number and/or e-mail address listed. This **AUTHORIZATION** allows us to better serve you in compliance with federal and state regulations and in no way is a condition to receiving goods or services.

Please do not contact me as provided above.

Customer agrees that this Agreement includes all of the terms and conditions on the **front and back side hereof**, that this Agreement cancels and supersedes any prior agreement including oral agreements, and as of the date below comprises the entire agreement between Customer and Dealer relating to these repairs or other matters referred to on the front or back side of this document.

CUSTOMER STATES CK ENG LIGHT IS ON VCC, Created VAL, fault p0305 (misfire cylinder 5) present and active, found via actual values, misfire is a "dead miss", removed all spark plugs, removed rear wheels, performed cylinder leakage check (1=95% 2=96% 3=94% 4=93% 5=43% 6=95%). Found cylinder leakage at cylinder 5, drained refrigerant (765g) drained coolant (could not be saved due to contamination), removed engine, removed bank 2 cam cover and found faulty rocker arm, damage to camshaft/journals and damage to piston and valves due to faulty rocker arm. (see photos for all damage. Damage to piston not time stamped as photos were taken with borescope) Per TI 59/15 if vehicle shows any wear to camshaft, engine must be replaced. Vehicle needs new Engine. Had to reinstall engine to move vehicle while waiting on new engine from Germany. Removed engine, removed transmission. swapped flywheel, exhaust and all other necessary components to new engine, mated transmission, installed engine, filled and bled coolant system, replaced dryer per WM (due to AC system being open), filled AC (900g), performed first start function, test drove, system is as designed after repair. Old Engine Number:F02719 New Engine Number:G61821

CLAIM #	WARRANTY OP.	CODES	FLAT	HRS.	OTHER	HRS.	FC	AUTH.	CODE	CLAIM TYPE
103577	03350053			0.18						99001000
103577	44051913			0.46						99001000
103577	44051914			0.46						99001000
103577	28702026			0.80						99001000
103577	10180275			0.69						99001000
103577	10011926			6.92						99001000
103577	15821976			1.64						99001000
103577	87031750			0.76						99001000
103577	19381775			0.62						99001000
103577	97850950			0.06						99001000
103577	10011926			6.92						99001000
103577	17010175			0.37						99001000
103577	37342775			0.57						99001000
103577	13601950			0.66						99001000
103577	26252075			0.96						99001000



6800 East Independence Blvd.
 CHARLOTTE, NORTH CAROLINA 28227
 (704) 531-3344
 www.hendrickporsche.com



CUSTOMER NO. 80020123		ADVISOR ANDREW MUELLER	121774	TAG NO. 595	INVOICE DATE 10/30/23	INVOICE NO. POWS103577	
GMP Performance 710 Pressley Rd. Charlotte, NC 28217		LABOR RATE	LICENSE NO.	MILEAGE 36,753	COLOR /	STOCK NO.	
		YEAR / MAKE / MODEL 15/PORSCHE/911/2DR CPE GT3				DELIVERY DATE	DELIVERY MILES
		VEHICLE I.D. NO. W P O A C 2 A 9 3 F S 1 8 9 0 9 6				SELLING DEALER NO.	PRODUCTION DATE
QUENTIN@GMPPERFORMANCE.COM		F.T.E. NO. 006046342		P.O. NO.	R.O. DATE 09/20/23		
RESIDENCE PHONE	BUSINESS PHONE 704-525-0941 x252	COMMENTS				MO: 36762	

CLAIM #	WARRANTY OP. CODES	FLAT HRS.	OTHER HRS.	FC	AUTH. CODE	CLAIM TYPE
103577	26331975	0.40				99001000
PARTS	QTY	FP-NUMBER	DESCRIPTION	U/COST	E/COST	U/PRICE
JOB # 1	1	9A1-100-975-EX	REPLACEMENT ENGI	76839.30	76839.30	129652.27
JOB # 1	2	999-073-443-01	HEX COMB SCREW 1	3.04	6.08	6.45
JOB # 1	2	999-072-869-01	HEXAGON-HEAD BOL	3.05	6.10	6.47
JOB # 1	2	999-084-123-09	HEXAGON NUT	2.54	5.08	5.39
JOB # 1	4	900-076-064-02	HEXAGON NUT	0.48	1.92	1.02
JOB # 1	2	9A7-008-677-00	HEXAGON-HEAD BOL	4.21	8.42	8.93
JOB # 1	2	999-072-859-01	HEXAGON-HEAD SCR	4.39	8.78	9.31
JOB # 1	4	999-084-445-01	LOCK NUT	1.88	7.52	3.99
JOB # 1	2	PAF-008-868	HEXAGON NUT	1.88	3.76	3.99
JOB # 1	1	999-086-009-02	NUT	5.64	5.64	11.97
JOB # 1	2	N-908-484-05	HEXAGON NUT	2.11	4.22	4.48
JOB # 1	3	996-106-801-03	O-RING	3.50	10.50	7.43
JOB # 1	2	999-707-660-40	O-RING	3.71	7.42	7.87
JOB # 1	1	944-573-143-01	RECEIVER DRIER	74.76	74.76	158.61
JOB # 1	10	PAF-906-651	SCREW	2.69	26.90	5.71
JOB # 1	6	9A7-008-464-00	OUTER HEXAGON RO	2.50	15.00	5.30
JOB # 1	12	WHT-008-727	PAN-HEAD SCREW	2.17	26.04	4.60
JOB # 1	2	997-111-336-90	SPHERICAL CLAMP	146.96	293.92	311.79
JOB # 1	4	900-380-005-01	HEXAGON NUT	0.48	1.92	1.02
JOB # 1	2	900-067-362-01	PAN-HEAD SCREW 8	0.84	1.68	1.78
JOB # 1	4	999-651-401-01	CABLE CLAMP	0.76	3.04	1.61
JOB # 1	2	999-512-707-00	HOSE CLAMP	1.88	3.76	3.99
JOB # 1	3	N-100-988-11	HEXAGON-HEAD SCR	0.49	1.47	1.04
JOB # 1	2	980-111-561-00	EXHAUST SEALING	16.39	32.78	34.77
JOB # 1	-1	9A1-100-975-EX	CORE RETURN	29752.13	29752.13	29752.13
JOB # 1	2	000-043-305-75	795649 G40 AFC 6	23.41	46.82	49.67
				JOB # 1 COST TOTAL	47690.70	
				JOB # 1 TOTAL PARTS		101180.57
				JOB # 1 TOTAL LABOR & PARTS		105436.25

SERVICE CHARGE The Service Charge covers or defrays some of Dealer's service department overhead costs, including, but not limited to, shop supplies, employee safety measures and training, and waste disposal and handling, many of which do not lend themselves to precise itemization or allocation. Not all repair or service transactions will cause Dealer to incur all of the costs defrayed by the Service Charge. The Service Charge may include Dealer profit. The Service Charge is not a government required fee.

As part of our effort to provide the highest possible level of service to our customers, we would like your authorization for this Dealership to contact you in order to ensure you are happy with your purchase, keep you informed of new product offerings and promotions, remind you of necessary vehicle maintenance or service, and for any other reason we feel is necessary or appropriate. **UNLESS YOU CHECK THE BOX BELOW**, by signing this form, you give this Dealership **PERMISSION** to contact you (**either personally, via text messages or with prerecorded telemarketing messages**) at the telephone numbers (which may include **wireless phone numbers**), fax number and/or e-mail address listed. This **AUTHORIZATION** allows us to better serve you in compliance with federal and state regulations and in no way is a condition to receiving goods or services.

Please do not contact me as provided above.

Customer agrees that this Agreement includes all of the terms and conditions on the **front and back side hereof**, that this Agreement cancels and supersedes any prior agreement including oral agreements, and as of the date below comprises the entire agreement between Customer and Dealer relating to these repairs or other matters referred to on the front or back side of this document.

J# 5+05POZ1	RECALL	HOURS:	0.71	TECH(S):	130215	147.68
TECH#	DATE	START	FINISH	ACT	TIME	DESCRIPTION
130215	10/30/23	8.60	9.80	1.20	0.00	FINISHED
130215	10/30/23	0.00	0.00	0.00	0.71	FINISHED
		TOTAL TECH TIME	1.20	0.71		

CUSTOMER STATES PERFORM RECALL AMCO complete 14.2v maintained during programming.

CLAIM #	WARRANTY OP. CODES	FLAT HRS.	OTHER HRS.	FC	AUTH. CODE	CLAIM TYPE
103577	AMC09999	0.71				99001000
						JOB # 5 TOTAL LABOR & PARTS
						147.68

G.O.G. & SUPPLIES						
JOB # 1	FREIGHT (PARTS)				7063.08	
					TOTAL - GOG	7063.08



6800 East Independence Blvd.
 CHARLOTTE, NORTH CAROLINA 28227
 (704) 531-3344
 www.hendrickporsche.com



CUSTOMER NO. 80020123		ADVISOR ANDREW MUELLER	121774	TAG NO. 595	INVOICE DATE 10/30/23	INVOICE NO. POWS103577	
GMP Performance 710 Pressley Rd. Charlotte, NC 28217 QUENTIN@GMPPERFORMANCE.COM		LABOR RATE	LICENSE NO.	MILEAGE 36,753	COLOR /	STOCK NO.	
		YEAR / MAKE / MODEL 15/PORSCHE/911/2DR CPE GT3				DELIVERY DATE	DELIVERY MILES
		VEHICLE I.D. NO. W P 0 A C 2 A 9 3 F S 1 8 9 0 9 6				SELLING DEALER NO.	PRODUCTION DATE
		F.T.E. NO. 006046342		P.O. NO.		R.O. DATE 09/20/23	
RESIDENCE PHONE	BUSINESS PHONE 704-525-0941 x252	COMMENTS				MO: 36762	

R/O TAX 0.00
 R/O TOTALS 112647.01

WARRANTY CLAIM DETAIL TOTALS-----

CLAIM#.....	LABOR...	PARTS...	SUB.LAB.	SUB.PART	GOG.....	MISC....	TAX....	TOTAL....
103577	4403.36	01180.57	0.00	0.00	7063.08	0.00		112647.01
CLAIM TOTALS	4403.36	01180.57	0.00	0.00	7063.08	0.00	0.00	112647.01

SERVICE CHARGE The Service Charge covers or defrays some of Dealer's service department overhead costs, including, but not limited to, shop supplies, employee safety measures and training, and waste disposal and handling, many of which do not lend themselves to precise itemization or allocation. Not all repair or service transactions will cause Dealer to incur all of the costs defrayed by the Service Charge. The Service Charge may include Dealer profit. The Service Charge is not a government required fee.

As part of our effort to provide the highest possible level of service to our customers, we would like your authorization for this Dealership to contact you in order to ensure you are happy with your purchase, keep you informed of new product offerings and promotions, remind you of necessary vehicle maintenance or service, and for any other reason we feel is necessary or appropriate. **UNLESS YOU CHECK THE BOX BELOW**, by signing this form, you give this Dealership **PERMISSION** to contact you (**either personally, via text messages or with prerecorded telemarketing messages**) at the telephone numbers (which may include **wireless phone numbers**), fax number and/or e-mail address listed. This **AUTHORIZATION** allows us to better serve you in compliance with federal and state regulations and in no way is a condition to receiving goods or services.

Please do not contact me as provided above.

Customer agrees that this Agreement includes all of the terms and conditions on the **front and back side hereof**, that this Agreement cancels and supersedes any prior agreement including oral agreements, and as of the date below comprises the entire agreement between Customer and Dealer relating to these repairs or other matters referred to on the front or back side of this document.

APPROVED BY SIGNATURE

Customer Signature

The Reynolds and Reynolds Company ERAINTINVE
 SF602556 Q (01/17)