

Service

197/20 ENU WLM6

4

WLM6 - Checking Brake Lines on the Front Axle and Replace if Necessary (Workshop Campaign)

Model Line: **911 (992)**

718 Boxster / 718 Cayman (982)

Model Year: As of 2020 up to 2021

Concerns: Brake line between brake calliper and brake hose

Information: There is a possibility that the brake lines on the front axle between the brake calliper and brake

hose were damaged during the production process on the affected vehicles.

If this is the case, corrosion can occur at the brake lines over the service life.

Action required: Check FRONT brake line at the left and right and rework or replace it, depending on the result of the

check.


Affected Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Vehicles:

Service WLM6 ENU 197/20

Technical Information

Installation Position:



Installation position of brake lines on front axle

Required parts and materials

Parts Info:

Part No.

Designation

Location

Number

Required parts 992:

V04015006D \Rightarrow Brake line 1 piece

- Front axle, left

"Basic" equipment (M No. A8C) Front disc brake, standard (M No. 1LS)

Service

197/20 ENU WLM6

4

Materials: Required materials (usually already available at the Porsche dealer or locally sourced):

V04015006E \Rightarrow Brake line

1 piece

- Front axle, right

"Basic" equipment (M No. A8C)

Front disc brake, standard (M No. 1LS)

or

V04015006F \Rightarrow Brake line

1 piece

- Front axle, left

"S" equipment (M No. A8F)

Front disc brakes, standard (M No.: 1LS/1LR)

V04015006G \Rightarrow Brake line

1 piece

- Front axle, right

"S" equipment (M No. A8F)

Front disc brakes, standard (M No.: 1LS/1LR)

or

V04015006H \Rightarrow Brake line

1 piece

Front axle, left"Basis/S" equipment

Front PCCB disc brake (M No. 1LQ/1 LX) Front PSCB disc brake (M No. 1ZP/1LZ)

V04015006I \Rightarrow Brake line

1 piece

Front axle, right"Basis/S" equipment

Front PCCB disc brake (M No. 1LQ/1 LX) Front PSCB disc brake (M No. 1ZP/1LZ)

Required parts 982:

V04015006J \Rightarrow Brake line

1 piece

- Front axle, left

V04015006K \Rightarrow Brake line

1 piece

- Front axle, right

Part No.	Designation	Quantity
00004321086	⇒ Brake fluid, 30-liter/ 7.9 gal container	As required (approx. 0.5 liter / 16.9 fl oz required per vehicle)

Expendable

Materials required for **reworking** the brake line:

items:

- Clean, lint-free cloth
- Cleaning solution

Required tools

Tools:

- Torque wrench, 6 50 Nm (4.5 37 ftlb.), e.g. **VAG 1331A Torque wrench, 6-50 Nm (4.5-37 ftlb.)** or equivalent
- Torque wrench, 150 800 Nm (111 592 ftlb.), e.g. **VAG 1601 Torque wrench, 150 800 Nm** (111 592 ftlb.)
- 9796 Socket wrench for central wheel bolt
- 9794 Assembly aid for central wheel bolt
- Suitable bleeding device for brake fluid, e.g. VAS 5234 Brake filling and bleeding equipment

Check front left and right brake lines



Information

The brake lines must be cleaned before starting the visual inspection and must be free of any environmental influences.


The brake line must be replaced if it is not possible to assign precisely the category A-C.

Work Procedure: 1

Move the vehicle onto a lifting platform and raise it. \Rightarrow Workshop Manual '4X00IN01 Raising the vehicle'.

2 Check front left and right brake lines for possible damage.

197/20 ENU WLM6



Limit sample catalogue for brake line

Assessment		Action	
(x)	Category A Replacing brake line Surface coating significantly damaged Zinc coating or base metal clearly visible Significant extent of damage Corrosion visible possibly	⇒ The affected brake line must be replaced. Continue with ⇒ Technical Information '4X00IN01 Replacing brake lines' [Scope 17–46]	
(X)	Category B Reworking brake line Coating damaged minimally Zinc coating visible in small areas Extent of damage very low to low No corrosion visible	The affected brake line must be reworked using an EDDING 750 or touch-up stick (sourced locally). Continue with Step 3. [Scope 2-4, 16, 29-40]	
 (v) Category C Brake line does not have to be replaced or reworked. • Coating not worn through 		End of remedial action Continue with ⇒ Technical Information '4X00IN01 Subsequent work'	

- No zinc coating visible
- Extent of damage very low

[Scope 1]

- 3 Remove all wheels on the front axle. For instructions, see:
 - ⇒ Workshop Manual '440519 Removing and installing wheel'.
 - ⇒ Workshop Manual '440519 Remove and install wheel with central bolt'.
- 4 Rework the affected brake line.
 - 4.1 Clean brake line using a suitable cleaning solution and leave it to dry off.
 - 4.2 Rework the position to be reworked with "EDDING 750".

Note: Any costs incurred for ordering the EDDING 750 or other comparable touch up paint can be invoiced via a subsequent credit appeal on the WLM6 line.

Continue with \Rightarrow *Technical Information '440519 Subsequent work'*.



Reworking brake line

Replacing brake lines



Information


- There are two bleeder valves on the brake calliper. Brake fluid must be drained at both bleeder valves in order to bleed the brakes.
- Always bleed the outer bleeder valve first.

Work Procedure: 1 Unclip electric plug connection for the brake pad wear indicator at the brake line.

2 Replace the affected brake line between the brake calliper and front brake hose.

197/20 ENU WLM6

- 2.1 Loosen and unscrew union nut on the ⇒ Replacing brake line -1 - brake line at the brake calliper ⇒ Replacing brake line -2-. Collect escaping brake fluid in a suitable container.
- 2.2 Loosen and unscrew union nut on the ⇒ Replacing brake line -3- brake line at the brake hose \Rightarrow Replacing brake line -4-. Then remove the brake line and close off the opening on the brake hose using a suitable stopper.



Replacing brake line

- 2.3 Position **new** brake connecting line on the brake calliper ⇒ Replacing brake line -2- and screw in the union nut ⇒ Replacing brake line - 1-with just a few turns initially.
- 2.4 ⇒ Replacing brake line -4- Insert brake line on the brake hose, align it without tension and secure \Rightarrow Replacing brake line -3- it to the brake hose with \Rightarrow Replacing brake line -4- the union nut.
 - Tightening torque 16 Nm (11.8 ftlb.)
- 2.5 Tighten union nut for the \Rightarrow Replacing brake line -1- brake connecting line on the brake calliper \Rightarrow Replacing brake line -2-. Make sure not to twist the brake line while doing this. Tightening torque 16 Nm (11.8 ftlb.)
- Bleed the brake system at all four brake callipers. ⇒ Workshop Manual '470107 Bleed brake system'.

Concluding work

- Install wheels. For instructions, see:
 - ⇒ Workshop Manual '440519 Removing and installing wheel'.
 - ⇒ Workshop Manual '440519 Remove and install wheel with central bolt'.
- Lower the vehicle and remove it from the lifting platform.
- Enter the campaign in the Warranty and Maintenance booklet. 3

Warranty processing

Scope 1: Checking brake lines

Valid for:

- Boxster / Cayman (982)
- 911 (992)

Labor time: 45 TU

Labor time: 60 TU

Labor time:

Checking brake lines Labor time: **35 TU**

Includes: Raising and lowering the vehicle

⇒ Damage Code WLM6 66 000, Repair Code 1

Scope 2: Checking brake lines and reworking them on one side

Valid for:

- Boxster / Cayman (982)
- 911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M No. 1PD)

Labor time:

Checking brake lines and reworking them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line

⇒ Damage Code WLM6 66 000, Repair Code 1

Scope 3: Checking brake lines and reworking them on one side

Valid for:

911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines and reworking them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line

⇒ Damage Code WLM6 66 000, Repair Code 1

Scope 4: Checking brake lines and reworking them on both sides

Valid for:

- Boxster / Cayman (982)
- 911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M No. 1PD)

Service

197/20 ENU WLM6

4

Labor time: 55 TU

Labor time: 79 TU

Labor time: 136 TU

Labor time:

Checking brake line and reworking it on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake lines

⇒ Damage Code WLM6 66 000, Repair Code 1



Information

Scopes 5 to 15 are invalid and are not relevant for this campaign.

Scope 16: Checking brake lines and reworking them on both sides

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake line and reworking it on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake lines

⇒ Damage Code WLM6 66 000, Repair Code 1

Scope 17: Checking brake lines and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M No. 1PD)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006D Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/16.9 floz or

Labor time: 136 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 18: Checking brake lines and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006E Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 19: Checking brake lines and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Service

197/20 ENU WLM6

4

Labor time: 136 TU

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006F Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 20: Checking brake lines and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006G Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 136 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 21: Checking brake lines and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006H Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 136 TU

Labor time: 136 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 22: Checking brake lines and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Service

197/20 ENU WLM6

4

Required parts:

VO4015006I Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 175 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 23: Checking brake lines and replacing them on one side

Valid for:

911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006F Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 24: Checking brake lines and replacing them on one side

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time: 175 TU

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006G Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 175 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 25: Checking brake lines and replacing them on one side

Valid for:

911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006H Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Service

197/20 ENU WLM6

4

Scope 26: Checking brake lines and replacing them on one side

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006l Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 136 TU

Labor time: 175 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 27: Checking brake lines and replacing them on one side

Valid for:

Boxster / Cayman (982)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006J Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/16.9 fl oz or

Labor time: 136 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 28: Checking brake lines and replacing them on one side

Valid for:

Boxster / Cayman (982)

Labor time:

Checking brake lines and replacing them on one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006K Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 29: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Service

197/20 ENU WLM6

4

Labor time: 137 TU

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006D Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 137 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 30: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006E Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 137 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 31: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006F Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 32: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Service

197/20 ENU WLM6

4

Labor time: 137 TU

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006G Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 137 TU

less)

 \Rightarrow Damage Code WLM6 066 000 2

Scope 33: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M No. 1PD)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006H Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/16.9 fl oz or

Labor time: 137 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 34: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006l Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 35: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Service

197/20 ENU WLM6

4

Labor time: 176 TU

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006F Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 176 TU

less)

 \Rightarrow Damage Code WLM6 066 000 2

Scope 36: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006G Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/16.9 fl oz or

Labor time: 176 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 37: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006H Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 38: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Service

197/20 ENU WLM6

4

Labor time: 176 TU

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Reworking brake line Replacing brake line Bleeding brake system

Required parts:

VO4015006l Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 137 TU

less)

 \Rightarrow Damage Code WLM6 066 000 2

Scope 39: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

• Boxster / Cayman (982)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006J Brake line on front axle, left 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

 \Rightarrow Damage Code WLM6 066 000 2

Scope 40: Checking brake lines, reworking them on one side and replacing them on one side

Valid for:

Boxster / Cayman (982)

Labor time:

Checking brake lines, reworking them on one side and replacing them on

one side

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake line Bleeding brake system

Required parts:

VO4015006K Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 146 TU

Labor time: 137 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 41: Checking brake lines and replacing them on both sides

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines and replacing them on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake lines Bleeding brake system

Service

197/20 ENU WLM6

4

Required parts:

V04015006DBrake line on front axle, left1 pieceV04015006EBrake line on front axle, right1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 146 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 42: Checking brake lines and replacing them on both sides

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M
 No. 1PD)

Labor time:

Checking brake lines and replacing them on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake lines Bleeding brake system

Required parts:

V04015006F Brake line on front axle, left 1 piece
V04015006G Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Scope 43: Checking brake lines and replacing them on both sides

Valid for:

911 (992) with standard wheel bolts or wheel bolts with anti-theft protection (M No. 1PA) or (M No. 1PD)

Labor time: 146 TU

Labor time:

Checking brake lines and replacing them on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake lines
Bleeding brake system

Required parts:

V04015006H Brake line on front axle, left 1 piece
V04015006l Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 186 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 44: Checking brake lines and replacing them on both sides

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines and replacing them on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake lines Bleeding brake system

Required parts:

V04015006FBrake line on front axle, left1 pieceV04015006GBrake line on front axle, right1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Service

197/20 ENU WLM6

4

Labor time: 186 TU

Scope 45: Checking brake lines and replacing them on both sides

• 911 (992) with wheels with central wheel lock (M No. 1PJ)

Labor time:

Checking brake lines and replacing them on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake lines Bleeding brake system

Required parts:

VO4015006H Brake line on front axle, left 1 piece
VO4015006I Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

Labor time: 146 TU

less)

⇒ Damage Code WLM6 066 000 2

Scope 46: Checking brake lines and replacing them on both sides

Boxster / Cayman (982)

Labor time:

Checking brake lines and replacing them on both sides

Includes: Raising and lowering the vehicle

Removing and installing wheels on the front axle

Replacing brake lines Bleeding brake system

Required parts:

V04015006J Brake line on front axle, left 1 piece
V04015006K Brake line on front axle, right 1 piece

Required materials:

00004321086 Brake fluid, 30-liter/ 7.9 gal container 0.02 piece

(approx. 0.5 liter/ 16.9 fl oz or

less)

⇒ Damage Code WLM6 066 000 2

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2023 Porsche Cars North America, Inc.