

CUSTOMER #: 103622

28250

INVOICE



17007 111th Ave NW
Edmonton, AB T5S 0J5
Tel (780) 426-3000
Fax (780) 733-7941
www.porschedmonton.com

PORSCHE
CENTRE EDMONTON

PAGE 1



BUS:		CELL:		SERVICE ADVISOR: 9712 MICHAEL N TENNESE			
COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	96	PORSCHE 911	WPOAA2990TS321849		117905/117908	T849	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN96 DD			WAIT 06SEP16		175.00	CASH	06SEP16
R.O. OPENED		READY	OPTIONS: ENG:3.6_Liter/_/282_HP				
06SEP16		06SEP16					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	PERFORM PORSCHE PRE-PURCHASE INSPECTION / /						
	PPI PERFORM PORSCHE PRE-PURCHASE INSPECTION						
	229 CRSC					275.00	275.00
	GOL Go Card Labour Discount					-27.50	-27.50
PARTS:	0.00	LABOR:	275.00	OTHER:	-27.50	TOTAL LINE A:	247.50

117908 2.00

Completed Pre-Purchase Inspection:

EXTERIOR

- Minor Rock Chips On Hood And Headlamp Lenses
- Both Fog Lamp Lenses Are Cracked
- Left Headlamp Washer Jet Slightly Crooked/Loose
- Rust Bubbles At Lower Right Of Windshield
- Windshield Is Cracked
- Dent On Passenger And Above Right Tail Lamp
- Crease On Rear Left Fender
- Minor Scratches Along Hood And Right Front Fender
- Right Rocker Trim Is Loose At Rear And Cover Cap Is Cracked At

Front

- Minor Curb Rash On Both Rear Wheels And Front Right
- Front Bumper Grill Is Loose And Ambient Air Temp Sensor Is

Hanging Down

INTERIOR

- Check Engine Light Is On
- Drivers Seat Is Slow To Move For/Aft, Possibly Needs Lubrication

Or Weak Motor

- Tweeters Are Loose And Separating From Door Panels
- Lighter Socket Inoperative, Possible Fuse
- Wear Around Rear Seat On Centre Console And Drivers Lower

B-Pillar

- A/C Not Blowing Full Cold, Compressor Is Not Cycling On, Possible Low On Charge, Requires

Diagnosis

- Jack, Tire Iron And Tire Compressor Are Missing From Luggage Area/Tool Kit

SERVICE HOURS

Monday - Friday

7:30 am to 5:00 pm

Saturday - Closed

Early/Latenight Drop-off Available

"Thank You for Your Business."

OUT INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. DATE _____	DESCRIPTION	TOTALS
	LABOUR AMOUNT	
	PARTS AMOUNT	
	DISCOUNTS	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	CHARGED TO ACCOUNTS	
	GST	
	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

ALL PORSCHE ACCESSORIES AND REMANUFACTURED PRODUCTS AS WELL AS DEALER LABOUR NECESSARY FOR THE INSTALLATION OF SAID PARTS ARE WARRANTED FOR 24 MONTHS WITH NO KILOMETRE RESTRICTION.

CUSTOMER #: 103622

28250



17007 111th Ave NW
Edmonton, AB T5S 0J5
Tel (780) 426-3000
Fax (780) 733-7941
www.porschedmonton.com

INVOICE

PORSCHE
CENTRE EDMONTON

PAGE 2

BUS:		CELL:		SERVICE ADVISOR: 9712 MICHAEL N TENNESE			
COLOUR	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT TAG	
RED	96	PORSCHE 911		WP0AA2990TS321849		117905/117908 T849	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN96 DD			WAIT 06SEP16		175.00	CASH	06SEP16
R.O. OPENED		READY		OPTIONS: ENG:3.6_Liter/_/282_HP			
06SEP16		06SEP16					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
- Owners Manual/Service Records Not Located In Vehicle							
ROAD TEST							
- Clutch Pedal Is High When Engaging, Possible Worn Disc, No Slippage Yet							
- Steering Wheel Is Off Set To The Left							
- Steering Is Heavier Than Usual/Requires More Effort							
- Rear Spoiler Is Noisy When Operating, May Require Lubrication							
- Exhaust Is Very Loud							
MECHANICALS							
- Front Right Suspension Components Previously Replaced (strut, hub, tie rod), No Evidence Of Major Body Damage							
- Oil Wetness From Steering Rack, Possible Cause Of Heavy Steering							
- Front Tires Worn Heavily On Inside Edges, Minor Cracks On Tires Between Tread, Minor Feathering On Inside Edges Of Rear Tires, Tread Depths FL 4.5mm, FR 4.0mm, RL 5.0mm, RR 4.5mm							
- Brake Cooling Duct On Left Front Control Arm Is Cracked							
- Both Outer C/V Boots Are Split And C/V Joints Are Dry, Recommend Replacing Boots And Re-packing Joints							
- Engine Belly Pan Is Missing							
- Oil Wetness On Engine From Both Chain Housings, Also Minor Wetness At Base Of Cylinder #1							
- Check Engine Light Is On, Faults Stored For Secondary Air System, Suspect Air Passages Are Plugged And Possible Worn Exhaust Valve Guides, Vehicle May Be Due For A Top End Rebuild/Valve Guide Replacement							
- Right Muffler Is Missing, Pipe Has Been Welded On, May Require Replacement Of Cat. Conv. Is Muffler Is To Be Re-installed							
- Lower Ignition Wires Are Deteriorating, Recommend Replacement							
- Minor Surface Rust On Rear Strut/Spring Perch Adjusters							
- Battery Static Voltage = 12.34 V, Tested At 467 A, ~80% State of Charge							
- Brake Measurements Pads/Rotors, FL 7mm/31.5mm, FR 7mm/31.9mm, RL 6mm/23.2mm, RR 6mm/23.2mm							

SERVICE HOURS Monday - Friday 7:30 am to 5:00 pm Saturday - Closed Early/Latenight Drop-off Available "Thank You for Your Business."	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. DATE _____	DESCRIPTION	TOTALS
		LABOUR AMOUNT	
		PARTS AMOUNT	
		DISCOUNTS	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		CHARGED TO ACCOUNTS	
		GST	
ALL PORSCHE ACCESSORIES AND REMANUFACTURED PRODUCTS AS WELL AS DEALER LABOUR NECESSARY FOR THE INSTALLATION OF SAID PARTS ARE WARRANTED FOR 24 MONTHS WITH NO KILOMETRE RESTRICTION.	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	
	X		

CUSTOMER #: 103622

28250



17007 111th Ave NW
Edmonton, AB T5S 0J5
Tel (780) 426-3000
Fax (780) 733-7941
www.porscheedmonton.com

INVOICE

PORSCHE
CENTRE EDMONTON

PAGE 3

BUS:		CELL:		SERVICE ADVISOR: 9712 MICHAEL N TENNESE			
COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
RED	96	PORSCHE 911	WPOAA2990TS321849		117905/117908	T849	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
01JAN96 DD			WAIT 06SEP16		175.00	CASH	06SEP16
R.O. OPENED	READY	OPTIONS: ENG:3.6_Liter/_/282_HP					
06SEP16	06SEP16						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
B							
PERFORM SHORT VEHICLE INSPECTION							
VIS PERFORM SHORT VEHICLE INSPECTION							
				229	CP	0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00

C							
CLIENT IS WAITING AT DEALERSHIP / /							
WAIT CLIENT IS WAITING AT DEALERSHIP							
				999	CP	0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00

D							
CUSTOMER DECLINED CAR WASH							
WN CUSTOMER DECLINED CAR WASH							
				229	CP	0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE D:	0.00

GST	(#: R800568800)	12.38	
SERVICE HOURS Monday - Friday 7:30 am to 5:00 pm Saturday - Closed Early/Latenight Drop-off Available "Thank You for Your Business."	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. DATE _____	DESCRIPTION	TOTALS
		LABOUR AMOUNT	275.00
		PARTS AMOUNT	0.00
		DISCOUNTS	-27.50
		SUBLET AMOUNT	0.00
		MISC. CHARGES	0.00
		TOTAL CHARGES	247.50
		CHARGED TO ACCOUNTS	0.00
		GST	12.38
		CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT
X			