

Delivered Date: 11/27/2017

INVOICE
RO# 16237

Due In: 10/02/2017 Due Out: 11/27/2017

P = Who Pays? (I = Insurance, C = Customer)

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
		Unibody-Frame Incl Setup				Frame	Rpr	2.0		I
		Nozzle,Headlamp Washer LT				Body	R&I	0.1		I
		Seal,Front Fender LT			1	Body	R&I			I
		Door,Fuel Filler LT			1		Blnd		0.9	I
1	Sublet	Wheel,Rear LT	SUBLET REPAIR	220.00		Body	Subl			I
		Wheel,Rear LT A				Body	R&I	0.3		I
1	Parts New	Panel,Rocker LT	99350396101 GRV	2,033.44	1	Body	Repl	3.8		I
1	Parts New	Deflector,Rocker Panel LT	99355951900 01C	227.63		Body	Repl			I
		Deflector,Rocker Panel LT A			1	Body	R&I			I
1	Parts New	Plate,Sill LT	99355198005	989.25	1	Body	Repl			I
1	Parts New	Door Shell,Front LT	99353100502 GRV	3,065.12		Body	Repl	6.6		I
1	Parts New	Label,Front Door LT	99370128724	16.20		Body	Repl	0.2		I
1	Parts New	Glass,Front Door T LT	993 542 011 01	627.21	1	Body	Repl			I
1	Parts New	Reg,Front Door Glass LT	911 542 935 46	603.46	1	Body	Repl			I
1	Parts New	Motor,Front Door Gls LT	911 624 015 43	751.37	1	Body	Repl			I
1	Parts New	Panel,Quarter LT	99350390102 GRV	4,509.41	1	Body	Repl	25.5		I
		Panel,Quarter RT				Body	Rpr	0.5		I
1	Parts New	Label,Quarter Panel LT	477000267	7.11	1	Body	Repl	0.1		I
		Pnl,Quarter Inner LT				Body	Rpr	2.0		I
		Pnl,Quarter Inner LT A					Refn		1.0	I
	Parts New	Shield,Quarter Inner LT			1	Body	R&I			I
		Qtr Glass R & I LT				Body	R&I			I
		Qtr Glass R & I RT				Body	R&I	1.5		I
		W/Strip,Quarter Glass RT				Body	R&I			I
1	Parts New	Cover,Inner Qtr Trim LT	99355141900 01C	50.20	1	Body	Repl			I
		Taillamp Assembly LT				Body	R&I			I
		Taillamp Assembly RT				Body	R&I			I
	Parts Other	Rear Bumper Overhaul				Body	Addl	1.8		I
		Cover,Rear Bumper				Body	Rpr	1.0		I
1	Paint Materials	Flex Additive	ECONOMY PART	15.00			Repl			I
1	Body Materials	Corrosion Protection	ECONOMY PART	44.75	1		Repl		0.3	I
		Colour Tint			1		Refn			I
		Cover Car Exterior			1		Refn		0.3	I
1	Sublet	Clean For Delivery	SUBLET REPAIR	20.00	1	Body	Subl			I
1	Haz Waste	Hazardous Waste Removal	ECONOMY PART	10.00	1	Body	Repl			I

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
1	Sublet	Caulk	SUBLET REPAIR	15.00		Body	Subl	0.3		
	Parts Other	Cover Car Interior					Addl		0.5	
	Parts Other	Front Bumper Cover R&I				Body	Addl	3.0		
		Fender,Front LT					Blnd		2.5	
		Fender,Front LT A			1	Body	R&I	3.5		
		Door Shell,Front LT					Refn		3.4	
		Panel,Rocker LT					Refn		1.6	
		Deflector,Rocker Panel. LT					Refn		1.0	
		Deflector,Rocker Panel RT				Body	R&I	0.5		
		Panel,Quarter LT					Refn		3.8	
		Panel,Quarter RT					Refn		2.6	
		Cover,Rear Bumper A					Refn		3.0	
1	Sublet	4 Wheel Alignment	SUBLET REPAIR	645.62	1	Body	Subl			
		Unibody Pull				Frame	Rpr	2.0		
1	Parts New	VIN Decal	993 701 112 17	271.32	1	Body	Repl	0.2		
5	Parts New	PUSH IN CLIPS	99950748440	5.85	1	Body	Repl			
3	Parts New	SCREW(99991907302)	999 919 073 02	6.60	1	Body	Repl			
6	Parts New	SCREW(99921801601)	999 218 016 01	8.82	1	Body	Repl			
1	Sublet	Stoneguard (LT Fender)	SUBLET REPAIR	59.94	1	Body	Subl			
1	Sublet	Install supl 1/4 stoneguar	SUBLET REPAIR	59.94	1	Body	Subl			
1	Sublet	Tow to clients house Nov27	SUBLET REPAIR	241.56	1	Body	Subl			
1	Parts New	Door Sound pad ,heat mould		50.00	1	Body	Repl	0.6		
2	Parts AM	ROCKER CHIP GUARD	ECONOMY PART	309.02	1	Body	Repl			
		ROCKER CHIP GUARD A			1		Refn		1.0	
		PAINt INSIDE 1/4 FLANGE			1		Refn			
		BODY WORK AT BODY JOIN			1	Body	Rpr			
	Parts Other	cover car for welding			1	Body	Addl	1.0		
1	Parts New	Lt 1/4 inner shield		192.51	1	Body	Repl			
	Bdy/Sup	Body Supplies		565.00						
	Pnt/Mat	Paint & Materials		657.00						

Frame Repair	300.00
Labor	5,580.00
Sublet	1,262.06
Parts	13,794.27
Additional Costs	1,222.00
SubTotal	22,158.33
PST	0.00
GST/HST	1,107.92
Grand Total	23,266.25

Due from Insurance		Due from Customer	
SubTotal	22,158.33	SubTotal	0.00
Tax	0.00	Tax	0.00
GST/HST Tax	1,107.92	GST/HST Tax	0.00
Total	23,266.25	Total	0.00

Total Amount 23,266.25

Thank you for coming to our shop for your repairs. Please like and review us on Google and Facebook.

GST #

INVOICE

#22 01/25/2018 11:58:07 AM RO# 16237

INVOICE
RO #: 16283

Engine: 6cyl Gasoline 3.6

Due In: 8/16/2017 Due Out: 8/16/2017

P = Who Pays? (I = Insurance, C = Customer)

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
		Body Labour Surcharges				Body	Rpr	49.8		I
		Refinsh Labour Surcharges					Ref n		20.4	I
		Frame Labour Surcharges				Frame	Rpr	4.0		I
1	Sublet	Transportation Fee	SUBLET REPAIR	100.00		Body	Subl			I
1	Sublet	Clean For Delivery	SUBLET REPAIR	30.00		Body	Subl			I
1	Paint Materials	Cover Car Exterior	ADDNL LABOR OPERATION	87.50		Body	Addl			I
	Bdy/Sup	MISC Body Supplies		807.00						I
	Pnt/Mat	MISC Paint & Materials		204.00						I

Labor	1,755.00
Frame Repair	300.00
Sublet	130.00
Parts	87.50
Additional Costs	1,011.00
SubTotal	3,283.50
PST	0.00
GST/HST	164.18
Grand Total	3,447.68

Due from Insurance		Due from Customer	
SubTotal	3,283.50	SubTotal	0.00
Tax	0.00	Tax	0.00
GST/HST Tax	164.18	GST/HST Tax	0.00
	-----		-----
Total	3,447.68	Total	0.00

Total Amount 3,447.68

Paid by cheque

Nov 23
[Signature]

Thank you for coming to our shop for your repairs. Please like and review us on Google and Facebook.

RA16283

Repair Surcharge

Premium Automobiles

Body & Refinish: \$88/hour
 Frame: \$150/hour
 Paint Materials: \$40/hour
 Body Materials: \$20/hour (total body hours)

Standard Automobiles

Body & Refinish: \$79/hour
 Frame: \$100/hour
 Paint Materials: \$40/hour
 Body Materials: \$20/hour (total body hours)

Certified Manufacturer Rates

(Audi, Bentley, Porsche)

Body & Refinish: \$100/hour
 Frame: \$150/hour
 Paint Materials: \$40/hour
 Body Materials: \$25/hour (total body hours)

*Aluminum Repairs: \$150/h (All vehicles) *Additional charges for materials may apply.
 Transport Fee: \$100 (Vehicle to go to dealer and back for any dealer or sublet work that is required.)

All Unibody (Frame) work performed on a Celette Bench that will require Jig rentals only specific to the vehicle's year, make, and model. Celette Bench is certified for all European Manufacturers and is required to become a Celette Bench.

Insured Name: _____
 Vehicle: _____

	Cosmos Rate	Insurance Rate	Difference	Hours	Surcharge Totals
Body & Refinish	\$ 100	\$ 75	\$ 25	x 70.2	= \$ 1755
Frame	\$ 150	\$ 75	\$ 75	x 4	= \$ 300
Paint Materials	\$ 40	\$ 30	\$ 10	x 20.4	= \$ 204
Body Materials	\$ 25	\$ 10	\$ 15	x 53.8	= \$ 807
*Aluminum	\$	\$	\$	x	= \$
**Transport Fee	\$ 100	\$ 0	\$ 100		= \$ 100

Miscellaneous Shortfalls:

Clean for delivery: $50 - 20 = 30$
 Cover car exterior: $1h \times 100 + 10 = 110 - 22.50 = 87.50$

= \$ 117.50

3166

Explained and agreed with Insured.

Total = \$ 3283.50 + Tax

Date: _____
 Signed: _____

Preliminary Final