


5. Zip the windstop flap onto the convertible top material.




Emergency operation with top open

Before closing the folding top manually, check the fuses.

Emergency operation when top operating motors are not operational:

1. Remove caps of emergency operation mechanism on both rear side panels.
2. Take the wheel nut wrench from the tool kit and loosen both screws approximately four turns.



3. Pull up the top and carefully place down on the windshield frame.
4. Operate the rocker switch until the indication light in the clock goes out.

Emergency operation when top locking motors are not operational:

Turn both locks with a screwdriver until the locks are visibly locked. Indicator light off.

The defect should be repaired immediately by an authorized Porsche dealer.