

Technical Bulletin

Model
6 Cyl.

Group
4

Subject:

911 Carrera Chassis

Part Identifier
4040

Number
9408

ATTENTION: Service Manager / Service Technician

Model Affected: 911 Carrera

Model Year: 1995

Concern: Some early production 911 Carrera Coupes received different production suspension components.

General Information: Below is a list of VIN ranges and the suspension components that are **different** from production components listed in spare parts microfiche.

Production Version 1:

911 Carrera Coupes produced from December 21, 1993 to January 25, 1994 within the following VIN ranges: 996SS320073 to 992SS320281.

Note: Four vehicles within the above VIN range were equipped with components that were subsequently instituted as Production Version 2. This was done to provide comparison vehicles for production. They are:

994SS320203
993SS320225
998SS320270
991SS320272

The following suspension components installed in Production Version 1 vehicles are different from the components installed in Production Version 3:

Part Number	Description
993 343 041 03	Left front shock
993 343 042 03	Right front shock
993 343 707 00	Front stabilizer (21mm)
964 343 792 18	Front stabilizer bushing (x2)
993 333 051 00	Left rear shock
993 333 052 00	Right rear shock
993 333 701 01	Rear stabilizer (18mm)
477 411 313 B	Rear stabilizer bushing (x2)
993 333 531 07 504	Rear spring set or
993 333 531 08 504	Rear spring set

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.



Technical Bulletin

Model
6 Cyl.

Group
4

Subject:

911 Carrera Chassis

Part Identifier

4040

Number

9408

Production Version 2:

911 Carrera coupes produced from January 25, 1994 to February 10, 1994 within the following VIN ranges: 994SS320282 to 993SS320418 and also including the four vehicles mentioned in **Note** on page 1 of this bulletin.

The following suspension components installed in **Production Version 2** vehicles are different from the suspension components installed in Production Version 3:

Part Number	Description
993 343 041 01	Left front shock
993 343 042 01	Right front shock
993 343 707 00	Front stabilizer (21mm)
964 343 792 18	Front stabilizer bushing (x2)
993 333 051 00	Left rear shock
993 333 052 00	Right rear shock
993 333 701 01	Rear stabilizer (18mm)
477 411 313 B	Rear stabilizer bushing (x2)
993 333 531 07 504	Rear spring set or
993 333 531 08 504	Rear spring set

Production Version 3:

911 Carrera Coupe and Cabriolet produced from February 10, 1994 as of VIN:

995SS320419
990SS320456
99XSS320478 - onward

The following suspension components are installed in **Production Version 3** vehicles:

Part Number	Description
993 343 041 06	Left front shock
993 343 042 06	Right front shock
993 343 707 04	Front stabilizer (20mm)
964 343 792 17	Front stabilizer bushing (x2)
993 333 051 14	Left rear shock
993 333 052 14	Right rear shock

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.



Technical Bulletin

Model
6 Cyl.

Group
4

Subject:

911 Carrera Chassis

Part Identifier
4040

Number
9408

(Production Version 3 cont'd.)

Part Number

Description

993 333 701 00

Rear stabilizer (17mm)

477 411 313 B

Rear stabilizer bushing (x2)

993 333 531 18 504

Rear spring set or

993 333 531 19 504

Rear spring set

Repair Procedures:

While each of the above production versions is acceptable, when repairing 911 Carrera Coupe or Cabriolet in Production Version 1 or 2 only **Production Version 3 suspension parts are available.** The following procedures must be followed when repairing **Production Version 1 or 2 vehicles:**

1. Front or rear shocks. Replace only in pairs.
2. Front or rear springs. Replace only in pairs.
3. Front and rear stabilizers. Replace both front and rear stabilizers together along with the necessary bushings.

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.

