



196 Quality Plaza
Hicksville, NY 11801

Invoice

Date	Invoice #
05/05/2007	11631

Bill To
Steve Elkins

Make/Model:
Year:
VIN:

Item	Description	Quantity	Rate	Amount
2-Parts	FVD GT2 Rear Spoiler with Carbon Wingblade and shipping	1	1,675.00	1,675.00T
2-Parts	FVD GT2 Front 1 piece spoiler with ship	1	895.00	895.00T
	Porsche Factory Parts:			
2-Parts	Breather Cover Plate	1	115.74	115.74T
2-Parts	Oil Screw Plug	1	3.19	3.19T
2-Parts	Rubber O-Ring	1	0.48	0.48T
2-Parts	Engine Cover - Protective Undertray	1	116.61	116.61T
2-Parts	Engine Cover - Undertray	1	105.18	105.18T
2-Parts	Engine Cover Support	1	3.57	3.57T
2-Parts	Dowel Pin	2	3.27	6.54T
2-Parts	Hex head screw	3	1.77	5.31T
2-Parts	Camshaft Cover	2	40.04	80.08T
2-Parts	Paper Gasket	2	2.24	4.48T
2-Parts	Lock Nut	10	0.60	6.00T
2-Parts	Washer	10	1.08	10.80T
2-Parts	Locking Nut	26	0.60	15.60T
2-Parts	Stud	2	3.33	6.66T
2-Parts	Hex Head Screw	2	2.77	5.54T
2-Parts	Woodruff Key	1	0.60	0.60T
2-Parts	Dowel Pin	2	0.77	1.54T
2-Parts	Hex Head Screw	1	3.88	3.88T
2-Parts	Screw	8	2.90	23.20T
2-Parts	Hex Head screw	3	1.77	5.31T
2-Parts	Socket Screw	12	2.37	28.44T
2-Parts	Socket Screw	6	2.60	15.60T
2-Parts	Chain Gear	4	3.47	13.88T
2-Parts	Air Duct	6	25.25	151.50T
2-Parts	Screw 8 x 20	1	1.12	1.12T
2-Parts	Hollow Screw	1	15.17	15.17T
2-Parts	Hollow Screw 12	1	7.19	7.19T
2-Parts	999 Pin	2	3.27	6.54T

Items are intended for off-road use only. Any emissions or performance related modification may effect the vehicle's factory warranty and may not be legal for road use - please check local/state laws for legalities that may arise. By signing the invoice, the customer accepts all liabilities and risks involved with the products installed on their vehicle and acknowledges RPM Racing North is not responsible for misuse of these modifications.

Signature: _____

Subtotal

Sales Tax (8.625%)

Total

Phone #	E-mail	Web Site	Payments/Credits
516-870-0351	Staff@RPMRacingInc.com	www.RPMNorth.com	Balance Due



196 Quality Plaza
Hicksville, NY 11801

Invoice

Date	Invoice #
05/05/2007	11631

Bill To
Steve Elkins

Make/Model:
Year:
VIN:

Item	Description	Quantity	Rate	Amount
2-Parts	Steering Pump Bracket	1	18.86	18.86T
2-Parts	Hex Head Bolt 8 x 16	2	0.23	0.46T
2-Parts	Seal Ring	1	0.42	0.42T
2-Parts	Hollow Screw 16	1	10.98	10.98T
2-Parts	Timing Guide Rail	2	49.19	98.38T
2-Parts	Timing Guide Rail	1	52.06	52.06T
2-Parts	Timing Guide Rail	1	40.31	40.31T
2-Parts	Cylinder Head Gasket	1	617.66	617.66T
2-Parts	Main Bearing <i>short</i>	1	258.59	258.59T
2-Parts	Intermediate Shaft Bearing	2	18.14	36.28T
2-Parts	Intermediate Shaft Bearing	2	40.83	81.66T
2-Parts	Main Bearing Set	1	344.98	344.98T
2-Parts	Crankcase Gasket Set	1	89.20	89.20T
2-Parts	Connecting Rod Bearing Set	1	251.88	251.88T
2-Parts	Chain Case Stud Seal	18	1.91	34.38T
2-Parts	Distributor Cap (List \$115/ea.)	2	63.00	126.00T
2-Parts	Distributor Rotor (List \$52/ea.)	2	31.00	62.00T
2-Parts	Ignition Distributor (993 Carrera Dual Dist. Unit, list \$1245)	1	874.00	874.00T
2-Parts	Freight Charges	1	100.00	100.00T
Other Parts:				
2-Parts	Machine Work - Richard Jacksic (Groove & Drill Main Bearings)	1	65.00	65.00T
2-Parts	Machine Work - Verden Tool (Machine Valve Pockets in Pistons)	1	192.00	192.00T
2-Parts	Pauter Machine - Rebuild Pauter Rods (Factory)	1	550.00	550.00T
2-Parts	Piston and Cylinder Set (OEM) 3.6L with expedited shipping	1	3,395.00	3,395.00T
2-Parts	Fuel Injectors, Bosch Style	1	469.00	469.00T
1-Labor	Labor for Engine Rebuild	57	100.00	5,700.00T

PP
Per

Items are intended for off-road use only. Any emissions or performance related modification may effect the vehicle's factory warranty and may not be legal for road use - please check local/state laws for legalities that may arise. By signing the invoice, the customer accepts all liabilities and risks involved with the products installed on their vehicle and acknowledges RPM Racing North is not responsible for misuse of these modifications.

Signature: _____

Subtotal	\$16,798.85
Sales Tax (8.625%)	\$1,448.90
Total	\$18,247.75

Phone #	E-mail	Web Site	Payments/Credits	\$-10,000.00
516-870-0351	Staff@RPMRacingInc.com	www.RPMNorth.com	Balance Due	\$8,247.75

7661.35



CUSTOMER	VEHICLE	WORK ORDER ADMIN.
----------	---------	-------------------

Elkins Construction
 Steve Elkins
 29 Sweet Hollow Rd
 Huntington, NY
 11743
 H#:631 424-5443 B#:631 424-0552

1996 PORSCHE 911 TURBO
 Plate :
 Odomtr: 0
 V.I.N.:
 Unit #:

WO # : 509
 Date : 01/10/2005
 PO # :
 REG # : 7093143
 Tech. : TASO

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labor	Tx	Total	C
1.00		B&B Headers With Heat Exchangers	2,450.00	2,450.00		TAX	2,450.00	
1.00		B&B High Flow Mufflers	1,100.00	1,100.00		TAX	1,100.00	
1.00		Fabspeed 100 Cell Cats	970.00	970.00		TAX	970.00	
1.00		Protosport Billet Aluminum Intercooler - Custom Fabricated	4,400.00	4,400.00		TAX	4,400.00	
1.00		Set Custom Spec Garrett/Turbonetics Ball Bearing Turbos	2,825.00	2,825.00		TAX	2,825.00	
1.00		Set Tial 40mm Wastegates	750.00	750.00		TAX	750.00	
1.00		2 Split Second Fuel Controller	780.00	780.00		TAX	780.00	
1.00		Set Billet Aluminum Diverters	265.00	265.00		TAX	265.00	
1.00		Freight - B&b	80.00	80.00		TAX	80.00	
1.00		Set High Flow Fuel Injectors	850.00	850.00		TAX	850.00	
1.00		Turbonetics - Freight	45.00	45.00		TAX	45.00	
1.00		Set Of Webb Camshafts - Gt2 Grind, Includ. Shipping	875.00	875.00		TAX	875.00	
1.00		Set (6) Pauter Connecting Rods	1,450.00	1,450.00		TAX	1,450.00	
6.00		Oversized Intake Valve - 51.5	108.00	648.00		TAX	648.00	
6.00		Oversized Exhaust Valve	113.00	678.00		TAX	678.00	
1.00		Set Valve Springs (hardened)	495.00	495.00		TAX	495.00	
1.00		Titanium Retianers	289.00	289.00		TAX	289.00	
1.00		Set (12) Early Valve Seats	96.00	96.00		TAX	96.00	
1.00		Total Seal Piston Rings (set)	280.00	280.00		TAX	280.00	
24.00		Racing Head Studs	21.00	504.00		TAX	504.00	
1.00		Viscous Coupling Unit	855.00	855.00		TAX	855.00	
1.00		Rocker Arm Conversion Kit - Hydraulic To Mechanical	1,095.00	1,095.00		TAX	1,095.00	
1.00		Machine Cylinder Heads To				TAX		

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Sub Tot.	21,780.00	0.00	21,780.00
		TAX	1,905.75
		MIS	0.00
		Deductible	0.00
		Total	23,685.75
		Amt. Paid	14,095.00
		Amt. Owing	9,590.75

CUSTOMER	VEHICLE	WORK ORDER ADMIN.
Elkins Construction Steve Elkins 29 Sweet Hollow Rd Huntington, NY 11743 H#:631 424-5443 B#:631 424-0552	1996 PORSCHE 911 TURBO Plate : Odomtr: 0 V.I.N.: Unit #:	WO # : 509 Date : 01/10/2005 PO # : REG # : 7093143 Tech. : TASO

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labor	Tx	Total	C
		Accept Twin Spark Plugs				TAX		
1.00		Machine Groove For Niresist				TAX		
		Rings - Cylinder Base And				TAX		
		Head				TAX		

Copyright Lankar Systems Inc ABMS 5.0 2005

RPM Racing Inc.
130 Railroad St. Huntington Station, NY 11746
Tel.#: (631) 423-0275 FAX: (631) 423-0276

PAID BY:....
12/08/2004 Visa 6,100.00
12/10/2004 Visa 4,000.00
12/13/2004 Cheque 3,995.00

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Sub Tot.	21,780.00	0.00	21,780.00
		TAX	1,905.75
		MIS	0.00
		Deductible	0.00
		Total	23,685.75
		Amt. Paid	14,095.00
		Amt. Owing	9,590.75



CUSTOMER	VEHICLE	WORK ORDER ADMIN.
Elkins Construction Steve Elkins 29 Sweet Hollow Rd Huntington, NY 11743 H#:631 424-5443 B#:631 424-0552	1996 PORSCHE 911 TURBO Plate : Odomtr: 0 V.I.N.: Unit #:	WO # : 509 Date : 01/10/2005 PO # : REG # : FB6D9469E6V5R5 Tech. : TASO

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
1.00		B&B Headers With Heat Exchangers	2,450.00	2,450.00		TAX	2,450.00	
1.00		B&B High Flow Mufflers	1,100.00	1,100.00		TAX	1,100.00	
1.00		Fabspeed 100 Cell Cats	970.00	970.00		TAX	970.00	
1.00		Protosport Billet Aluminum Intercooler - Custom Fabricated	4,400.00	4,400.00		TAX	4,400.00	
1.00		Set Custom Spec Garrett/Turbonetics Ball Bearing Turbos	2,825.00	2,825.00		TAX	2,825.00	
1.00		Set Tial 40mm Wastegates	750.00	750.00		TAX	750.00	
1.00		Set Billet Aluminum Diverters	265.00	265.00		TAX	265.00	
1.00		Freight - B&b	80.00	80.00		TAX	80.00	
1.00		Set High Flow Fuel Injectors	850.00	850.00		TAX	850.00	
1.00		Turbonetics - Freight	45.00	45.00		TAX	45.00	
1.00		Set Of Webb Camshafts - Gt2 Grind, Includ. Shipping	875.00	875.00		TAX	875.00	
1.00		Set (6) Pauter Connecting Rods	1,450.00	1,450.00		TAX	1,450.00	
6.00		Oversized Intake Valve - 51.5	108.00	648.00		TAX	648.00	
6.00		Oversized Exhaust Valve	113.00	678.00		TAX	678.00	
1.00		Set Valve Springs (hardened)	495.00	495.00		TAX	495.00	
1.00		Titanium Retianers	289.00	289.00		TAX	289.00	
1.00		Set (12) Early Valve Seats	96.00	96.00		TAX	96.00	
1.00		Total Seal Piston Rings (set)	280.00	280.00		TAX	280.00	
24.00		Racing Head Studs	21.00	504.00		TAX	504.00	
1.00		Viscous Coupling Unit	855.00	855.00		TAX	855.00	
1.00		Hardware And Shaft For V.c.	125.00	125.00		TX1	125.00	
1.00		Rocker Arm Conversion Kit - Hydraulic To Mechanical	1,095.00	1,095.00		TAX	1,095.00	
1.00		Machine Cylinder Heads To	550.00	550.00		TAX	550.00	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the vehicle listed above for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Sub Tot.	35,495.50	0.00	35,495.50
		TX1	3,105.86
		TX2	0.00
		Deductible	0.00
		Total	38,601.36
		Amt. Paid	37,135.63
		Amt. Owing	1,465.73



CUSTOMER	VEHICLE	WORK ORDER ADMIN.
Elkins Construction Steve Elkins 29 Sweet Hollow Rd Huntington, NY 11743 H#:631 424-5443 B#:631 424-0552	1996 PORSCHE 911 TURBO Plate : Odomtr: 0 V.I.N.: Unit #:	WO # : 509 Date : 01/10/2005 PO # : REG # : FB6D9469E6V5R5 Tech. : TASO

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		Accept Twin Spark Plugs				TAX		
1.00		Machine Groove For Niresist	950.00	950.00		TAX	950.00	
		Rings - Cylinder Base And				TAX		
		Head Including Custom Made				TAX		
		Niresist Rings				TAX		
1.00		Machine Clyinder Heads To	399.00	399.00		TAX	399.00	
		Accept .5mm Over Sized Intake				TAX		
		& Exhaust Valves And Machine				TAX		
		Valve Seats				TAX		
1.00		Machine Pockets In Pistons	250.00	250.00		TX1	250.00	
1.00		Shipping - Cylinder Heads	95.00	95.00		TAX	95.00	
		(round Trip)				TAX		
1.00		996 Motorsport Oil Pump -	941.00	941.00		TAX	941.00	
		\$1139 Retail				TAX		
1.00		Cross Drill And Modify	800.00	800.00		TX1	800.00	
		Crankshaft And Case				TX1		
12.00		Valve Guides	12.50	150.00		TAX	150.00	
1.00		Swaintech Coating - 6	1,050.00	1,050.00		TX1	1,050.00	
		Pistons, 6 Cylinders And 12				TX1		
		Valve Faces				TX1		
1.00		Spec Stage 3-F Clutch Kit	945.00	945.00		TAX	945.00	
1.00		Electromotive Tec3r	2,695.00	2,695.00		TAX	2,695.00	
1.00		Plug And Play Harness	685.00	685.00		TAX	685.00	
1.00		Idle Speed Control	170.00	170.00		TAX	170.00	
1.00		Wide Band O2 Sensor	425.00	425.00		TAX	425.00	
1.00		Sequential Injection	190.00	190.00		TAX	190.00	
1.00		Set Plug Wires	280.00	280.00		TAX	280.00	
1.00		Shipping - Electromotive	75.00	75.00		TAX	75.00	
6.00		Porsche O.e.m. Rod Bearings	41.00	246.00		TX1	246.00	
1.00		Hardware For Camshafts -	115.00	115.00		TX1	115.00	

I hereby authorize the above repair work to be done along wit the necessary materials. You and your employees may operate the vehicle listed above for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repiars thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Sub Tot.	35,495.50	0.00	35,495.50
		TX1	3,105.86
		TX2	0.00
		Deductible	0.00
		Total	38,601.36
		Amt. Paid	37,135.63
		Amt. Owing	1,465.73



WWW.RPMRACINGINC.COM

CUSTOMER	VEHICLE	WORK ORDER ADMIN.
Elkins Construction Steve Elkins 29 Sweet Hollow Rd Huntington, NY 11743 H#:631 424-5443 B#:631 424-0552	1996 PORSCHE 911 TURBO Plate : Odomtr: 0 V.I.N.: Unit #:	WO # : 509 Date : 01/10/2005 PO # : REG # : FB6D9469E6V5R5 Tech. : TASO

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		Porsche Oem (shims, Flanges, Washers, Etc.)				TX1		
2.00		Cam Sprockets 993 Oem	31.00	62.00		TX1	62.00	
2.00		Turbo Oil Inlet Lines - Oem	119.00	238.00		TX1	238.00	
9.00		Case Washers - Engine Misc.	3.50	31.50		TX1	31.50	
1.00		Intake O-ring/intercooler Gskt	19.00	19.00		TX1	19.00	
1.00		Blitz Sbc I-d Boost Controller - Black, Shipped	550.00	550.00		TAX	550.00	
1.00		Sparco Evo 2 Seat W/ship + Brackets	690.00	690.00		TX1	690.00	
2.00		Seat Heater Kit With Shipping	89.00	178.00		TX1	178.00	
1.00		Brey Krause Side Mount Kit	108.00	108.00		TX1	108.00	
3.00		Bosch Connectors For Tps/tec3	41.00	123.00		TX1	123.00	
1.00		Front Mount Gt2 Oil Cooler Kit	960.00	960.00		TX1	960.00	
1.00		Turbonetics Silicone Hosing - 90 Elbows, Reduces, Connectors And Joints	400.00	400.00		TX1	400.00	

Copyright Lankar Systems Inc. ABMS 5.0 200

RPM Racing Inc.
130 Railroad St. Huntington Station, NY 11746
Tel.#: (631) 423-0275 FAX: (631) 423-0276

PAID BY:...
12/8/2004 Visa 6,100.00
12/10/2004 Visa 4,000.00
12/13/2004 Cheque 3,995.00
1/18/2005 Visa 3,295.00

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the vehicle listed above for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Sub Tot.	35,495.50	0.00	35,495.50
		TX1	3,105.86
		TX2	0.00
		Deductible	0.00
		Total	38,601.36
		Amt. Paid	37,135.63
		Amt. Owing	1,465.73

Repair Order #

1322

Estimate Ref # 0

Date Printed: 07/16/2008

7:00 pm

RPM North

120 Fairchild Ave.

Plainview, NY 11803-0000

Phone: (516) 870-0351

Fax: (516) 870-0353

E-mail: Staff@RPMNorth.com

Web Address: www.RPMNorth.com

Repair Order

Elkins, Steve	Hat/ref # 1996 PORSCHE 911 TURBO H6 3.6L 3606CC FI GAS T C	Promised Time:
29 Sweet Hollow Rd.	VIN:	Date Written: 07/16/2008
Huntington, NY 11743-0000	License:	Written By:
	Unit #:	Save Old Parts: No
	DOM:	
	Mileage In: 0	
	Mileage Out: 0	

Job #1	Remove and replace alternator			
Labor -- Rate 1	Work Requested - Alternator problem	4.00	\$126.00	\$504.00
	Door light switch			
Work Performed - Remove and replace alternator				
Remove and replace belts				
Look at door light switch (working properly)				
Part -- 11654-9356846	Porsche alternator	1.00	\$1,234.79	\$1,234.79
Part --	Accesory belt	1.00	\$12.89	\$12.89
Part --	Accesory belt	1.00	\$20.76	\$20.76
Part --	Accesory belt	1.00	\$7.96	\$7.96
	SubTotal:			\$1,780.40

All items are intended for off-road use only, unless otherwise noted. Any emissions or performance related modification may effect the vehicle's aftermarket warranty and may not be legal for road use - please check local/state laws for legalities that may arise. By signing the invoice, the customer accepts all liabilities and risks involved with the products installed on their vehicle and acknowledges RPM Racing North is not responsible for misuse of these modifications.

Signature: 

Parts:	\$1,276.40
Labor:	\$504.00
Sublet:	\$0.00
Misc:	\$0.00
Discount:	\$0.00
Hazmat:	\$1.00
Supplies:	\$1.00
Tax:	\$153.56
Total:	\$1,935.96

Repair Order #

1147

RPM North

120 Fairchild Ave.

Plainview, NY 11803-0000

Phone: (516) 870-0351

Fax: (516) 870-0353

E-mail: Staff@RPMNorth.com

Estimate Ref # 0
Date Printed: 11/16/2007
5:14 pm

Web Address: www.RPMNorth.com

Repair Order

	Hat/ref #	Promised Time:
Elkins, Steve	1996 PORSCHE 911 TURBO H6 3.6L 3606CC FI GAS T C	
29 Sweet Hollow Rd.	VIN:	Date Written: 11/16/2007
Huntington, NY 11743-0000	License:	Written By:
	Unit #:	Save Old Parts: No
	DOM:	
	Mileage In: 0	
	Mileage Out: 0	

Job #1	GT30R Turbo Upgrade			
Labor -- Rate 1	refabricate headers to fi...			
	Work Requested - GT30R Turbo Upgrade	1.00	\$4,200.00	\$4,200.00
	refabricate headers to fit new turbo			
	install			
	tune			
			SubTotal:	\$4,200.00

All items are intended for off-road use only, unless otherwise noted. Any emissions or performance related modification may effect the vehicle's aftermarket warranty and may not be legal for road use - please check local/state laws for legalities that may arise. By signing the invoice, the customer accepts all liabilities and risks involved with the products installed on their vehicle and acknowledges RPM Racing North is not responsible for misuse of these modifications.

Signature: _____

Parts:	\$0.00
Labor:	\$4,200.00
Sublet:	\$0.00
Misc:	\$0.00
Discount:	\$0.00
Hazmat:	\$0.00
Supplies:	\$0.00
Tax:	\$362.25
Total:	\$4,562.25
Less Paid:	\$4,562.25
Balance Due:	\$0.00

Quote

Date Printed: 12/21/2007 3:47:04PM

RPM North
 120 Fairchild Ave.
 Plainview, NY 11803-0000
 Phone --(516) 870-0351

Elkins Steve
 29 Sweet Hollow Rd.
 Huntington, NY 11743-0000

1996 PORSCHE 911 TURBO H6 3.6L 3606CC FI GAS T C

Written By:

Job #1	Install Fire System		Tech:	
Labor--Install Fire System		4.00	\$126.00	\$504.00
Part--Fire System		1.00	\$500.00	\$500.00
Job Subtotal :				\$1,004.00

All items are intended for off-road use only, unless otherwise noted. Any emissions or performance related modification may effect the vehicle's aftermarket warranty and may not be legal for road use - please check local/state laws for legalities that may arise. By signing the invoice, the customer accepts all liabilities and risks involved with the products installed on their vehicle and acknowledges RPM Racing North is not responsible for misuse of these modifications.

Signature: _____

Parts	\$500.00
Labor	\$504.00
Sublet	\$0.00
Misc	\$0.00
Hazmat	\$1.00
Supplies	\$1.00
Tax	\$86.60
Total	\$1,092.60

Invoice #

1038

RPM North

120 Fairchild Ave.

Plainview, NY 11803-0000

Phone: (516) 870-0351

Fax: (516) 870-0353

E-mail: Staff@RPMNorth.com

Web Address: www.RPMNorth.com

Estimate Ref # 0

Date Printed: 04/05/2008

2:30 pm

Invoice

Hat/Ref #

Promised Time:

Elkins, Steve
29 Sweet Hollow Rd.
Huntington, NY 11743-0000

1996 PORSCHE 911 TURBO H6 3.6L 3606CC FI GAS T C

VIN:

Date Written: 08/25/2007

License:

Mileage In: 0

Written By: Anthony

Unit #:

Mileage Out: 0


Save Old Parts: No

DOM:

Part	--	Clutch masters clutch kit	1.00	\$1,775.00	\$1,775.00
Sublet	--	Work Requested - Resurface Flywheel	1.00	\$100.00	\$100.00
Work Performed - Resurfaced flywheel					

Job Subtotal: \$26,730.00

Paid in full



Invoice #

1038

RPM North

Estimate Ref # 0
 Date Printed: 08/29/2007
 6:11 pm

120 Fairchild Ave.
 Plainview, NY 11803-0000
 Phone: (516) 870-0351
 Fax: (516) 870-0353
 E-mail: Staff@RPMNorth.com
 Web Address: www.RPMNorth.com

Invoice

Invoice	Hat/ref #	Promised Time:
Elkins, Steve 29 Sweet Hollow Rd. Huntington, NY 11743-0000	1996 PORSCHE 911 TURBO H6 3.6L 3606CC FI GAS T C VIN: License: Unit #: DOM:	Date Written: 08/25/2007 Written By: Anthony Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	Allignment	Eddie			
Labor -- Rate 1	Work Requested - Job		0.00	\$126.00	\$0.00
	Work Performed - Tech performed troubleshooting, isolation and removed intergrated Tech 3 electro motive system and installed Haltech Stand Alone system. Tech created custom Fabricated 3" stainless steel exhaust system including fitment to bumper. Tech fabricated custom heat exchanger. Modified existing intercooler. Installed 4" high flow open element air filter. Install and isolated motorsport fuel pump, fittings, lines encased in rubber, installed Bosch 5 bar fuel pressure regulator. Performed full 4 wheel 3-D alignment. Replaced throwout bearing that was provided with parts from customer.R&I new intake air temperature sensor and throttle position sensor. Installed 12 new NGK V-power racing spark plugs. Installed and wired two digital 6 MSD boxes and coils and fabricated mounts for the MSD coils. Twin plug distributor was installed with new caps and rotors and complete ignition wire set. Fabricate intercooler inlet pipes and four silicone hoses.				
Labor -- Rate 1	Work Requested - Job		0.00	\$126.00	\$0.00
	Work Performed - Assembled intake manifolds, injectors, fuel rails, exhaust manifolds, turbos, wastegates, wastegate dump tubes, oil lines for turbo, oil return lines, brackets. Installed flywheel, new flywheel bolts, clutch and pressure plate, throw out bearing. Install transmission on to motor including starter, slave cylinder, reverse light switch. Then install motor and transmission into the engine cradle of the car. R&I suspension brackets, bolts. Trouble shoot problem with ignition trigger. Realized flywheel trigger was damaged. Custom fabricated front pulley with trigger to use with Holafect sensor from Haltech. R&I rear bumper and modify crossmember bracket for exhaust system. Modified rear GT2 deck lid for clearance on intercooler.				
Labor -- Rate 1	Work Requested - Job		160.00	\$126.00	\$20,160.00
	Work Performed - Fixed gauges and heater control unit. straightened up interior. Fixed door switch installed front seats and seatbelts. Installed center console and reconfigured wiring inside of cockpit. R&I shift light requested by customer. R&I roll cage, and modified rear deck dash piece				
Labor -- Rate 1	Work Requested - innovate gauge install		5.00	\$126.00	\$630.00
	Work Performed - innovate gauge install				

Invoice #

1038

Estimate Ref # 0

Date Printed: 08/29/2007

6:11 pm

RPM North

120 Fairchild Ave.

Plainview, NY 11803-0000

Phone: (516) 870-0351

Fax: (516) 870-0353

E-mail: Staff@RPMNorth.com

Web Address: www.RPMNorth.com

Invoice

Invoice	Hat/ref #	Promise Time:
Elkins, Steve	1996 PORSCHE 911 TURBO H6 3.6L 3606CC FI GAS T C	
29 Sweet Hollow Rd. Huntington, NY 11743-0000	VIN: License: Unit #: DOM:	Date Written: 08/25/2007 Written By: Anthony Save Old Parts: No
	Mileage In: 0 Mileage Out: 0	

Job Name	Description	Technician	Qty	List	Extended
Part --	magnaflow muffler		2.00	\$150.00	\$300.00
Part --	U bend piping 3in		4.00	\$100.00	\$400.00
Part --	3in to 2.5in reducer		2.00	\$80.00	\$160.00
Part --	Innovate wideband air fuel/ratio gauge		1.00	\$490.00	\$490.00
Part --	993 window switch regulator		1.00	\$50.00	\$50.00
Part --	993 TPI sensor		1.00	\$29.00	\$29.00
Part --	993 fuel pressure regulator		1.00	\$200.00	\$200.00
Part --	993 motorsport fuel pump		1.00	\$320.00	\$320.00
Part --	MSD Ignition		2.00	\$575.00	\$1,150.00
Part --	MSD coils		2.00	\$150.00	\$300.00
Part --	Seat Buckle		2.00	\$0.00	\$0.00
Part --	4" Cone filter		1.00	\$80.00	\$80.00
Part --	Throw out bearing		1.00	\$45.00	\$45.00
Part --	NGK V-Power racing spark plugs		12.00	\$5.50	\$66.00
Sublet --	Work Requested - fix leather on back dash piece		1.00	\$475.00	\$475.00
Work Performed - Performed					
Job Subtotal :				\$24,855.00	

RPM North

120 Fairchild Ave.

Plainview, NY 11803-0000

Shop Phone: (516) 870-0351

Fax: (516) 870-0353

Email: Staff@RPMNorth.com

Web Address: www.RPMNorth.com

Repair Order

1421

Estimate Ref #1,103

Date Printed: 02/03/2009

Printed Time: 2:45 pm

Hat/Ref:

Time Promised:

Elkins, Steve
 29 Sweet Hollow Rd.
 Huntington, NY 11743
 Home: Work:
 Cell: (516) 351-1955

1996 PORSCHE 911 TURBO H6 3.6L 3606cc FI GAS T C
 VIN:
 License: Mileage In: 0 Date Written: 12/10/2008
 Unit #: Mileage Out: 0 Written By:
 DOM: Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	Install Motec, build wiring...				
Part	M600		1.00	3,632.00	3,632.00
Part	CDI-8		1.00	2,400.00	2,400.00
Part	Datalogging 512		1.00	315.00	315.00
Part	Dual wideband		1.00	1,162.00	1,162.00
Part	Dual coils		6.00	145.00	870.00
Part	CDI wiring harness		1.00	662.04	662.04
Part	Trigger wheel		1.00	130.00	130.00
Part	Crank trigger		1.00	192.00	192.00
Part	Magnets		1.00	14.00	14.00
Part	Baro sensor		1.00	223.40	223.40
Part	Pressure transducer		2.00	225.00	450.00
Part	TPS		1.00	240.00	240.00
Part	Bosch LSM sensors		2.00	340.00	680.00
Part	Air temp sensor		1.00	53.00	53.00
Part	Head temp sensor		1.00	126.00	126.00
Part	M600 harness		1.00	625.00	625.00
Part	Termination kit		1.00	105.00	105.00
Labor Rate 1	Work Requested - Install Motec, build wiring harness and tune on Dyno		40.00	126.00	5,040.00
Part	Dyno time		1.00	400.00	400.00
				Discount:	2,650.00
				Job Total:	14,669.44

All items are intended for off-road use only, unless otherwise noted. Any emissions or performance related modification may effect the vehicle's aftermarket warranty and may not be legal for road use - please check local/state laws for legalities that may arise. By signing the invoice, the customer accepts all liabilities and risks involved with the products installed on their vehicle and acknowledges RPM Racing North is not responsible for misuse of these modifications.

Signature: _____

Payment Date	Type	Method	Amount
1/19/2009	Other		1,750.00
2/3/2009	Cash		7,000.00
Payment Totals:			\$8,750.00

Parts:	\$12,279.44
Labor:	\$5,040.00
Sublet:	\$0.00
Misc:	\$0.00
Discount:	\$2,650.00
Hazmat:	\$1.00
Supplies:	\$1.00
Tax:	\$1,265.24
Invoice Total:	\$15,936.68
Less Paid:	8,750.00
Balance Due:	\$7,186.68

Lm 24
1 Gear Ave
Lindenhurst N.Y

11757
111
111
111

Invoice

Invoice No: 0
Date: 29 May 13

Bill To:

Steve Elkins

Description	Quantity	Rate	Amount
Intercooler fabrication	1.00	\$2,900.00	\$2,900.00
Intercooler piping	2.00	\$275.00	\$550.00
Repair throttle body	1.00	\$100.00	\$100.00
Repair wiring	8.00	\$125.00	\$1,000.00
Repair vacuum leaks	10.00	\$100.00	\$1,000.00
Oil change	1.00	\$90.00	\$90.00
Spark plugs	12.00	\$9.00	\$108.00
Injector cleaning	6.00	\$25.00	\$150.00
Labor Install spark plugs Install injector Replace injector seal	3.00	\$100.00	\$300.00
Apex-1 boost controller	1.00	\$550.00	\$550.00
Labor Install boost controller	2.50	\$100.00	\$250.00
Detail Wash Wax Interior detail	1.00	\$400.00	\$400.00
Rear lights	1.00	\$200.00	\$200.00

Description	Quantity	Rate	Amount
Previous balance	1.00	\$400.00	\$400.00
Recalibrate ECU			
Repair fan harness			
Repair fuel pump harness			

* Indicates non-taxable item

Subtotal	\$7,998.00
TAX (0.00%)	\$0.00
Total	\$7,998.00
Paid	\$5,000.00
Balance Due	\$2,998.00