

**CUSTOMER**  
BHAT002  
Mr. Inayatullah Bhatti  
NA

**VEHICLE**  
REGISTRATION : 12806 I  
MAKE : Porsche  
MODEL : 996  
CHASSIS NUMBER : 991S640083  
ENGINE NUMBER :  
COLOUR : Black

DATE 26/08/2012  
ESTIMATE NUMBER **6720**

**WORK TO BE DONE** Note : We have confirmed that engine oil seperator is faulty, need to replace first to see if we have any further problem on the engine

	<b>Labour Rate</b>	<b>Hours Est.</b>	<b>Price</b>
replace oil seperator		2.5	750.00
flush engine and cooling system		4	1,200.00

## **PARTS/MATERIALS**

<b>PART NUMBER DESCRIPTION</b>	<b>Price</b>	<b>QTY</b>	<b>Total Price</b>
OIL SEPARATOR	554.00	1	554.00
FILTER ELEMENT	113.00	1	113.00
SEALING RING	6.00	1	6.00
ENGINE OIL(208L)	45.00	9	405.00
cooling system flush	140.00	1	140.00
engine coolant	16.00	12	192.00
BIO DEGREASER	100.00	2	200.00
ENGINE OIL VISCO 2000	25.00	8	200.00
Consumables	120.00	1	120.00

LABOUR : **1,950.00**  
PARTS : **1,930.00**  
SUB-TOTAL : **3,880.00**  
TOTAL : **3,880.00**

Terms & conditions apply as per jobsheet or armotors.ae