

R&D Automotive

16 Tivoli Street

Albany NY 12207

Phone: 518-598-1273

Fax: 518.598.1275

BavarianRocketScience@gmail.com

BavarianRocketScience.com

Repair Shop 7036352

WORK ORDER

PAUL BAUMGARTNER

Albany NY 12207

21475
4/19/2019

Key #:
Date In: 4/15/19
Time In: 3:07PM

Cust.#: 3713
PO Nbr:

Lic# 93822 Veh ID:
2005 PORSCHE 911 Turbo Cabriol
VIN: WP0CB29955S675309 3.6 T
Odometer In: Out: 74,773
Inspection Due: Hrs:

Ident/Ser#:

Item	Qty/Time	Description	Price/Rate	Amount	
PARTS					
TIRE	2.00	225/40ZR18 BRIDGESTONE POTENZA S-02A	245.72	491.44	1
SHIPPING	1.00	SHIPPING	48.00	48.00	1
HARDWARE	1.00	WHEEL WEIGHTS , VALVE STEMS ETC.	10.00	10.00	1
1890991044	3.00	BRAKE AND PARTS CLEANER	10.00	30.00	1
996 349 293 00	2.00	CV Boot Kit-Front Inner	60.82	121.64	1
996 349 291 00	2.00	CV Boot Kit-Front Outer	60.82	121.64	1
22-052568	2.00	Strut Assembly-Front	574.88	1149.76	1
996 343 501 00	2.00	Strut Bearing-Front	49.01	98.02	1
99634301504	1.00	STRUT MOUNT LEFT FT UPPER	316.77	316.77	1
99634301604	1.00	STRUT MOUNT RIGHT FT UPPER	316.77	316.77	1
99634352300	2.00	SUPPORT RING	24.82	49.64	1
99633305903	2.00	STRUT MOUNT FLANGE WITH STUDS	166.00	332.00	1
99634330102	2.00	BUMP STOP FRONT	20.54	41.08	1
24-068116	2.00	Shock Absorber-Rear	326.00	652.00	1
996 333 059 03	2.00	Strut Mount-Rear	163.61	327.22	1
99633310503	2.00	REAR BUMP STOPS	39.62	79.24	1
99333310701	2.00	BELLOWS , REAR	22.01	44.02	1
996 512 551 03	2.00	Hatch Strut	62.11	124.22	1
996 511 551 01	2.00	Hood Strut	50.54	101.08	1
BF1200	1.00	BRAKE FLUID, LITER ATE YELLOW	24.00	24.00	1
996 107 225 60	1.00	Oil Filter Kit w/ O-Ring	24.70	24.70	1
0W40	9.00	OIL, MOBIL 1 0W40	12.18	109.62	1
3 397 001 582	1.00	Wiper Blade Set-Front 550mm/530mm	74.35	74.35	1
99661371601	1.00	SEAT SWITCH - DRIVER SIDE	570.00	570.00	1
99661371901	1.00	SEAT SWITCH - PASSENGER	570.00	570.00	1
99650412300	1.00	FENDER LINER AERO - LEFT/FRONT	135.00	135.00	1
PPI	1.00	PRE OR POST PURCHASE INSPECTION	125.00	125.00	1
LABOR					
TIRE DISPOSAL	2.00	TIRE DISPOSAL	8.00	16.00	1
M/B 35 - 45	2.00	MOUNT AND BALANCE TIRE LOW PROFILE AND 19 OR 20 INCH RIMS	35.00	70.00	1
8	5.00	PORSCHE LABOR - INSTALL INNER AND OUTER CV BOOTS ON FRONT AXLES	125.00	625.00	1
8	4.00	PORSCHE LABOR - INSTALL FRONT STRUTS	125.00	500.00	1

93822

2005 PORSCHE 911 Turbo Cabriol

tl

21475

PAUL BAUMGARTNER

R&D Automotive

16 Tivoli Street

Albany NY 12207

Phone: 518-598-1273

Fax: 518.598.1275

BavarianRocketScience@gmail.com

BavarianRocketScience.com

Repair Shop 7036352

WORK ORDER

Item	Qty/Time	Description	Price/Rate	Amount	
8	4.00	PORSCHE LABOR - INSTALL REAR SHOCKS AND RELATED PARTS	125.00	500.00	1
8	3.50	PORSCHE LABOR - 4 WHEEL ALIGNMENT	125.00	437.50	1
8	1.00	PORSCHE LABOR - INSTALL HOOD AND DECK STRUTS	125.00	125.00	1
8	2.00	PORSCHE LABOR - REMOVE AND REINSTALL FRONT BUMPER COVER TO CLEAN OUT DEBRIS	125.00	250.00	1
BRAKEFLUSH	0.80	BRAKE SYSTEM FLUSH (.8)	125.00	100.00	1
LOF911	0.80	LOF 911/ONE FILTER (.8)	125.00	100.00	1
8	0.50	PORSCHE LABOR - AIM HEADLIGHTS	125.00	62.50	1
8	3.00	PORSCHE LABOR - REPLACE SEAT SWITCHES, BOTH SIDES	125.00	375.00	1
8	0.50	PORSCHE LABOR - INSTALL FENDER LINER AIR DUCT	125.00	62.50	1

Total Parts:	6087.21	Paid With	Sub Total:	9310.71
Total Labor:	3207.50		Sales Tax	744.86
Total Sublet:	16.00			

Writer: 1

Invoice Amount: **10055.57**

Ref/Ser:

Less Deposits:

Contact Ph: **CELL 518-421-9639**

Balance Due: 10055.57

PPI:

1. CUSTOMER STATES CAR WANDERS - CHECK TIRE PRESSURES - OK - SIGNS OF PREVIOUS TIRE RUB IN REAR, BOTH SIDES - FRONT TIRES SEVERELY WORN ON INSIDE EDGES, BEYOND WEAR BARS AND HAVE DRY ROT - NEEDS TWO TIRES (BRIDGESTONE POTENZA S02A - 225/40-18) - \$650 - \$700 INSTALLED - 4 SHOCKS NEEDED, FRONT \$2805 REAR \$1602, 4 WHEEL ALIGNMENT \$437.50
2. FRONT DRIVER OUTER CV BOOT TORN/LEAKING, PASSENGER SIDE CLOSE AS WELL RECOMMEND ALL 4 \$870
3. RECOMMEND OIL AND FILTER CHANGE - \$250
4. RADIATORS FULL OF ROAD DEBRIS - NEED TO BE CLEANED \$250
5. NEEDS HEADLIGHTS AIMED - AIM HEADLIGHTS \$62.50
6. RECOMMEND BRAKE FLUID FLUSH \$124
7. WIPERS OLD/WORN - REPLACE WIPER BLADES \$75
8. NEEDS FRONT TRUNK/BOOT STRUTS AND REAR ENGINE DECK/HATCH STRUTS \$360

OTHER NOTES/RECOMMENDATIONS:

- A. SEAT SWITCHES - FRONT DRIVER, REAR PASSENGER BROKEN, LIMITED FUNCTIONALITY
- B. LEFT FRONT FENDER LINER/ UNDER TRAY DUCT/UNDER BODY AERO MISSING- OTHER COMMON SIGNS OF BOTTOMMING OUT AND TIRE RUB
- C. TRANSMISSION GASKET LEAK - TRANSFER CASE WET/DAMP - CLEAN AND RECHECK IN 500 MILES?
- D. HEADLINER TORN ON PASSENGER SIDE C PILLAR - WILL NEED TO GO TO UPHOLSTEROR FOR ESTIMATE, BALLPARK \$200-\$300 TO RESTITCH?
- E. CRACKED PAINT ON FRONT BUMPER/ DRIVERS SIDE FRONT PANEL FITMENT NOT GREAT - BALLPARK \$1000-\$1200?
- F. RUST BUBBLE STARTING ON DRIVERS SIDE DOOR - FRONT/BOTTOM - \$500-\$750? (NEEDS ESTIMATE FROM BODYSHOP)
- G. DEBRIS/INSULATION IN INTERIOR VENTS
- H. WEAR ON CONVERTIBLE TOP - NEW TOP APPROX \$2300-\$2600 INSTALLED

93822

2005 PORSCHE 911 Turbo Cabriol

tl

21475

PAUL BAUMGARTNER

Page 2 Of 3

R&D Automotive

16 Tivoli Street

Albany NY 12207

Phone: 518-598-1273

Fax: 518.598.1275

BavarianRocketScience@gmail.com

BavarianRocketScience.com

Repair Shop 7036352

WORK ORDER

Item	Qty/Time	Description	Price/Rate	Amount
12 MONTHS OR 12,000 MILE WARRANTY ON NEW PARTS AND LABOR PURCHASED THROUGH R&D AUTOMOTIVE. NO WARRANTY ON USED PARTS OR CUSTOMER SUPPLIED PARTS.				

Signature:

Date:

THANK YOU

Int Order#: 23042

Thank You for Your Business!