

How to use the Microphone settings patch

If your car loses the Microphone and the Speakers settings each time you enter the vehicle, please use the following config file and follow the instructions below.

Before you start the procedure please ensure that the Gateway 500 MOST is already updated to firmware version 2.19.

Copy the **GW_CFG.BIN** config file from the '**Enable**' folder to the root of the USB stick then connect it to the USB port of the Gateway and wait approx. **20-30 seconds** and test the system.