

# AUTOSCOPE

FOREIGN CAR CARE

601 COIT RD.  
 PLANO, TEXAS 75075  
 972 867-7467

Customer : <b>ZEMMEL, BOB</b>	VEHICLE : <b>2009 PORS 911 CARRERA</b>	Inv. # : <b>0061858</b>
Address :	LICENSE : <b>JKX6238</b>	Date : <b>9/20/18</b>
City : <b>PLANO, TX 75074-</b>	V.I.N. : <b>WP0AA29959S706753</b>	Page : <b>Page 1 of 2</b>
Phone 1 : ( <b>860</b> ) <b>938-2300</b>	Ext : <b>buyer</b>	ENGINE : <b>3.6 H6</b>
Phone 2 : ( <b>860</b> ) <b>399-4166</b>	Ext : <b>office</b>	MILEAGE : <b>62022</b>
		TRANS : <b>AUTO</b>
		PO # :

Tech	Labor Description	Qty	Parts Number	Parts Description	Labor	Parts	Subtotal
------	-------------------	-----	--------------	-------------------	-------	-------	----------

	<b>BRYAN #PERFORM PRE-BUY INSPECTION</b>				400.00		400.00
	<b>BRYAI OWNER OF VEHICLE REQUEST OIL AND FILTER SERVICE NEEDED AT THIS TIME.</b>				Declined		
		1.00		OIL FILTER		Declined	
	Location:			H3E			
		8.00		LEICHTLAUF HIGH TECH 5W-40		Declined	
	<b>BRYAN By Mileage This Is What The Vehicle Is Due For. 60,000 Mile Service.</b>				1035.09	343.54	1378.63
	Replace Engine Air Filter						
	Replace Cabin Air Filter Replace Engine Drive Belt						
	Replace Spark Plugs Perform Brake System Fluid Flush						
		2.00		Air Filter			
		1.00		Cabin Air Filter			
		1.00		Multi Rib Belt			
		6.00		Spark Plug			
		1.00		BRAKE FLUID			
	Location:			WALL			
	<b>BRYAN When Pulling Vehicle In To Shop, Noticed A Vibration From Engine While Idling In Gear. Engine Mounts Are Collapsed. Recommend Replacing Engine And Transmission Mounts.</b>				610.71	565.25	1175.96
		2.00		Engine Mount			
		1.00		Transmission Mount			
	<b>BRYAN Radiator Cooling Ducts Have A Large Amount Of Debris. Recommend Cleaning Radiator Cooling Ducts.</b>				297.38		297.38
	<b>BRYAN Left Rear Tire Has Approximately 2/32 Tread Depth Remaining, Right Rear Tire Has Approximately 3/32 Tread Depth Remaining. Wering Inside Edge Of Rear Tires Excessively.</b>				0.00		
	<b>BRYAN Front Brake Pads Approximately 5MM Remaining, Approximately 1.5MM Lip On Front Rotors.</b>				0.00		
	<b>BRYAN Rear Brake Pads Approximately 5MM Remaining. Approximately 1MM Lip On Rear Rotors.</b>				0.00		
	<b>BRYAN Left Front Wheel Bent Badly, Right Front Wheel Bent Slightly.</b>				0.00		
	<b>BRYAI Left Rear Wheel Has A Large Amount Of Curb Rash.</b>				0.00		
	<b>BRYAN Steering Wheel Is Off To The Left. Recommend Performing Alignment.</b>				0.00		



# AUTOSCOPE

FOREIGN CAR CARE

601 COIT RD.  
 PLANO, TEXAS 75075  
 972 867-7467

Customer : **ZEMMEL, BOB**  
 Address :  
 City : **PLANO, TX 75074-**  
 Phone 1 : ( 860 ) 938-2300  
 Phone 2 : ( 860 ) 399-4166

Ext : **buyer**  
 Ext : **office**

VEHICLE : **2009 PORS 911 CARRERA**  
 LICENSE : **JKX6238**  
 V.I.N. : **WP0AA29959S706753**  
 ENGINE : **3.6 H6**  
 MILEAGE : **62022**

Inv. # : **0061858**  
 Date : **9/20/18**  
 Page : **Page 2 of 2**  
 TRANS : **AUTO**  
 PO # :

Tech	Labor Description						
	Qty	Parts Number	Parts Description	Labor	Parts	Subtotal	

--	--	--	--	--	--	--	--

OK	Bad	Recommendation	OK	Bad	Recommendation

## NOTES

Visit us online at [autoscope.co](http://autoscope.co) & follow us on



### Notice Pursuant to SEC 700.01, Texas Property code:

I am the person or agent acting on behalf of the person who is obligated to pay for the repair of the motor vehicle subject to the repair contract. I understand that this vehicle is subject to repossession in accordance with SEC9503 Texas Business and Commerce Code, if a written order for payment for repair on the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer or maker of the order has no account or the account on which it is drawn has been closed they will be held liable.

Signature X \_\_\_\_\_ Date \_\_\_\_\_

### DISCLAIMER OF WARRANTIES

Unless specified by AutoScope all work performed carries a 12 month or 12,000 Mile Warranty. There is No warranty on owner supplied parts. The seller hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes or authorizes any other person to assume to forfeit any liability in connection with the sale of said products. Warranty is void on parts if vehicle has been modified outside of factory specification or used for non-street applications.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant AutoScope and/or its employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto; once work has been completed I understand that after three days there will be a \$25.00 per day storage fee.

Signature X \_\_\_\_\_ Date \_\_\_\_\_

Labor :	\$2,343.18
Parts :	\$908.79
Sublet :	\$0.00
Other Fees :	\$0.00
Environment :	\$0.00
Subtotal :	\$3,251.97
Sales Tax :	\$74.98
By :	Total : \$3,326.95
	Paid : \$0.00
Total Due :	\$3,326.95

