

CUSTOMER STATES- WARNING ON FOR REDUCE POWER  
 EMISSION PARTS WARRANTY  
 FOUND HIGH PRESSURE FUEL PUMP TO BE LEAKING OIL AND HAVE  
 FAULTS FOR TOO LOW PRESSURE ON STARTUP. STARTS AND RUNS  
 POORLY. REMOVED AND REPLACED HP FUEL PUMP. FILLED AND BLED  
 COOLING SYSTEM AND TOOK VAL. TEST DROVE AND OK AT THIS TIME.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	1	9A1-110-315-FX	HIGH-PRESSURE PU		WARRANTY
	2	999-707-517-41	O-RING		WARRANTY
	1	900-123-007-30	ALUM SEAL RING		WARRANTY
				TOTAL - PARTS	0.00

JOB# 1 TOTALS-----  
 JOB# 1 JOURNAL PREFIX POCS JOB# 1 TOTAL 0.00

COMMENTS-----  
 TOW IN NIGHT DROP  
 DELETED OPERATION(S)-----  
 11POZ05 FLUID LEAK-ENGINE

TOTALS-----

THANK YOU FOR YOUR BUSINESS!!	TOTAL LABOR....	0.00
*****	TOTAL PARTS....	0.00
* [ ] CASH [ ] CHECK CK NO. [ ] *	TOTAL SUBLET...	0.00
* [ ] VISA [ ] MASTERCARD [ ] DISCOVER *	TOTAL G.O.G....	0.00
* [ ] AMER XPRESS [ ] OTHER [ ] CHARGE *	TOTAL MISC CHG.	0.00
*****	TOTAL MISC DISC	0.00
	TOTAL TAX.....	0.00

**TOTAL INVOICE \$ 0.00**

"This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal."[s.559.904(4)]  
 "The State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state[s.403.718],and a \$1.50 fee to be collected for each new or remanufactured battery sold in the state [s.403.7185]".

CUSTOMER SIGNATURE \_\_\_\_\_

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

[www.sunsetautogroup.com](http://www.sunsetautogroup.com)

I ACKNOWLEDGE AND APPROVE OF ALL WORK PERFORMED, INCLUDING ANY ADDITIONAL WORK THAT MAY HAVE BEEN ADDED ON THE ORIGINAL WORK ORDER. I ACKNOWLEDGE RECEIPT OF A COPY OF THIS INVOICE AND I HAVE REVIEWED THE TERMS AND CONDITIONS LISTED ON THE REVERSE SIDE OF THIS PAGE.

CUSTOMER SIGNATURE X \_\_\_\_\_

THANK YOU!

The Reynolds and Reynolds Company ERAINTNVE CC732241 Q (06/16)