



Black Canyon Performance

5785 W. 56th Avenue
 Arvada, CO 80002
 (303) 423-0588
 Info@blackcanyonperformance.com
 https://www.blackcanyonperformance.com

Invoice for RO #3979

Service Advisor: Chris McNeal
 Posted Date: 03/31/21 at 04:57 PM MDT
 Client: Alex McCulloch
 Vehicle: 2010 Porsche 911 Carrera

Alex McCulloch adm@glenshelly.com Phone: (303) 808-6303	2010 Porsche 911 Carrera 3.6L 6Cyl GAS A102 Naturally Aspirated VIN: WP0AA2A9XAS706523 License: N/A Color: N/A Odometer In: 91966 / Out: 91966	RO #3979 Time-In: 03/25/21 at 02:09 PM MDT Save Parts: No
---	--	---

Client concerns:

- Pre Purchase Inspection

1 - Pre Purchase Inspection Note: Over Rev Counter Notes Range 1 4896 Range 2 239 Range 3 46 Range 4 183 Range 5 295 Range 6 0		TECH: J Paul
<i>Labor:</i> Inspection	\$150.00	
✓ Authorized on 03/25/21 at 02:10 PM MDT		\$150.00

2 - Lower Control Arm Note: Play can be felt from the lower ball joint within the lower control arms. The drivers side is a lot worse than the passenger side.		TECH: J Paul
<i>Labor:</i> Lower Control Arm: 911; Both Sides	\$375.00	
<i>Part:</i> Porsche Control Arm	2	\$977.80
✓ Authorized on 03/31/21 at 12:38 PM MDT		\$1,396.80 <i>Subtotal \$1,352.80 + est. Tax \$44.00</i>

3 - Four wheel Alignment		TECH: J Paul
<i>Labor:</i> Full suspension adjustment	\$137.50	
✓ Authorized on 03/31/21 at 12:38 PM MDT		\$137.50

Total Repair Order & Signature:

Total Jobs:	\$1,640.30
Total Fees:	\$23.19
Subtotal:	\$1,663.49
Taxes:	\$44.00
Grand Total:	\$1,707.49
BALANCE DUE:	\$0.00

Authorized by _____

Completed Transactions						
03/31/21	MCCULLOCH/ALEXANDER D	\$1,707.49	Credit Card Payment	Visa**** 9273 Auth: 55840D	Chip Visa AID:A0000000031010 ARC:Z3	