

UIN 086A39E
New Oil
Unit No. Mobil FSX2 5W50

Unit:
Make
Model
Serial No.
Site
Compartment:
Name Mobil FSX2 5W50
Make
Model
Serial No.
Capacity: qt






Customer:

MICHAEL HARMAN
1007 Turner Trce E
Mount Juliet TN 37122
USA

DIAGNOSIS

New oil. Diagnosis not applicable.

ANALYST: Jon.Sowers

LEGEND				
				
Normal	Severe	Abnormal	Caution	Normal

DATE SAMPLED	10-Jan-21
DATE RECEIVED	15-Jan-21
DATE REPORTED	18-Jan-21
LAB NO.	42021578999
SIF NO.	25924874
TIME ON UNIT	Hrs
TIME ON OIL	Hrs
OIL BRAND	Mobil
OIL TYPE	Mobil 1
OIL GRADE	SAE 5W50
OIL ADDED	
FILTER	
OIL CHANGED	
WO NUMBER	
Metals (ppm)	
Iron (Fe)	2
Chromium (Cr)	<1
Lead (Pb)	<1
Copper (Cu)	<1
Tin (Sn)	<1
Aluminium (Al)	6
Nickel (Ni)	<1
Silver (Ag)	<1
Titanium (Ti)	<1
Vanadium (V)	<1
Contaminants (ppm)	
Silicon (Si)	2
Sodium (Na)	6
Potassium (K)	3
Additives (ppm)	
Magnesium (Mg)	26
Calcium (Ca)	3629
Barium (Ba)	<1
Phosphorus (P)	1000
Zinc (Zn)	1126
Molybdenum (Mo)	84
Boron (B)	382
Contaminants	
Water (%)	<0.05
Physical Tests	
Viscosity (cSt 100C)	16.7
Viscosity (cSt 40C)	104.9
Physical / Chemical	
Base Number (mgKOH/g)	11.3



UIN 086A39E

U.S. Laboratories

Atlanta, Georgia - 420

5300 OakBrook Parkway
Building 200 Suite 245
Norcross, GA 30093
800.394.3669

Valley View, Ohio - 410

6180 Halle Dr. Suite D
Valley View, OH 44125
800.726.5400

Kansas City, Kansas - 430

935 Sunshine Road
Kansas City, KS 66115
800.332.8055

Phoenix, Arizona - 440

3319 West Earll Drive
Phoenix, AZ 85017
800.445.7930

Portland, Oregon - 401

4943 NW Front Avenue
Portland, OR 97210
800.770.4128

Canadian Laboratories

Burlington, Ontario - 450

5036 South Service Rd.
Burlington, ON L7L5Y7
905 332 9559

Edmonton, Alberta - 402

9450 17 Ave NW
Edmonton, AB T6N 1M9
888.489.0057

Sales & Marketing

Houston, Texas

10450 Stancliff Road, Suite 210
Houston, TX 77099
877.835.8437

International Locations

Australia

Brisbane, Perth, Sydney,
Muswellbrook

Europe

Prague

New Zealand






Wellington

South America

Santiago de Chile,
Belo Horizonte, Brazil

Southeast Asia

Kuala Lumpur, Singapore



Filter Image

Filter patch test is not performed Contact laboratory for more information

Since services are based on samples and information supplied by others, and since corrective actions, if any, are necessarily taken by others, these services are rendered without any warranty or liability of any kind beyond the actual amount paid to ALS Tribology for the services. Reported recommendations are based on interpretations of the generated test results and historical data. Certain test results appearing in this report may have been tested at other ALS laboratories within the Tribology divisional network.

Michael Harman
Attn: Mike Harman
1007 Turner Trce E
Mount Juliet TN 37122
USA