

UNIT# 29P129

PORSCHE
INVOICE

Michael Stead Porsche
2555 North Main Street
Walnut Creek, CA 94597

(925) 280-4900
Fax: (925) 280-4912
www.steadporsche.com

3

CA 94523-1728

PAGE 1

HOME: 925-
BUS:

CONT: N/A
CELL: 415

SERVICE ADVISOR: 777 MELISSA JONES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
E7E7-AN	09	PORSCHE C4S COUPE	S721157		1795/1799	T852	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
26APR09 DD		26APR2013	17:00 19AUG09			CASH	21AUG09
R.O. OPENED	READY	OPTIONS: STK:29P129 DLR:146					
08:18 19AUG09	08:36 21AUG09						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PERFORM CAMPAIGN W913 - EXHAUST CLAMPS
CAUSE: WORKSHOP CAMPAIGN

W913 PERFORM CAMPAIGN W913 - EXHAUST CLAMPS
770 WP95

(N/C)

1 000-043-300-71 CLAMP KIT. MUFFLER.

(N/C)

FC: W913 PART#: COUNT:

CLAIM TYPE: R

AUTH CODE:

...,1797 completed w913

B customer states pdk shifts to early and late update?

CAUSE: 011

00 TRANSMISSION CONTROL MODULE PROGRAMED

770 WP95

(N/C)

03350000 ON BOARD DIAGNOSTIC SEE SRT GUIDE FOR DE

770 WP95

(N/C)

37309590 TRANSMISSION CONTROL MODULE TROUBLESHOOT

770 WP95

(N/C)

FC: 3730 PART#: COUNT:

CLAIM TYPE: 2

AUTH CODE:

...,1799 reprogramed pdk , faults and errors after program. p1749 p1872

...,p1991 would not clear.As per craig irish need to power down and restart

...,program,also may require ather module reprogram the calibrate.

C CUSTOMER STATES DO NOT WASH

00 * GENERAL SERVICING

1 CP

0.00

0.00

BAR# AK196618 EPA# 000102813