

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
ARCTIC SIL	09	PORSCHE 911	WP0CB29949S755464		13115/13118	T6744
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
27SEP09 DD			17:00 03SEP10		CASH	20SEP10
R.O. OPENED	READY	OPTIONS: STK:P1874 ENG:3.8_Liter TRN:250				
01SEP10	20SEP10					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A THEFT RECOVERY WITH ELECTRICAL DAMAGE. PLEASE INSPECT ELECTRICAL SYSTEM & ADVISE.

ELEC ELECTRICAL - DIAGNOSIS/REPAIR

904 CP 7.00

1	997-610-341-00	PAN. FUSE CARRIER 1	13.08	13.08	13.08	13.08
1	997-610-340-00	FUSE CARRIER 1 FRAME	18.69	18.69	18.69	18.69
1	997-551-101-00-A10	COVERING. INT TRIM.	116.67	116.67	116.67	116.67
1	997-551-621-00-01C	LID	12.30	12.30	12.30	12.30
1	997-613-105-02-A05	TIP SWITCH MODULE	79.32	79.32	79.32	79.32
1	997-551-019-04-A03	DOOR SILL COVERING	191.44	191.44	191.44	191.44

PARTS: 431.50 LABOR: 910.00 OTHER: 0.00 TOTAL LINE A: 1341.50

13118 7.00 7.0HRS-904 REPAIR DAMAGED WIRES UNDER FUSE BOX REPLACE BROKEN FUSE BOX AND FUSE HOLDER. UNABLE TO FIND SWITCH CONNECTOR FOR HOODS. SCANNED ALL CONTROL UNITS AND CLEARED ALL FAULTS.

B THEFT RECOVERY WITH ENGINE & EXHAUST DAMAGE. PLEASE INSPECT & ADVISE.

ENG ENGINE MINOR REPAIR

904 CP 8.00

1	997-113-109-33	EXHAUST MANIFOLD	1336.40	1336.40	1336.40	1336.40
1	997-113-110-33	EXHAUST MANIFOLD	1336.40	1336.40	1336.40	1336.40
1	997-111-128-32	HOLDER	177.21	177.21	177.21	177.21
2	900-385-098-01	TORX SCREW 8X25	0.82	0.82	1.64	1.64
2	997-111-107-30	SEALING. EXHAUST MAN	15.89	15.89	31.78	31.78
2	997-111-113-30	SEALING. EXHAUST MAN	7.94	7.94	15.88	15.88
1	997-111-159-32	FRONT MUFFLER	870.14	870.14	870.14	870.14
1	9A1-110-090-02	VACUUM PUMP	194.28	194.28	194.28	194.28
1	999-701-504-40	O-RING	3.90	3.90	3.90	3.90
1	999-701-505-40	O-RING	6.86	6.86	6.86	6.86
2	999-073-471-01	TORX SCREW 8X21	0.82	0.82	1.64	1.64

MISC VOR FREIGHT CHARGE FOR VACUUM PUMP FROM GERMANY

PO#673543

CP

15.68 15.68

PARTS: 3976.13 LABOR: 1040.00 OTHER: 15.68 TOTAL LINE B: 5031.81

13118 8.00 8.0HRS-904 REPLACE DAMAGED CAT PIPE -CENTER MUFFLER-MOUNTING

Thank You!

NOTICE TO CONSUMER:

I acknowledge notice and oral approval of any additional customer or warranty work performed and/or increase in the original estimate price. I also acknowledge and approve all repairs as itemized and/or receipt of vehicle. I also acknowledge receipt of additional consumer warranty and service information contained in the Parts and Service Warranty Disclaimer.

ORIGINAL ESTIMATE \$ _____
CUSTOMER SIGNATURE _____

AUTHORIZED REVISED ESTIMATE \$ _____

X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES/ADJ.	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

BAR REG ARD233548 EPA# CAD 983641291
REG ARD233549

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
ARCTIC SIL	09	PORSCHE 911	WPOCB29949S755464		13115/13118	T6744
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
27SEP09 DD			17:00 03SEP10		CASH	20SEP10
R.O. OPENED	READY	OPTIONS: STK:P1874 ENG:3.8_Liter TRN:250				
01SEP10	20SEP10					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

BRACKET FOR DRIVER'S SIDE MUFFLER. REPLACED DAMAGED VACUUM PUMP.

C THEFT RECOVERY WITH BROKEN HEIGHT SENSOR, BENT OIL PAN, WATER & A/C PIPES.

SUSP SUSPENSION - STEERING

904 CP	7.20						
1 996-573-091-01 A\C INTAKE PIPE		146.78		936.00		936.00	
1 999-707-558-41 O-RING		4.09		4.09		4.09	
1 999-707-534-41 O-RING		4.09		4.09		4.09	
2 R134A 1LB		19.95		19.95		39.90	
10 Q-1-09-0151 MOBIL 1 FORM		7.95		7.95		79.50	
1 9A1-107-032-10 AS OIL PAN		406.92		406.92		406.92	
1 9A1-107-325-02 SEALING		13.88		13.88		13.88	
1 996-341-371-03 SENSOR LINK SUPPORT		3.71		3.71		3.71	
1 997-631-121-00 ANGLE ROTAT. SENSOR		79.91		79.91		79.91	
1 997-341-375-01 ARTICULATED ROD		23.12		23.12		23.12	
1 9A1-106-125-01 WATER PIPE		57.30		57.30		57.30	
2 000-043-301-05 ANTIFREEZE (3.79 L)		35.46		35.46		70.92	

PARTS: 930.12 LABOR: 936.00 OTHER: 0.00 TOTAL LINE C: 1866.12

13118 7.20 7.20HRS-904 REPLACE FRONT HEIGHT SENSOR AND MOUNTING BRACKET. REPLACED BENT OIL PAN AND CHANGED OIL. REPLACED BENT LOWER WATER PIPE. BLEED COOLING SYSTEM. REPLACED DAMAGED LOWER LOW PRESSURE A/C HOSE. EVACUATED AND CHARGE A/C SYSTEM.

EST: 5,000.00 01SEP10 15:32 SA: 393

TEST DROVE VEHICLE TO DETERMIN ENGINE & TRANSMISSION CONDITION. ENGINE SEEMS TO BE FINE & TRANSMISSION SHIFTING THRU ALL 6 SPEEDS. COULD FIND NO FAULT WITH ENGINE & TRANSMISSION AT THIS TIME.

Thank You!

<p>NOTICE TO CONSUMER: I acknowledge notice and oral approval of any additional customer or warranty work performed and/or increase in the original estimate price. I also acknowledge and approve all repairs as itemized and/or receipt of vehicle. I also acknowledge receipt of additional consumer warranty and service information contained in the Parts and Service Warranty Disclaimer.</p> <p>ORIGINAL ESTIMATE \$ _____ CUSTOMER SIGNATURE _____</p> <p>AUTHORIZED REVISED ESTIMATE \$ _____</p> <p>X</p>	DESCRIPTION	TOTALS
	LABOR AMOUNT	2886.00
	PARTS AMOUNT	5337.75
	GAS, OIL, LUBE	0.00
	SUBLET AMOUNT	0.00
	MISC. CHARGES/ADJ.	15.68
	TOTAL CHARGES	8239.43
	LESS INSURANCE	0.00
	SALES TAX	467.05
	PLEASE PAY THIS AMOUNT	8706.48

BAR REG ARD233548 EPA# CAD 983641291
REG ARD233549