

Description	Qty
<p>Inspections found power steering hydraulic reservoir below minimum level clutch slave system not operational unless pushing clutch pedal very slowly, also will not hold assist after vehicle is shut off.</p> <p>tech found two problems, one way valve in power steering reservoir failed, accumulator not holding pressure</p>	3.5
power steering reservoir	1
hydraulic system accumulator	1
Subtotal	