2006 Porsche Cayenne

2003-08 RESTRAINTS Airbag - 9pa_Cayenne

Work instructions		OK	If not OK
Check passenger 1 side airbag by simulation	 Before working on this fault code, read through and follow the section below: 69 63 19 REMOVING AND INSTALLING SIDE AIRBAG - AS OF MY 2003 (ALL MODELS), and 69 AW SAFETY REGULATIONS FOR HANDLING AIRBAGS AND AS OF MY 2003 (ALL MODELS) for handling airbag and belt tensioner - vehicles Switch ignition off and remove ignition key (if KESSY system is installed, pull off operating lever) Disconnect negative terminal of vehicle battery and cover battery terminal with insulating material for safety. Always wait at least 1 minute before doing any more work on the system 	Go to Step	2
2 Check passenger side airbag	 Commercially available tool: Use Additional airbag tester, Porsche set No. 169 and connect test box 5056/C with test cable 5056/3 in place of the passenger side airbag Re-connect vehicle battery properly Switch on ignition Read out fault memory Erase fault memory Switch off ignition Remove ignition key (if KESSY system is installed, pull off operating lever) Switch on ignition Read out fault memory 	Fault code is no longer detected Go to Step 4	Go to Step 3
3 Check wiring harness for pinching or chafing damage		No damage visible Go to Step 6	Replace wiring harness > End
Carry out visual inspection on 2-pin 4 plug connection for passenger side air-	 Switch off ignition Check that the 2-pin plug connection for the passenger side airbag is connected and locked 	Go to Step	Connect and lock plug connection properly