

## Fault code 0955

### Key 1

#### Diagnostic conditions

- Internal KESY control module function test

#### Possible cause of fault

- ◆ Battery in key 1 discharged

#### Affected pins

-

### Diagnosis/troubleshooting

Work instruction		Display OK	If not OK
1	Replace battery in key 1	→ End	

