

November 18, 2016 MANUFACTURER COMMUNICATION NUMBER: 122-E3D6M-12



## Components: ELECTRICAL SYSTEM

**NHTSA ID Number:** 10120623

**Manufacturer Communication Number:** 122-E3D6M-12

### Summary

Due to incorrect sealing of the electric plug connection on the transfer case servo motor, moisture can get into the connector. As a result, the contacts can become corroded. In the event of a customer complaint, check the plug connection on the servo motor and the servo motor

itself for damage:

? If the electric plug connection on the transfer case servo motor is corroded, replace section of cable

including electric plug connection using a repair kit.

? If the servo motor is damaged, replace section of cable including electric plug connection and

transfer case servo motor.

### 7 Affected Products ▾

**Request Research** (Services fees apply)