

# MANTIS AUTOSPORT INC

1029 SPEERS RD, UNIT 5

OAKVILLE, ON

L6L 2X5

Tel.#: (905) 844-6219

CUSTOMER	VEHICLE	WORK ORDER ADMIN.
<b>PORSCHE CENTER OAKVILLE</b>	<b>2008 PORSCHE CAYMAN S</b>	<b>WO # : 63405</b>
<b>891 PROGRESS AVE</b>	<b>Plate : N/A</b>	<b>Date : 11/14/2023</b>
<b>OAKVILLE, ON L6L 6K1</b>	<b>ODO : 53,856</b>	<b>Time :</b>
	<b>V.I.N.: WP0AB29878U780473</b>	<b>PO # :</b>
	<b>Unit #:</b>	<b>REG # : 79937 5142</b>
<b>B#: H#:</b>	<b>Engine: 3.4 L F6</b>	<b>Tech. : LUKE/LUKE</b>

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		>BASIC PRE PURCHASE INSPECTION			405.00	HST	405.00	
		BASIC PRE PURCHASE INSPECTION				HST		
		-----				HST		
		-CHECK ON OVERALL VEHICLE				HST		
		CONDITION				HST		
		-CHECK AND REPORT ON REQUIRED				HST		
		SAFETY ITEMS				HST		
		-CHECK AND REPORT ON REQUIRED				HST		
		MAINTANENCE ITEMS				HST		
		**PPI RESULTS**				HST		
		-IMS/RMS LEAKING, EVIDENCE ON				HST		
		BELLHOUSING				HST		
		-HAS AFTERMARKET IPD INTAKE				HST		
		PLENUM INSTALLED				HST		
		-BATTERY FAILED LOAD TEST				HST		
		8.8V@760CCA				HST		
		-HAS H&R SPORT LOWERING				HST		
		SPRINGS INSTALLED				HST		
		-ENGINE HAS BLUE PAINT ON				HST		
		ENGINE BLOCK, NOT SURE IF				HST		
		ENGINE HAS BEEN REPLACED OR				HST		
		REBUILT				HST		
		-SERIAL NUMBER ON ENGINE				HST		
		M97/2167801387				HST		
		-PASSENGER SIDE DOOR				HST		
		ALIGNMENT IS OFF				HST		
		-FRONT BUMPER NOT STRAIGHT,				HST		
		POOR INSTALLATION				HST		
		-EVIDENCE THE WHOLE VEHICLE				HST		

I hereby authorize the above work to be done and the above materials to be supplied/installed on the following conditions. I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of work done and materials supplied whether the vehicle is in Mantis Autosport possession or not, the right to take possession of vehicle, hold or sell it in order to recover the unpaid cost. I authorize Mantis Autosport, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize Mantis Automotive to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I agree that Mantis Autosport will not be responsible for loss, damage or theft of my vehicle or its contents, however caused, while being stored for the purposes of repair. \*All parts are new unless otherwise etated. \*All Parts & Labour warranties are void when parts are supplied by Customer.

Signature \_\_\_\_\_

<b>Sub Tot.</b>	<b>0.00</b>	<b>929.25</b>	<b>929.25</b>
		<b>HST</b>	<b>120.80</b>
		<b>Deductible</b>	<b>0.00</b>
		<b>Total</b>	<b>1,050.05</b>
<b>Page</b>		<b>Amt. Paid</b>	<b>0.00</b>
<b>1 of 3</b>		<b>Amt. Owing</b>	<b>1,050.05</b>

CUSTOMER		VEHICLE	WORK ORDER ADMIN.	
PORSCHE CENTER OAKVILLE		2008 PORSCHE CAYMAN S	WO #	: 63405
891 PROGRESS AVE		Plate : N/A	Date	: 11/14/2023
OAKVILLE, ON L6L 6K1		ODO : 53,856	Time	:
		V.I.N.: WP0AB29878U780473	PO #	:
		Unit #:	REG #	: 79937 5142
B#:	H#:	Engine: 3.4 L F6	Tech.	: LUKE/LUKE

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		HAS BEEN REPAINTED, PAINT THICKNESS NOT EVEN OVER VEHICLE				HST		
		-SCRATCHES ON RIGHT FRONT FENDER				HST		
		-REAR SPOILER HAS BEEN DEACTIVATED SO IT DOES NOT IMPACT BODYKIT SPOILER				HST		
		-LF GRILLE HAS EXPOSED WIRES, LIGHTING WIRING HARNESS NOT ROUTED PROPERLY				HST		
		-AIR BAG WARNING ON. DIAG TIME REQUIRED TO DETERMINE CAUSE				HST		
		-SLIGHT ENGINE RATTLE HEARD DURING TEST DRIVE. DIAG TIME REQUIRED TO DETERMINE CAUSE				HST		
		-INTERMITTENT CLUNKING IN REAR OF VEHICLE. DIAG TIME REQUIRED TO DETERMINE CAUSE				HST		
		-RATS NEST ON TOP OF THE ENGINE UNDER THE ENGINE COVER				HST		
		-THERE MIGHT BE RODENT DAMAGE, WOULD REQUIRE DIAG TIME TO DETERMINE IF THERE IS				HST		
		-TIRES				HST		
		235/40R18 MICHELIN PILOT SPORT 2 N4 - 7MM OF TREAD LIFE				HST		
		-6U8901DX0823				HST		
		265/40R18 MICHELIN PILOT SPORT 2 N4 - 8MM OF TREAD LIFE				HST		
		-6UDRWLJX4221				HST		
		-TPMS HAS 60 MONTHS OF LIFE LEFT				HST		

I hereby authorize the above work to be done and the above materials to be supplied/installed on the following conditions. I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of work done and materials supplied whether the vehicle is in Mantis Autosport possession or not, the right to take possession of vehicle, hold or sell it in order to recover the unpaid cost. I authorize Mantis Autosport, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize Mantis Automotive to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I agree that Mantis Autosport will not be responsible for loss, damage or theft of my vehicle or its contents, however caused, while being stored for the purposes of repair. \*All parts are new unless otherwise stated. \*All Parts & Labour warranties are void when parts are supplied by Customer.

Signature \_\_\_\_\_

<b>Sub Tot.</b>	0.00	929.25	929.25
		<b>HST</b>	120.80
		<b>Deductible</b>	0.00
		<b>Total</b>	1,050.05
<b>Page</b>		<b>Amt. Paid</b>	0.00
2 of 3		<b>Amt. Owing</b>	1,050.05

CUSTOMER		VEHICLE	WORK ORDER ADMIN.	
PORSCHE CENTER OAKVILLE		2008 PORSCHE CAYMAN S	WO #	: 63405
891 PROGRESS AVE		Plate : N/A	Date	: 11/14/2023
OAKVILLE, ON L6L 6K1		ODO : 53,856	Time	:
		V.I.N.: WP0AB29878U780473	PO #	:
		Unit #:	REG #	: 79937 5142
B#:	H#:	Engine: 3.4 L F6	Tech.	: LUKE/LUKE

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Tx	Total	C
		**BOREScope, COMPRESSION AND LEAKDOWN RESULTS**				HST		
		COMPRESSION AND LEAKDOWN				HST		
		-----				HST		
		CYLINDER 1 - 240PSI 9%				HST		
		LEAKDOWN - SOME SCORING VISIBLE				HST		
		CYLINDER 2 - 235PSI 8%				HST		
		LEAKDOWN - SOME SCORING VISIBLE				HST		
		CYLINDER 3 - 240PSI 6%				HST		
		LEAKDOWN				HST		
		CYLINDER 4 - 240PSI 6%				HST		
		LEAKDOWN				HST		
		CYLINDER 5 - 235PSI 6%				HST		
		LEAKDOWN				HST		
		CYLINDER 6 - 235PSI 6%				HST		
		LEAKDOWN				HST		
3.00		BOREScope, COMPRESSION AND LEAKDOWN TEST			480.00	HST	480.00	
		Shop And Environmental Fee			44.25	HST	44.25	

WO# 63405

Copyright 2023 Autogence Inc. - LANKAR 11.17.

## Technician must be clocked onto correct job

All wheels that have been removed during repair have been torqued to \_\_\_\_\_

## PAID BY:...

I hereby authorize the above work to be done and the above materials to be supplied/installed on the following conditions. I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of work done and materials supplied whether the vehicle is in Mantis Autosport possession or not, the right to take possession of vehicle, hold or sell it in order to recover the unpaid cost. I authorize Mantis Autosport, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize Mantis Automotive to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I agree that Mantis Autosport will not be responsible for loss, damage or theft of my vehicle or its contents, however caused, while being stored for the purposes of repair. \*All parts are new unless otherwise stated. \*All Parts & Labour warranties are void when parts are supplied by Customer.

Signature \_\_\_\_\_

Sub Tot.	0.00	929.25	929.25
		HST	120.80
		Deductible	0.00
		Total	1,050.05
Page		Amt. Paid	0.00
3 of 3		Amt. Owing	1,050.05