

**VAL information** » Summary**Vehicle status** ^**Fault memory entries**

37 Fault memory entries

**Vehicle information** ^

<b>VIN</b>	WP0CC2A81GS152694	<b>Model type</b>	Boxster/Cayman
<b>Mileage</b>	13026 km	<b>Order type</b>	981510
<b>Transmission type</b>	G8120	<b>Date / time</b>	11.02.2021 16:34:55 GMT+1
<b>Engine number</b>	DBXB	<b>Operating time</b>	400 h
<b>Country code</b>	C02	<b>UI_VOLTAGE (Keine Übersetzung verfügbar)</b>	14.8 V

**VAL information** » PIWIS Tester information**PIWIS Tester information details** v**VAL information** » Fault codes

✓	Airbag (variant: A2... fault code: C12018 ; 00702C	Software: ... Hardware:... 2
✓	Seat occupancy d... fault code:	Software: ... Hardware:...

<b>LV041_Diagnostics, O2S interchanged behind cat. conv.</b>	Diagnostics not completed
<b>LV030_Diagnostics, oxygen-sensor heater behind cat. conv., bank 1/2</b>	Diagnostics ended without faults
<b>LV050_Diagnostics, tank vent valve</b>	Diagnostics ended without faults
<b>LV081_Diagnostics, bank 1 secondary air</b>	Diagnostics not supported
<b>LV082_Diagnostics, bank 2 secondary air</b>	Diagnostics not supported
<b>LV090_Intake camshaft diagnostics</b>	Diagnostics not completed
<b>LV061_Diagnostics, idle speed fuel supply</b>	Diagnostics not completed
<b>LV060_Diagnostics, partial-load fuel supply</b>	Diagnostics not completed
<b>LV104_Diagnostics, overall system valve lift</b>	Diagnostics not completed
<b>Z211_Overspeed range 1: Number of ignitions</b>	0
<b>Z211_Overspeed range 1: Operating hours</b>	0.00 h
<b>Z212_Overspeed range 2: Number of ignitions</b>	0
<b>Z212_Overspeed range 2: Operating hours</b>	0.00 h
<b>Z213_Overspeed range 3: Number of ignitions</b>	0
<b>Z213_Overspeed range 3: Operating hours</b>	0.00 h
<b>Z214_Overspeed range 4: Number of ignitions</b>	0
<b>Z214_Overspeed range 4: Operating hours</b>	0.00 h
<b>Z215_Overspeed range 5: Number of ignitions</b>	0
<b>Z215_Overspeed range 5: Operating hours</b>	0.00 h
<b>Z216_Overspeed range 6: Number of ignitions</b>	0
<b>Z216_Overspeed range 6: Operating hours</b>	0.00 h
<b>XX_Mileage over service life</b>	12534 km
<b>P030_Boost pressure specified value</b>	978.76 hPa

LV502\_Blockage due to actuated clutch or engaged gear, selector lever not in P No

LV507\_Blockage due to fault memory entry No

LV503\_Blockage due to excessive coolant temperature (T020) No

LV504\_Blockage due to insufficient coolant temperature (T020) No

LV506\_Blockage due to excessive exhaust gas temperature behind catalytic converter (K014/K016) No

LV505\_Blockage due to excessive engine oil temperature (T030) No

LV501\_Blockage due to parking brake open No

LV508\_Blockage due to implausible engine speed No

**Coding**



**Fault codes**



**U0155 - Communication with instrument cluster(no signal)**



**U0164 - Communication with A/C control unit(no signal)**

Instrument cluster ... fault code: C1201E ; C12080 ; ... Software: ... Hardware:... 9

Steering-wheel el... fault code: C12019 Software: ... Hardware:... 1

Stopwatch (A2.1) fault code: C1201F Software: ... Hardware:... 1

PCM fault code: 8008 Software: ... Hardware:... 1

BOSE audio ampl... fault code: Software: ... Hardware:...

Air conditioning (v... fault code: C12000 ; C12007 ; ... Software: ... Hardware:... 5

Button module in ... fault code: Software: ... Hardware:...

▼ **Front door (variant... fault code:** **Software: ... Hardware:...**

▼ **Front door (variant... fault code:** **Software: ... Hardware:...**