



GLOBAL MOTORSPORTS GROUP, LLC 3210 S. SHANNON ST, SANTA ANA, CA 92704
 PHONE +1 714 432 1582 FAX +1 714 432 1590 GMGRACING.COM
 BAR #AC248488 EPA #1482625-01

Repair Order # 14831

Joe Morgan
 160TobyLn
 Anaheim, CA 92807

2018 Porsche 911 Turbo S

VIN: WP0AD2A91JS156376
 Engine: H6 3.8L, 3800cc, DOHC, GAS, FI
 Trans: PDK

License# 8DGP964
 ODO In: 2613
 Color: Silver
 Mfg. Date:

InvDate: 2/04/2019
 Service Writer: Scott Centra
 Status: Work In Progress
 Driver: Morgan, Joe
PO #

(714)928-4373 Mobile
 joe@outsourcucc.com

Unit #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Disc.	Ext
------------------	----------------------	--------------------	-----	-----	-------	-------	-----

Customer requests: Install GMG Turbo S exhaust

Labor Service - Install Exhaust			5.00		175.00		875.00
New	GMGEX9912TTGT2TIPS	GMG 991.2 TT GT2 Slash Cut Quad Tips		1.00	5,395.00	-539.50	4,855.50

Customer requests: Install GMG Turbo Sport headers

Labor Service - Install sport headers			2.00		175.00		350.00
New	GMGHEADER991TT	GMG WC Sport Header Set, 991 Turbo & Turbo S		1.00	3,195.00	-319.50	2,875.50

Customer requests: Install GIAC software upgrade stage 2

Labor Service - Install GIAC software			3.00		175.00		525.00
New	GIAC	Giac software tuning, stage 2		1.00	2,900.00		2,900.00

Customer requests: Install BMC performacne air filter

Labor Service - Replace Air Filter					175.00		0.00
New	FB79820	BMC Air Filter, 991 Turbo		1.00	209.00		209.00

Customer requests: Install customer provided BBS magnesium wheels in satin black.

Labor Service - Mount and Balance four tires. Includes removing and replacing tires from wheels, mount on vehicle, electronically balance wheels and tires.				1.00	240.00		240.00
New	PIRELLI TROFEO 20"	Pirelli Trofeo 305-30-20 and 245-35-20 Set - R Compound set 2 front and 2 rear		1.00	2,324.00		2,324.00
New	9P1601361	TPMS Wheel Valve Stem (Black)		4.00	29.21		116.84
New	7PP907275G	TPMS Sensor		4.00	110.11		440.44
Sublet	SHIPPING	Shipping for tires		1.00	95.00		95.00
New	99736120791	Porsche Turbo S center caps with black logo		4.00	78.75		315.00
Sublet	SHIPPING	Shipping for wheel caps		1.00	35.00		35.00

Customer requests: The vehicle needs an Oil and Filter Service.

Labor Service - Oil and filter service, top off fluids, set tire pressures, reset service reminder.			1.50		175.00		262.50
New	948 107222 00	Oil filter cartridge (OX254D4)		1.00	30.06		30.06
New	MOBIL 1 0W-40	ENGINE OIL - Mobil 1 0W-40 syn oil		8.00	14.99		119.92
New	WURTH DRAIN SEAL	Wurth Drain seal		1.00	1.00		1.00
New	BRAKEKLEEN SP390	Brake clean/parts cleaner - SP390		1.00	8.99		8.99

Customer requests: Install Tech Art lowering springs

Labor Service - Install Lowering Springs and perform 4-wheel alignment.			9.90		175.00		1,732.50
New	091200140009	Tech Art 991.2 Turbo lowering springs		1.00	760.00		760.00

Vehicle Tire Information

Check Performed.

	Left Front	Right Front	Left Rear	Right Rear	CheckedBy
Tire Pressure PSI	33	33	41	41	



GLOBAL MOTORSPORTS GROUP, LLC 3210 S. SHANNON ST, SANTA ANA, CA 92704
 PHONE +1 714 432 1582 FAX +1 714 432 1590 GMGRACING.COM
 BAR #AC248488 EPA #1482625-01

Repair Order # 14831

Joe Morgan

2018 Porsche 911 Turbo S

License# 8DGP964

InvDate: 2/04/2019

Continued from previous page

<p>Warranty All repair work is warranted for 12 months/12,000, whichever comes first, unless otherwise stated on this repair order. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. I have read and understand the above and acknowledge recei</p> <p>I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I _____ agree and assume all risk and liability with the installation of the above describe exhaust system or header and acknowledge that I understand they are intended for motorsport/racing purposes only. X _____ Absolutely no warranties expressed or implied due to the intend use of this product. Exhaust systems and</p> <p>X _____ Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee. X _____ Customer acknowledges receipt of merchandise and services.</p>	<p>Estimate only, do not pay.</p>	<p>Repair Order Summary:</p> <table border="0"> <tr> <td>Parts</td> <td style="text-align: right;">14,956.25</td> </tr> <tr> <td>Labor</td> <td style="text-align: right;">3,985.00</td> </tr> <tr> <td>Sublet</td> <td style="text-align: right;">130.00</td> </tr> <tr> <td colspan="2"> </td> </tr> <tr> <td>Sub Total</td> <td style="text-align: right;">19,071.25</td> </tr> <tr> <td>Sales Tax (CA)</td> <td style="text-align: right;">1,159.11</td> </tr> <tr> <td>Total</td> <td style="text-align: right;">20,230.36</td> </tr> </table>	Parts	14,956.25	Labor	3,985.00	Sublet	130.00			Sub Total	19,071.25	Sales Tax (CA)	1,159.11	Total	20,230.36
Parts	14,956.25															
Labor	3,985.00															
Sublet	130.00															
Sub Total	19,071.25															
Sales Tax (CA)	1,159.11															
Total	20,230.36															
<p>Page 2 of 2</p>	<p>Discard old parts</p>	<p>Original Estimate: 27,459.43</p>														