



SERVICE

Date	Invoice #
2/11/2022	8768

Bill To
Clay Condry

Ship To
Clay Condry

VIN#	Mileage	Terms	Vehicle
WP0AD299X8S783477	47682		2008 997 TURBO SILVER

Description	Qty	Rate	Amount
remove engine and transaxle. completely disassemble intake on top side of engine. replace customer supplied sharkwerks stainless elbows and hose and seal kit . install new water pump and thermostat not supplied from sharkwerks as well as two heater hoses	1	3,600.00	3,600.00
water pump OEM	1	527.53	527.53T
water pump gasket OEM	1	17.75	17.75T
thermostat assembly OEM	1	76.74	76.74T
thermostat gasket OEM	1	7.03	7.03T
heater hose not included in sharkwerks kit	1	46.78	46.78T
return heater hose not included in sharkwerks kit	1	52.11	52.11T
oil filter kit	1	26.75	26.75T
Mobil 1 0-40 Synthetic Motor Oil	11	10.25	112.75T
Porsche Coolant/Antifreeze	2.5	47.57	118.93T
Subtotal			4,586.37
I estimate this job at \$6000 including the 1300 in parts you purchased from SW so it came in slightly under that number maybe 100 less		0.00	0.00
*****		0.00	0.00

Subtotal
Sales Tax
Total
Payments/Credits
Balance Due

Phone #
405-330-9116



SERVICE

Date	Invoice #
2/11/2022	8768

Bill To
Clay Condry

Ship To
Clay Condry

VIN#	Mileage	Terms	Vehicle
WP0AD299X8S783477	47682		2008 997 TURBO SILVER

Description	Qty	Rate	Amount
Everything below this line is in addition to the initial estimate of fixing coolant pipes with sharkwerks kit and adding water pump and thermostat		0.00	0.00
install customer provided hre wheels		0.00	0.00
TPMS SENSOR list \$192.37	4	74.89	299.56T
Subtotal			299.56
labor to remove transaxle from engine to inspect clutch and pressure plate to guarantee that it was indeed 764 race engineering plate	2	90.00	180.00
Subtotal			180.00
labor to remove clutch and pressure plate assembly and replace rear main crankshaft seal	0.5	90.00	45.00
Rear crankshaft seal OEM	1	50.69	50.69T
Subtotal			95.69
labor to replace original ignition coils and spark plugs with engine removed this saves over 6 hours	2.5	90.00	225.00
labor over doing them with engine in the car			
Updated latest version OEM ignition coil	6	87.64	525.84T
spark plug OEM	6	19.15	114.90T

Subtotal	
Sales Tax	
Total	
Payments/Credits	
Balance Due	

Phone #
405-330-9116



SERVICE

Date	Invoice #
2/11/2022	8768

Bill To
Clay Condry

Ship To
Clay Condry

VIN#	Mileage	Terms	Vehicle
WP0AD299X8S783477	47682		2008 997 TURBO SILVER

Description	Qty	Rate	Amount
Subtotal			865.74
labor to swap 997.2 intercoolers into 997.1 brackets	3	120.00	360.00
Subtotal			360.00
tech found auxilary electric water pump under intake seaping , replaced before it became a real leak. replacement of this part in the car would be terribly difficult if not impossible without removing engine and trans and removal of intake requiring a do over of the repair		0.00	0.00
Auxilary water pump OEM porsche only, no aftermarket avaiable	1	569.57	569.57T
Subtotal			569.57
labor to remove seats and install customer provided carbon seats including bracket swap included with parts	1.5	120.00	180.00
Subtotal			180.00
credit customer paid \$3000 cash up front before reparis	1	-3,000.00	-3,000.00
discount to cover cost of sales tax		-210.12	-210.12

Subtotal	\$3,926.81
Sales Tax	\$210.12
Total	\$4,136.93
Payments/Credits	\$0.00
Balance Due	\$4,136.93

Phone #
405-330-9116