



1840 National Ave
Hayward, CA 94545
(510) 782-0188
info@spmsracing.com
spmsracing.com

Invoice #2618

Created: 9/17/2021
Invoiced: 11/22/2021
Service Writer: Konstantin Braverman

Eddy Chan

Mobile: (415) 666-5816
eddyningning@yahoo.com

2016 Porsche Cayman GT4 (Yellow)

VIN: WP0AC280GK191977
License Plate: JAKE821
Mileage: 18,587

Customer Comments

Replace stock aluminum cam adjuster bolt with aftermarket steel bolt for 981 GT4 to prevent potential failure.

Engine Cam Actuator Bolt Upgrade Kit

Description	Price	QTY	Subtotal
1 Engine Actuator Bolts R&I <i>Note: Performed Engine actuator bolt replacement Performed oil and filter service and reset oil service reminder.</i>			\$1,200.00
2 Valve Cover Gasket: 1-3	\$52.16	1	\$52.16
3 Valve Cover Gasket: 4-6	\$52.24	1	\$52.24
4 Exhaust Manifold Gasket	\$32.27	2	\$64.54
5 Exhaust Manifold to Muffler Gasket	\$10.97	2	\$21.94
6 SPM Cam Actuator Steel Bolt Upgrade Kit	\$56.06	1	\$56.06
EPA (1.5%): \$3.70 Shop Supplies (3%): \$36.00 Tax (10.75%): \$26.55			Total: \$1,513.19

Engine Oil & Filter R&R

Customer Provided Torco oil

Description	Price	QTY	Subtotal
1 Engine Oil & Filter R&R			\$140.00
2 Reset Oil Change Light w/ Porsche Computer			\$0.00
3 Oil Filter Kit: Cayman/S/R	\$37.44	1	\$37.44
EPA (1.5%): \$0.56 Shop Supplies (3%): \$4.20 Tax (9.75%): \$3.65			Total: \$185.85

Inspect/Fix

Description	Subtotal
1 Inspect/Diag Exhaust Tips -Adjustment for exhaust tips. <i>Note: Clamps Re-torqued.</i>	\$200.00
Shop Supplies (3%): \$6.00	
Total: \$206.00	

Full Inspection

Description	Price	QTY	Subtotal
-------------	-------	-----	----------



1840 National Ave
Hayward, CA 94545
(510) 782-0188
info@spmsracing.com
spmsracing.com

Invoice #2618

Created: 9/17/2021
Invoiced: 11/22/2021
Service Writer: Konstantin Braverman

1	Full Inspection	\$200.00
2	CEL Diagnosis	\$200.00
3	Discount	-\$200.00
Total:		\$200.00

Exhaust Controller Module			
Recommend to pass 90db, if not already present.			
Description	Price	QTY	Subtotal
1 Track Nanny GPS Exhaust Controller	\$712.50	1	\$712.50
2 Track Nanny Controller Install			\$200.00
EPA (1.5%): \$10.69		Shop Supplies (3%): \$6.00	Tax (10.75%): \$76.59
Total:			\$1,005.78

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 10,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Warranty is voided if vehicle is driven on closed course race track. ALL SALES FINAL

30% Restocking fee will be added on any returns for un-open, new, and, or unused parts. Subject to examination before credit is issued. No returns on used, clearance, or discounted parts.

Thank you for your business. Your payment is due upon vehicle pickup.

Totals only include authorized services

Parts	\$996.88
Labor	\$1,940.00
Subcontract	\$0.00
Subtotal	\$2,936.88
Shop Supplies	\$52.20
EPA	\$14.95
Tax	\$106.79
Grand Total	\$3,110.82
Paid To Date	(\$3,110.82)
REMAINING BALANCE	\$0.00

Signature _____

Payments		
11/24/2021	Credit card ending in 3588	\$2,410.82
11/8/2021	Credit card ending in 5509	\$700.00

Declined

Exhaust Manifold R&R (Both Sides)			
Credit from initial diagnostic applied here			
Description	Price	QTY	Subtotal