

expense	date	invoice number/where	mileage	Owner	Work Recorded
\$913.59	1/30/2007	11138 - Porsche Colorado Springs	45866	Robert G (below)	45,000 mile Porsche Service performed
\$261.11	4/25/2008	12884 - Porsche Colorado Springs	55389		Replace front axle/brake lines
\$1,829.00	8/5/2009	14758 - Porsche Colorado Springs	75594		Oil change, fluid top off, wheel alignment, front rotors and pads, key battery
\$143.11	8/21/2009	15010 - Porsche Colorado Springs	75825		Rear deck shock, reverse switch
\$94.82	1/11/2010	15460 - Porsche Colorado Springs	80485		Brake light repair, reverse light repair
\$3,114.02	2/25/2011	17244 - Porsche Colorado Springs	92118		90,000 Porsche service (oil change, gear oil diff, gear oil transmission, all filters etc.), alignment, resealed bank 1 and 2 cam covers, rear brake pads, battery.
\$28.34	11/8/2011	18547 - Porsche Colorado Springs	99724		
\$5.19	11/21/2011	18633 - Porsche Colorado Springs	10017		
\$162.21	3/6/2012	19113 - Porsche Colorado Springs	10308		Rear turn signal
\$196.06	3/25/2012	19223 - Porsche Colorado Springs	10321		Purge valve
\$631.10	6/26/2012	19897 - Porsche Colorado Springs	10661		105,000 Porsche minor maintenance service performed, oil change, filters etc.
\$2,596.76	7/6/2012	19916 - Porsche Colorado Springs	10682		Replaced oil filter tube, CV boot right front, left and right differential seal replacement, coolant tank replacement, window regulator replacement (driver door)
\$274.27	3/20/2013	21529 - Porsche Colorado Springs	11478		Replace intake manifold fitting
\$3,259.73	5/13/2013	21872 - Porsche Colorado Springs	11649		ADS, Clutch, IMS, Cylinder head gaskets
\$2,698.58	1/21/2013	22382 - Porsche Colorado Springs	12438		Porsche 120,000 major maintenance, oil change, engine filter, cabin filter, fuel filter, spark plugs, door adjustment, bulb replacement, brake fluid flush
\$307.78	10/14/2014	25418 - Porsche Colorado Springs	13279		Oil change, Left brake light bulb
\$152.44	3/7/2015	26280 - Porsche Colorado Springs	13742		Driver door handle repair
\$4,481.02	5/8/2015	26665 - Porsche Colorado Springs	13891		Timing chain tensioner (camshaft adjuster replaced), oil change, parking bulb replaced, mudguard installed
\$1,198.75	6/30/2015	27165 - Porsche Colorado Springs	14102		Front brake rotors and pads
\$48.95	7/7/2015	27234 - Porsche Colorado Springs	14170		Diag light issues (headlight/halllight)
\$333.46	7/20/2015	27289 - Porsche Colorado Springs	14157		Rear right taillight harness
\$425.57	1/12/2016	28651 - Porsche Colorado Springs	14625		Front parking light, battery
\$915.49	3/25/2016	29229 - Porsche Colorado Springs	14662		Tire balance, alignment, oil change
\$65.93	5/10/2016	29707 - Porsche Colorado Springs	15085		Classic tire replaced, noise diag
\$791.29	2/14/2017	32259 - Porsche Colorado Springs	15720		Replace ignition switch, replace steering lock, multi point inspection
\$1,934.18	5/12/2017	33051 - Porsche Colorado Springs	15949		Oil change, multi point inspection, brake fluid flush, cv axle replacement,
\$146.22	10/11/2018	27910 - Autoworks Colorado	169042	Tom S (below)	Oil change
\$145.80	10/25/2018	27960 - Autoworks Colorado	169149		Diag CEL
\$266.91	11/16/2018	18115004 - Autoparts Denver	169279	Gary (below)	Alignment, found suspension worn
\$313.04	12/17/2018	4225553 - online order motor mounts			
\$414.62	1/28/2018	0048891 - Torack			
\$900.15	12/28/2018	14813 - Axis Automotive and Machine	167181		Front wheel bearing replacement, front shocks replaced
\$303.55	4/15/2019	15048 - Axis Automotive and Machine	188919		Coolant expansion tank replaced
\$266.91	6/5/2019	190052004 - Autoparts Denver	189346		Wheel alignment
\$291.88	6/20/2019	RM European auto parts			Motor mounts
\$447.80	8/27/2019	15341 - Axis Automotive and Machine	170000		CV boot repair, Stey bar links, Rear struts replaced
\$423.00	3/8/2020	715566818 - Specialized ECU Repair			New key programmed
\$411.78	4/24/2020	438806 - Suburban Auto Parts			Fuel pump, fuel gauge seal
\$2,482.49	7/14/2020	7471 - Autoparts Denver	172882	Steven (below)	Oil change, full brake job all pads rotors, cabin filter, air filter
\$1,090.91	8/11/2020	Tyrolsport	174000		Falser mod, low temp thermostat
\$298.72	10/17/2020	549-080-335 ECS	175209		All 8 coils and plugs replaced
\$322.00	10/31/2020	Aquaking Autopia	175478		Detail service, paint correction polish interior refresh
\$138.67	11/17/2020	Weathersch floor mats			
\$294.34	11/18/2020	Suncoast Parts			Replace both cupholders, battery cover replacement, added cubby in dash
\$25.79	11/21/2020	Sunset Porsche Parts			
\$48.00	12/03/2020		176196		Serpentine belt replacement, passenger seat motor cable, cylinder 5 and 6 spark plug tube replacement
\$8,548.16	12/14/2020	1234 - Tyrolsport	178429		IMS, Clutch, IMS, ADS, Remove oil pan clean and inspect bottom end, reverse light switch, front tie rod end + rearward control arm + rearward control arm, diff fluid service, transmission fluid service, oil change
\$674.87	8/4/2021	Discount tire direct			Yokohama Advan Sport A/S+
\$457.28	8/25/2021	1941 - Tyrolsport	181590		New tire mounted/balanced, Alignment
\$298.89	1/26/2022	2929 - Tyrolsport	183300		Oil Change, both gas left side
\$223.80	4/12/2022	USP Motorsports			Titanium wheel bolt set
\$1,550.41	4/18/2022	2503 - Tyrolsport	185500		Water pump replacement, oil pump seal, oil pump gasket, cam plug, new oil filter tube
TOTAL					
\$47,120.18					
Owner Breakdown					
\$26,313.29	Robert				
\$298.92	Tom				
\$4,078.74	Gary				
\$16,439.13	Steven				