

<b>Date</b>	<b>Work</b>	<b>Cost</b>
9/30/2019	964 Suspension Full - Bilstein B6 H&R Springs, replace front camber plates, replace rear strut mounts, RS Alignment, 964 drive belts, 964 Front rotors and pad, dampners, 964 Front and Rear Brake Lines, Brake flush, Window Switches	\$ 6,088.39
11/18/2019	Speedo Refurbishment	\$ 323.70
1/13/2020	Replace Combination Switch	\$ 587.32
10/22/2020	Oil and Filter Service, Inspection, Radio Fuse	\$ 292.24
12/7/2020	Drivers Side Axle Repack, Install Short Shift Kit and Golden Rod	\$ 1,108.86
4/1/2021	New Battery	\$ 287.85
4/14/2021	964 Maintenance - Tune Engine, Valves and Injector Adjustment, Replace Upper and Lower Spark Plugs, Air Filter, Fuel Filter, Ditributor Caps and Rotors, Balance Tires, Rear Axle Repack, New Fuel Pressure Regulator, AC Recharge	\$ 5,163.06
4/7/2022	Oil and Filter Service, Inspection, Install Rennline Pedals and Floor Board	\$ 496.64
4/19/2023	Oil and Filter Service, Inspection, Brake Fluid Flush, Continental Extreme Contact DWS Tires & Install	\$ 1,842.09
11/27/2023	Oil and Filter Service, Inspection, New Oil Pressure Sender, Leakdown Test - 8%, 6%, 8%, 5%, 8%, 6%	\$ 1,818.35
	Continental TR741UB-OR Bluetooth Radio	\$ 243.00
	FD Short Shift Kit + Golden Rod	\$ 756.00
	<b>Total</b>	<b>\$ 19,007.50</b>