

# R. FISCHER MOTORS

22221 N. Hillview Drive  
 Lake Barrington, IL 60010  
 (847) 304-8822

**Invoice # 16022**

**Dave Zuelke**

**1986 Porsche 944 Turbo**

License #

Inv Date: 4/12/2017

ODO In:66050 Out: 66058

Promised: 4/13/2017 @ 5:00pm

VIN:

Color:

Service Writer:

Engine: L4 2.5L, 2475cc, SOHC, GAS, FI, A

Mfg. Date:

Status: Complete

Trans:

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Disc.	Ext
<b>Estimate Timing Belts &amp; Waterpump Replacement: Replace Waterpump, Timing &amp; Balance Shaft Belts</b>							<b>1,472.49</b>
Labor Service - Replace Waterpump -	include new belts, coolant change, thermostat		6.00		135.00		810.00
New 944 105 157 04	Timing Belt			1.00	34.35		34.35
New 944 102 219 04	Balance Shaft Belt			1.00	125.80		125.80
New 951 106 021 10	Water Pump - New			1.00	546.12	-109.22	436.90
New 944 106 129 05	Thermostat			1.00	29.44		29.44
New AF	Coolant/Anti-freeze OAT Global, 1 gallon			2.00	18.00		36.00
<b>Car was stored since 2000 - Estimate Fluid Changes: Visual inspection and provide recommendations</b>							<b>341.82</b>
Labor Service - Drain Fuel System, Purge Fuel Circuit, Replace Fuel Filter, Add Fresh Fuel and Road Test			2.00		135.00		270.00
Additional time required - Full fuel tank, Clutch Disc seized							
New 928 110 253 06	Fuel Filter			1.00	41.82		41.82
Sublet FUEL	Gasoline/Diesel			1.00	30.00		30.00
<b>Brake Fluid Change</b>							<b>134.95</b>
Labor Service - General Labor			0.80		135.00		108.00
New 9001A	Brake Fluid, TYP 200			1.00	26.95		26.95
<b>The Transaxle needs standard Maintenance Service.</b>							<b>84.00</b>
Labor Service - General Labor			0.40		135.00		54.00
New 80W90	Hypoid Gear Oil			4.00	7.50		30.00
<b>The vehicle needs an Oil and Filter Service.</b>							<b>113.83</b>
Labor Service - Oil Service - Mobil 1 15w-50			0.25		135.00		33.75
New MOBIL1	Mobil 1 Oil			6.50	9.95		64.68
New OC142	Oil Filter			1.00	12.85		12.85
New CU22X27	Drain Plug Seal			1.00	0.55		0.55
Sublet EPA	EPA			1.00	2.00		2.00
<b>Notes: Belt Rollers, V-Belts, Air Filter</b>							<b>646.97</b>
Labor Service - Components rusted/seized/chewed upon - additional clean up effort due to lack of use and mice CMS			2.00		135.00		270.00
New 944 105 027 04	Timing Belt Tensioner			1.00	110.96		110.96
New 944 105 241 04	Timing Belt Roller			1.00	55.14		55.14
New 944 102 025 07	Balance Shaft Belt Tensioner			1.00	72.71		72.71
New 944 102 277 06	Auxiliary Shaft Roller			1.00	73.01		73.01
New 951 110 121 01	Air Filter			1.00	28.34		28.34
New 6PK-1000	Drive Belt-Alternator To Compressor			1.00	26.05		26.05
New 999 192 236 50	Drive Belt			1.00	10.76		10.76
<b>Customer states that vehicle stored last 17 years: Full Detail.</b>							<b>250.00</b>
Labor Service - Sublet					135.00		0.00
Sublet DETAIL	Complete Interior/Exterior Detailing			1.00	250.00		250.00
<b>Customer states that vehicle was stored 17 years: Tires on the vehicle need replacement.</b>							<b>180.00</b>
Labor Service - Dismount, Mount and Balance 4 tires			1.20		125.00		150.00
New WW	Wheel Weight			3.00	4.00		12.00
Sublet TD	Tire Disposal			3.00	6.00		18.00

# R. FISCHER MOTORS

22221 N. Hillview Drive  
 Lake Barrington, IL 60010  
 (847) 304-8822

Invoice # 16022

Dave Zuelke

1986 Porsche 944 Turbo

License #

Inv Date: 4/12/2017

**Notes**

Tires are old, recommend replacement  
 Interior/Exterior Detailing  
 Charging system/voltmeter indicator lamp

*paid c# 2785567*

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. R Fischer Motors and employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. R. Fischer Motors will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

\_\_\_\_\_  
 Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

\_\_\_\_\_  
 Customer acknowledges receipt of merchandise and services.

**Invoice Summary**

Parts	1,097.63
Parts Discount	-50.00
Labor	1,695.75
Sublet	300.00
Fluids	130.68

**Tax Breakdown:**  
 Default Sales Tax 82.48

Sub Total	3,174.06
Sales Tax (IL)	82.48