

4.29-06 A/C CONTROL MODIFICATION

- 1.) INTERRUPTED WIRE FROM A/C CONTROL HEAD TO A/C COMPRESSOR CLUTCH. USED A RELAY TO ACTIVATE COMPRESSOR FROM 12^V JUMP POST FUSED 10AMPS.
- 2.) DISCONNECTED REFRIGERANT TEMP SWITCH ON TOP OF RECEIVER/DRYER.
- 3.) USE RELAY TO TURN ON AUX. ELECTRIC FAN WHENEVER A/C IS ON REGARDLESS OF TEMP. SHOULD BE BETTER FOR R134A OR FREEZE12.

