

Technical Bulletin

Model

928

Group

15

Subject: O-Ring for Camshaft Bearing

Part Identifier

1516

Number

78-04

Camshaft O-ring thickness has been changed from 4mm (0.160 in.) to 5mm (0.196 in.), as of Engine Numbers:

829 0252 (5 speed)
829 5131 (automatic)

Part Numbers

Old Part Number 999 701 425 40
New Part Number 999 701 602 40

O-Ring Replacing

Order new 5mm thick O-ring for replacement.

SERVICE

Page 1 of 1
November 1, 1978