

Relay Designation	Relay Slot Location By Year				Part Number	Notes
	92-95	91	90	87/89		
Rear Window Defogger	I-II	I-II	I-II	I-II	928.615.115.00	Double size 2 slot relay
Daytime Running Light	III*	III*	III*	None	431.951.253.G	*Optional (e.g. Canada) 90+ only
Fog light	IV	IV	IV	XIII	141.951.253.B	Front Fog Lamps
X-Relay	None	None	None	IV	141.951.253.B	X-Bus repeater, direct only 90+
Starter	V	V	V	XIV	141.951.253.B	Drives solenoid on starter body
Flap control	None	None	VI	XVIII	944.615.119.00	Radiator air flaps deleted 91+
Power Windows	None	None	None	VI	928.615.126.00	Supply Control Relay, 90+ have Wndw/Sunrf Control unit (10eP)
Headlight Washer	VII	VII	XIX	XIX	928.618.111.00	Active only w/ headlights up
Fog Light (Disable Relay)	VIII	VIII	VIII	None	928.615.137.01 928.615.125.00 141.951.253.B*	USA 87-89 ROW 87-89 (bridge - not M193) *90+USA/Jpn: fogs off w/hi-beam
Windshield Intensive Wash	None	IX	IX	IX	928.615.113.01	Deleted on GTS models
Supply Relay	X	X	X	None	141.951.253.B	Fog Light/AC/Fans supply disable during start (not actually X-Bus)
Intermittent Wipers	XI	XI	XI	VII	928.615.101.01 (993.615.101.01)	(VW digital type: #3B0.955.531) (Later Porsche Equivalent)
Fresh air blower	XII	XII	XII	X	141.951.253.B	HVAC Blower
Flasher Turn Signals	XIII	XIII	XIII	V	111.953.227.D (1H0.953.227) 928.615.131.00*	Original Flasher (no trailer) (Alternate Flasher - no trailer) *M208 Trailer Signal Flasher
Defroster	XIV	XIV	XIV	VIII	928.615.203.00 (141.951.253.B*)	DEF mode on HVAC with Fuse Tester Integrated (*Alternate)
ABS	XV	XV	XV	XVII	928.615.124.01	ABS Braking
Two-tone horn	XVI	XVI	XVI	XII	141.951.253.B	Std. STSP Relay
Kick down (M249 only)	XVII	XVII	XVII	XV	928.618.109.01 928.618.108.00 928.618.108.01	M249 AT only 87-88 M249 AT only 89-93 (note1) M249 AT only 93-95 (note2)
Backup Light (M249 only)	XVIII	XVIII	XVIII	XXII	141.951.253.B 928.615.125.00*	M249 AT only *M481 MT has 87/30 bridge
FCU Freq Control	XIX	XIX	None	None	964.618.221.00	Digital Speedometer
Inside light	None	None	XIX	XXI	928.618.225.01	Moved to Alarm Module 91+
Suppressor	XXI	XXI	XXI	XI	928.618.223.00	Noise Supsressor (not a relay)
EZK/Disable Ignition	XXII	XXII	XXII	XVI	928.615.203.00 (141.951.253.B)*	Ignition Disable from Alarm with Fuse Tester Integrated (*Alternate)
Headlight Combination	XXIII-XXIV	XXIII-XXIV	XXIII-XXIV	XXIII-XXIV	928.618.107.04 / 928.618.107.01*	Hi/Lo beam & Headlight (*equiv) Up/Dn Motor (changed 86+) Double size 2 slot relay
MFI / LH-Jetronic	XXV	XXV	XXV	XXV	141.951.253.B	Std. STSP Relay
Fuel Pump	XXVI	XXVI	XXVI	XX	141.951.253.B	Std. STSP Relay
--- empty unwired slot 1----	VI*	VI*	XX*	III*	N/A	*Can use empty slots for spares
--- empty unwired slot 2----	IX*	XX*	---	XXVI*	N/A	*Can use empty slots for spares
--- empty unwired slot 3----	XX*	---	---	---	N/A	*Can use empty slots for spares
MT Max Slots Filled (of 26)	21	22	23	22	N/A	NB Max for all possible options
AT Max Slots Filled (of 26)	23	24	25	24	N/A	NB Max for all possible options