PCCB Rotor Check | VAS 6813

	4/23/15 Pad	8/18/15 Pad	11/20/15 Pad	Measurement	New	Track Miles Mileage Date Wear	2,086 14,750 4/29/16	Wear %
		Thickness		Point	Figure	Limit	Measured	
				1	<u> </u>	42	54.2	81%
Left Front	10.5 mm	9.6 mm	7.0 mm	2	67	50	63.2	78%
			Replaced	3	62	46	59.5	84%
				1	57	42	54.1	81%
Right Front	10.5 mm	9.9 mm	7.0 mm	2	50	37	47.1	78%
			Replaced	3	61	45	57.9	81%
				1	62	47	59.6	84%
Left Rear	10.5 mm	8.6 mm	6.0 mm	2	57	43	55.0	86%
			Replaced	3	59	45	57.3	88%
				1	52	40	50.7	89%
Right Rear	10.5 mm	8.6 mm	6.0 mm	2	51	39	50.1	93%
			Replaced	3	47	36	44.9	81%

Corrected -0.06