P0410 is the DTC that caused this Freeze Frame Data to be Stored Secondary Air Injection System Malfunction

Fuel System 1 Status Fuel System 2 Status Calculated Load Open Loop Control - Warmup Open Loop Control - Warmup

150.8 Deg F 66 Deg C Coolant Temperature

Short Term Fuel Trim Bank 1 0.00 %

ong Term Fuel Trim Bank 1 Rich (+) 4.69 %

Short Term Fuel Trim Bank 2

ong Term Fuel Trim Bank 2 Rich (+)

1053.25 Rpm

Engine Speed Vehicle Speed 15 Kmh 9 Mph