

Scotty s Automotive

108 Hwy 377 N
Roanoke, TX. 76262

Phone - 817-490-9478 Fax - 817-491-2360

INVOICE

10183

Org. Est. # 018252

INVOICE

Work Completed Date : 06/18/2016

Print Date : 06/18/2016

HEILMAN, JOHN
62 CYPRESS CT
Roanoke, TX 76262
Home 817-897-7737
Cust ID : 1013

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI)
Lic # : BM6P595 - TX Odometer In : 0
Unit # :
Vin # :
Hat # : Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
CLUTCH KIT\ PRESSURE PLATE AND T.O. BEARING AND CLUTCH DISC CK	1.00	568.22	568.22	CLUTCH PRESSURE PLATE - Remove & Replace - Carrera 4S - [DOES NOT include resurface Flywheel.] Hazardous Materials	930.60 2.00
DUAL MASS FLYWHEEL ASSEMBLY 996.114.012.04	1.00	970.00	970.00		
CLUTCH SLAVE CYLINDER AND CLUTCH LEVER AND FLYWHEEL BOLTS M10x1x50 8COUNT.AND PILOT BEARING 997.116.237.04	1.00	416.00	416.00		
Shop Supplies		57.70	57.70		

BAL. \$610.50

Org. Estimate \$ 3,110.50 Revisions \$ 0.00 Current Estimate \$ 3,110.50

Labor:	932.60
Parts:	2,011.92
Sublet:	\$0.00
Sub:	2,944.52
Tax:	165.98
Total:	3,110.50
Bal Due:	\$3,110.50

[Payments -]
Parts/labor warrantied 90 days/3,000 miles whichever comes first. Warranty work must be performed in our shop & not exceed original cost of repair. We are not responsible for loss/damage to vehicle/articles left in car due to fire, theft or any other cause. Vehicles not picked up within 3 days of completion are subject to a \$22/day storage fee. I understand this vehicle is subject to repossession in accordance with Sec. 9.503 Texas Business & Commerce Code if payment is stopped or dishonored for lack of funds.

Signature *[Signature]* Date 6-18-16 Time _____

Scotty s Automotive

108 Hwy 377 N

Roanoke, TX. 76262

Phone - 817-490-9478 Fax - 817-491-2360

INVOICE

10137

INVOICE

Print Date : 06/02/2016

HEILMAN, JOHN
 62 CYPRESS CT
 Roanoke, TX 76262
 Home 817-897-7737
 Cust ID : 1013

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI)
 Lic # : - TX Odometer In : 0
 Unit # :
 Vin # :
 Hat # : Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
WATER PUMP WP	1.00	376.50	376.50	REMOVE AND REPLACE OIL SEPARATOR	544.50
THERMOSTAT TS	1.00	77.79	77.79	REMOVE AND REPLACE WATER PUMP AND THERMOSTAT	445.50
WATER PUMP GASKET/ STEEL SHIM WPG	1.00	12.56	12.56	REMOVE AND REPLACE SPARK PLUGS	247.50
THERMOSTAT GASKET TSG	1.00	8.76	8.76	Hazardous Materials	2.00
OIL SEPARATOR OS	1.00	222.96	222.96		
PORSCHE SF COOLANT SF	2.00	69.95	139.90		
Shop Supplies		41.52	41.52		

Org. Estimate \$ 2,192.09 Revisions \$ 0.00 Current Estimate \$ 2,192.09

Labor:	1,239.50
Parts:	879.99
Sublet:	\$0.00
Sub:	2,119.49
Tax:	72.60
Total:	2,192.09
Bal Due:	\$2,192.09

PO. # 4895

[Payments -]

Parts/labor warrantied 90 days/3,000 miles whichever comes first. Warranty work must be performed in our shop & not exceed original cost of repair. We are not responsible for loss/damage to vehicle/articles left in car due to fire, theft or any other cause. Vehicles not picked up within 3 days of completion are subject to a \$22/day storage fee. I understand this vehicle is subject to repossession in accordance with Sec. 9.503 Texas Business & Commerce Code if payment is stopped or dishonored for lack of funds.

Signature _____ Date _____ Time _____