



Turning Wrenches
 1304 N. English Street Road
 Louisville, KY 40223
 Email: Turningwrenchesllc@gmail.com Website: www.turning-wrenches.com
 502-821-3180

Authorization - Estimate of Deferred Work

Bill To: Binkley, Steven
 107 WHEELS CT
 LAYTON, KY 40071
 US
 Mobile: (502) 693-6874
 Email: S.W.BINK02@GMAIL.COM

Plate KY 088EHJ
 Description Black 2000 Porsche 911 Carrera H6 3.4L
 3400CC
 VIN WP0CA299XYS654169
 Unit ENGINE 9601 BODY 996
 Odometer 52,104 In / 0 Out

Work Order # 18998
 Service Advisor Paul Welch
 Technician Tony Broad

Appointment 3/7/2023 2:00 PM
 Promised 3/8/2023 2:00 PM

Deferred Service

Used Engine Assembly

Remove and Replace engine assembly Recommend updating IMS bearing on replacement engine. Also being a manual possibility the clutch will need to be replaced.

Labor	
Used Engine Assembly 97K	1 Unit
Intermed. Shaft Brg. Set ** NO RETURN **-----WILL REQUIRE ONE OR THE OTHER, WILL VERIFY WHICH ONCE APART	1 Unit
Intermed. Shaft Brg. Set Dual Row Bearing	1 Unit
Contingency	1 Unit
Clutch Kit-----VEHICLE MAY NEED CLUTCH WHICHEVER OPTION CUSTOMER GOES WITH. THIS IS STRICTLY INFORMATION PRICING OF 2 MAIN COMPONENTS. MORE PIECES MAY BE NEEDED	1 Unit
Flywheel-----VEHICLE MAY NEED CLUTCH WHICHEVER OPTION CUSTOMER GOES WITH. THIS IS STRICTLY INFORMATION PRICING OF 2 MAIN COMPONENTS. MORE PIECES MAY BE NEEDED	1 Unit

Sub

Cylinder Head

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor	
Cylinder Head Bolt	24 Unit
Cylinder Head-----BG, GERMANY APPROX 4 WEEKS	1 Unit
Cylinder Head Gasket Set- BG *****GROUPED PRICING OF Q# 46776***** SEE QUOTE ON WORKORDER CLIP BOARD	1 Unit
CONTINGENCY	1 Unit

Sub

Short Block Assembly

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor	
Engine Short Block Assembly-----BG APPROX. 1 WEEK	1 Unit
Cylinder Head Bolt	24 Unit

Engine Gasket Set Complete w/all Gaskets
CONTINGENCY

1 Unit
1 Unit

Sub \$20,472.00

Total Before Taxes & Miscellaneous Charges		\$60,552.90
(*) Shop Supplies / Hazardous Waste / Environmental Compliance Fees		\$46.24 S
(S) State Sales Tax	6 %	<u>\$3,635.95</u>
Grand Total		\$64,235.09

I consent to receiving messages regarding your services, via automated technology, to the cellular phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. I understand I may be charged a minimum diagnostic fee of \$150.00.

Warranty on repair parts and labor is **3 years or 36,000 miles**, whichever comes first, maintenance items excluded. Warranty excludes scheduled maintenance items and brakes. All brake warranted for 1 year or 12,000 miles, whichever comes first. Warranty work has to be performed in our shop and cannot exceed the original cost of repair.

Customer Signature: _____